

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2015 Jan 12	British Columbia, Canada	
	Estimate: RIGHT REAR SIDE Estimate Date: n/a	\$1,875.42
	Claim: COLLISION RIGHT REAR SIDE	\$1,639.39
2018 Mar 20	British Columbia, Canada	
	Estimate: LEFT REAR SIDE Estimate Date: n/a	\$811.76
	Claim: COLLISION LEFT REAR SIDE	\$746.62
2018 Sep 5	British Columbia, Canada	
	Estimate: REAR CENTER Estimate Date: n/a	\$2,923.43
	Claim: COLLISION REAR CENTER	\$2,784.41
2018 Nov 6	British Columbia, Canada	
	Estimate: LEFT FRONT CORNER Estimate Date: n/a	\$9,915.67
	Claim: COLLISION LEFT FRONT CORNER	\$206.78
	Claim: COLLISION LEFT FRONT CORNER	\$9,484.03
2019 Jan 21	British Columbia, Canada	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00
2022 Dec 16	British Columbia, Canada	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

JA4JZ3AX3EZ603514



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 May 17	8,122 KM	Service Facility Richmond, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire(s) replaced Oil and filter changed
2017 Sep 22	51,476 KM	Hesp Auto North Vancouver, British Columbia, Canada	Vehicle serviced
2018 Dec 13	65,862 KM	Kal Tire 661 North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> One tire mounted One tire balanced
2020 May 25	83,081 KM	The Shop Automotive North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brake light bulb(s) replaced Headlight bulb(s) replaced Front brake rotor(s) replaced Front brake pads replaced Brake rotor(s) replaced
2021 Jan 25	89,644 KM	The Auto Room Sale & Service Ltd. North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Four wheel alignment performed Vehicle serviced <ul style="list-style-type: none"> Lower control arm bushings replaced Four wheel alignment performed
2021 Feb 12	90,006 KM	The Shop Automotive North Vancouver, British Columbia, Canada	Vehicle serviced
2021 Aug 19	95,059 KM	The Shop Automotive North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Oil and filter changed Transfer case fluid flushed/changed
2021 Nov 16	98,328 KM	The Shop Automotive North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2021 Dec 1	98,711 KM	The Shop Automotive North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Sway bar link(s) replaced
2022 Apr 14		Rover Automotive Inc North Vancouver, British Columbia, Canada	Vehicle serviced
2022 Aug 11	106,064 KM	Rover Automotive Inc North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Air filter replaced Oil and filter changed Cabin air filter replaced/cleaned
2022 Nov 17	111,341 KM	Rover Automotive Inc North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire(s) replaced Brakes checked Rear brake pads replaced Brake pads replaced

JA4JZ3AX3EZ603514

