
(i)



Vehicle History Report #: 56036243 Report Date: September 9, 2024 | 11:39 a.m. EDT Report Status: Complete

## 2017 HYUNDAI TUCSON LIMITED

Sport utility vehicle | 4 Cylinders | Gas KM8J3CA45HU258190 Country of Assembly: Korea (South) Last Reported Odometer: 178,620 KM



Canada as of September 09, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report**



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2018 Jun 1	Ontario, Canada	
	Claim: Collision	\$0.00
	Claim: Collision	\$0.00

## **Other Damage Records**

RECORD DATE	DETAILS	AMOUNT
<b>1</b> 2023 Mar 22	Toronto, Ontario, Canada	
	Auction Announcement: AUCTION ANNOUNCED AS STRUCTURAL DAMAGE	

## Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Jul 8		Timmins Hyundai	Vehicle serviced
		Timmins, Ontario, Canada	
2016 Dec 6	11,541 KM	Kal Tire - Timmins	Vehicle serviced
		Timmins, Ontario, Canada	Maintenance reminder reset
			Oil and filter changed
2016 Dec 15	12,228 KM	Kal Tire - Timmins	Vehicle serviced
		Timmins, Ontario, Canada	Maintenance reminder reset
			Oil and filter changed
2017 Mar 24	26,977 KM	Kal Tire - Timmins	Vehicle serviced
		Timmins, Ontario, Canada	Maintenance reminder reset
			Oil and filter changed
2017 Jun 16	40,404 KM	Kal Tire - Timmins	Vehicle serviced
		Timmins, Ontario, Canada	Maintenance reminder reset
			Oil and filter changed
2018 Jan 12	71,207 KM	Pathway Hyundai	Vehicle serviced
		Orlans, Ontario, Canada	
2024 Jul 31		Boyer Hyundai	Vehicle serviced
		Pickering, Ontario, Canada	



KM8J3CA45HU258190

Recall #: R0173 | Antilock Brake System (ABS) Control Module Recall Date: 2021 Feb 22

#### **Recall Description**

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could corrode internally and cause a short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners of this problem by mail. Dealers will rework the wiring to the ABS fuse wiring and, if necessary, update the ABS module. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)

Recall #: R0198 | Engine Inspection Recall Date: 2021 Dec 22

#### **Recall Description**

Issue: On certain vehicles equipped with a 2.0 L Nu GDI engine, the connecting rod bearings could wear prematurely. As a result, there could be an abnormal knocking noise from the engine and/or the oil pressure warning light may turn on. If you continue to drive the vehicle with worn connecting rod bearings, the engine could fail. An engine failure would cause a sudden loss of power with an inability to restart. In some cases, a damaged connecting rod could puncture the engine block and cause an oil leak. Note: For the Sonata model, only the Sonata Hybrid is affected by this recall. Additional Note: Engine compartment fires can happen for many different reasons. In some cases, there is too much damage to find the cause of a fire. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Oil that leaks onto a hot component could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer for an engine inspection test, to determine if there is bearing damage. If damage is found, the engine will be replaced. Dealers will also update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)

Recall #: R0180 | Engine Control Module Reprogramming Recall Date: 2022 May 06

#### **Recall Description**

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)

### Stolen Vehicle Check

This vehicle is not actively declared stolen.

### Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jul 8		Timmins Hyundai Timmins, Ontario, Canada	Service Record	Vehicle serviced

KM8J3CA45HU258190

### CARFAX Canada Vehicle History Reports

9/24, 11	1:48 AM	CARFAX Canada Vehicle History Reports					
		ODOMETER	SOURCE	RECORD TYPE	DETAILS		
	2016 Jul 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Fleet Vehicle colour noted as gray		
	2016 Dec 6	11,541 KM	Kal Tire - Timmins Timmins, Ontario, Canada	Service Record	Vehicle serviced		
	2016 Dec 15	12,228 KM	Kal Tire - Timmins Timmins, Ontario, Canada	Service Record	Vehicle serviced		
	2017 Mar 24	26,977 KM	Kal Tire - Timmins Timmins, Ontario, Canada	Service Record	Vehicle serviced		
	2017 Jun 16	40,404 KM	Kal Tire - Timmins Timmins, Ontario, Canada	Service Record	Vehicle serviced		
	2017 Sep 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed		
	2018 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Fleet		
	2018 Jan 12	71,207 KM	Pathway Hyundai Orlans, Ontario, Canada	Service Record	Vehicle serviced		
	2018 Jun 1		Insurance Records Ontario, Canada				
	2018 Jun 1		Ontario, Canada	Collision			
	2018 Sep 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal		
	2019 Sep 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal	-	
	2020 May 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported	-	
	2020 Jul 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported	-	
	2020 Sep 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported	-	
	2020 Nov 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal		
	2021 Feb 22		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0173		
	2021 Dec 22		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0198		
	2022 May 6		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0180	3190	
	2023 Mar 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray	KM8J3CA45HU258190	
	2023 Mar 22	178,620 KM	Auto Auction Toronto, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS STRUCTURAL DAMAGE	KM8J3C	

#### CARFAX Canada Vehicle History Reports

Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported	
Ontario, Canada			
		Vehicle colour noted as gray	
Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
Ontario, Canada		New Owner reported	
		Previous Use: Personal	
		Vehicle colour noted as gray	
Motor Vehicle Dept.	Canadian Renewal	New Owner reported	
Ontario, Canada		Vehicle colour noted as gray	
Boyer Hyundai	Service Record	Vehicle serviced	
Pickering, Ontario, Canada	1		
Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
Ontario, Canada		New Owner reported	
		Previous Use: Personal	
		Vehicle colour noted as gray	
-	Ontario, Canada Motor Vehicle Dept. Ontario, Canada Boyer Hyundai Pickering, Ontario, Canada Motor Vehicle Dept.	Ontario, Canada Ontario, Canada   Motor Vehicle Dept. Canadian Renewal   Ontario, Canada Service Record   Pickering, Ontario, Canada Service Record   Motor Vehicle Dept. Canadian Renewal	Ontario, CanadaNew Owner reported Previous Use: Personal Vehicle colour noted as grayMotor Vehicle Dept. Ontario, CanadaCanadian Renewal Service RecordNew Owner reported Vehicle colour noted as grayBoyer Hyundai Pickering, Ontario, CanadaService Record Canadian RenewalVehicle servicedMotor Vehicle Dept. Ontario, CanadaCanadian Renewal Service RecordRegistration Issued or Renewed New Owner reported Previous Use: Personal



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, dometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be relable, but no responsibility is assumed by CARFAX Canada. Is source data providers receive data and information from external sources believed to be relable, but no responsibility is assumed by CARFAX Canada. Is source data providers receives data and information and its source data providers receives data and information and its source data providers receives data and information from external sources believed to be relable, but no responsibility is assumed by CARFAX Canada. Source data providers receives data and information approvements for any errors, inaccuracies or omissions. The reports are provided strictive is basis, and CARFAX Canada not its source data providers receives data and information approvements and its source data providers receives data and information approvements and its source data providers receives data and information approvements approvements are careful approvements are expensible. Including and warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for any etros are expensible for any errors and information contained within a report. Including the approxide are expensible approved are provide are expensible. The reports are obter ported to the vehicle that is the subject matter of any leage are to approximate and test dive, to make a better decision about the vehicle that the history report, but agree to be bound by all of the terms and conditions in CARFAX Canadas. Conditions of Use and any CARFAX C

© 2024 CARFAX Canada ULC. All rights reserved.

