

2013 MITSUBISHI OUTLANDER ES

Sport utility vehicle | 4 Cylinders | Gas
JA4AT2AW8DU609260
Country of Assembly: Japan
Last Reported Odometer: 111,067 KM

Low
Kilometres™ >



Accident/Damage Records Found



Last Registered In:
Manitoba (Normal)



4 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 10, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2013 Dec 19	Manitoba, Canada	
	Claim: Collision	Not Reported
2016 Jun 23	Manitoba, Canada	
	Claim: Collision	Not Reported



Registration

✓ This vehicle has been registered in the province of **Manitoba** in **Canada** with **Normal** branding.
We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Aug 27	12,798 KM	Midas Auto Service Experts Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none">Oil and filter changed
2014 May 12		Vickar Mitsubishi Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completedRecommended maintenance performedAlignment performedFour wheel alignment performedOil and filter changedSafety inspection performed
2014 Dec 2		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed
2025 Nov 4	111,067 KM	Crown Honda Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed



Open Recalls

Recall #: SR-16-009 | 2007-2013 OUTLANDER -REPLACE WIPER LINK (PERFORM AT SAME TIME AS Recall Date: 2016 Oct 26

Recall Description

IN THE EVENT THAT WATER DROPS DOWN THROUGH THE BACK SIDE OF THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD

JA4ATZAW8DU609260

AND WINDSHIELD), THE FRONT WIPER LINK BALL JOINT MAY EXPERIENCE EXCESSIVE MOISTURE AND CORRODE. IF THIS OCCURS, THE RESIN CASE OF THE BALL JOINT WILL WEAR PREMATURELY DUE TO THE BALL JOINT CORROSION AND THE WIPER LINK MAY ULTIMATELY SEPARATE CAUSING THE WINDSHIELD WIPERS TO STOP OPERATING.

Remedy

WNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR THE REPAIR. AT NO CHARGE TO THE CUSTOMER, THE RUBBER BOOT WHICH COVERS THE BALL JOINT WILL BE REPLACED WITH A COUNTERMEASURE ONE TO PREVENT WATER INTRUSION. THE WIPER MOTOR CRANK ARM WILL ALSO BE INSPECTED AND REPLACED AS NECESSARY IN CASE OF EXCESSIVE FREE PLAY ON THE LINK. I

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](https://owners.mitsubishicars.com/s/services/open-recalls). (https://owners.mitsubishicars.com/s/services/open-recalls)

Recall #: SR-17-003 | 2007-2013MY OUTLANDER -REPLACE WIPER MOTOR (PERFORM AT SAME TIME Recall Date: 2017 Jul 20

Recall Description

WATER CAN POTENTIALLY DROP DOWN ONTO THE FRONT WIPER MOTOR THROUGH A GAP BETWEEN THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD AND WINDSHIELD) AND THE FRONT WINDSHIELD. IF THIS OCCURS, WATER COULD POTENTIALLY COLLECT IN THE AREA OF THE WIPER MOTOR BREATHING HOLE. IF THE WIPER MOTOR IS NOT OPERATING, THIS WATER CAN THEN POTENTIALLY ENTER THE WIPER MOTOR THROUGH THE BREATHING HOLE. IF THIS OCCURS, SUCH WATER INTRUSION OVER TIME MAY CAUSE INTERNAL CORROSION AND/OR ELECTRICAL CONDUCTION FAILURE RESULTING IN NON-OPERATION OF THE WINDSHIELD WIPER MOTOR.

Remedy

WNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR REPAIR. AT NO CHARGE TO THE CUSTOMER, THE WIPER MOTOR WILL BE REPLACED WITH AN UPGRADED WIPER MOTOR THAT WILL PREVENT WATER INTRUSION. I

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](https://owners.mitsubishicars.com/s/services/open-recalls). (https://owners.mitsubishicars.com/s/services/open-recalls)

Recall #: SR-20-003 | FRT CROSSMEMBER CORROSION - LANCER, OUTLANDER, ETC (JA) Recall Date: 2020 Jul 28

Recall Description

THE INSIDE AND OUTSIDE SURFACES OF THE FRONT CROSS MEMBERS USED ON CERTAIN VEHICLES, IF EXPOSED LONG TERM TO SNOWMELT WATER AND ANTI-FREEZING AGENTS, MAY CORRODE DUE TO INSUFFICIENT PERFORMANCE OF THE RUST PROTECTION. SHOULD SIGNIFICANT CORROSION OCCUR OVER TIME, A LOWER CONTROL ARM COULD EVENTUALLY BECOME DETACHED RESULTING IN LOSS OF VEHICLE CONTROL AND A POTENTIAL COLLISION.

Remedy

WNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR INSPECTION. THE CROSS MEMBER WILL BE INSPECTED AND THE FOLLOWING ACTION WILL BE TAKEN AT NO CHARGE TO THE CUSTOMER: (1) IF NO SIGNIFICANT CORROSION IS IDENTIFIED, A SEALING/ANTI-CORROSION AGENT WILL BE SPRAYED INSIDE/OUTSIDE THE CROSS MEMBER; (2) IN THE EVENT THAT SIGNIFICANT CORROSION IS IDENTIFIED, THE CROSS MEMBER WILL BE REPLACED WITH A COUNTERMEASURE CROSS MEMBER. OWNERS SEEKING REIMBURSEMENT FOR ANY EXPENSES ASSOCIATED WITH THIS RECALL WILL BE DIRECTED IN THE NOTIFICATION LETTER TO CONTACT THE MITSUBISHI CUSTOMER RELATIONS DEPARTMENT FOR INSTRUCTIONS ON HOW TO APPLY FOR A REFUND. S

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](https://owners.mitsubishicars.com/s/services/open-recalls). (https://owners.mitsubishicars.com/s/services/open-recalls)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Apr 16		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2013 Aug 27	12,798 KM	Midas Auto Service Experts Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2013 Dec 19		Manitoba, Canada	Collision	
2014 Feb 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial Vehicle colour noted as black
2014 Apr 22	35,355 KM	Auto Auction Winnipeg, Manitoba, Canada	Auction Announcement	AUCTION ANNOUNCED AS PREVIOUS DAILY RENTAL
2014 Apr 22		Auto Auction Winnipeg, Manitoba, Canada	Auction Announcement	Previous Daily Rental
2014 May 12		Vickar Mitsubishi Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Dec 2		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as black
2014 Dec 2		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2016 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2016 Jun 23		Manitoba, Canada	Collision	
2016 Oct 26		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-16-009
2017 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2017 Jul 20		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-17-003

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2019 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2020 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2020 Jul 28		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-20-003
2021 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 Jul 9		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2024 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2025 Jan 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2025 Nov 4	111,067 KM	Crown Honda Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>