



Vehicle History Report #: 62178098
Report Date: June 13, 2025 | 4:27 p.m. EDT
Report Status: Complete
Reference:

2011 ACURA MDX ADVANCE

Sport utility vehicle | 6 Cylinders | Gas
2HNYD2H7XBGH532675
Country of Assembly: Canada
Last Reported Odometer: 162,262 KM

No Reported
Accidents ¹⁴



Glass Records Found



Last Registered In:
Ontario (Normal)



23 Service Records Found



U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of June 13, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

2HNYD2H7XBGH532675

CUSTOMER #: 1081049

60998

ACURA OF THORNHILL

Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

INVOICE

VLAD TOPA
511-3 ELLESMERE ST
RICHMOND HILL, ON L4B 4N2
HOME: CONT:437-981-2377
BUS: CELL:437-981-2377

PAGE 5

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TA
	11	ACURA MDX		2HNYD2H7XBH532675		162038/162038		T518
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN11 DD			09:30 22JUL24		188.00	CASH	24JUL24	
R.O. OPENED		READY		OPTIONS: DLR:9141				
08:50 22JUL24		16:20 24JUL24						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TO
	264685	CM				188.00	188
1	56110-RYE-A05	A	PUMP SUB ASSY P/S		1141.73	1141.73	1141
1	08285-P99-0CZF3	8	HONDA P/S FLUID		23.98	23.98	23
1	08285-P99-0CZF3	8	HONDA P/S FLUID		23.98	23.98	23
150FFPART15%			PARTS DISCOUNT				
		CR				-178.45	-178
PARTS:	1189.69	LABOR:	188.00	OTHER:	-178.45	TOTAL LINE M:	1199

N** Miscellaneous Engine - REPLACE ENGINE OIL PUMP'S GASKETS + T - BELT PACK

CAUSE: OIL LEAKING

EN001 Miscellaneous Engine - REPLACE ENGINE OIL PUMP'S GASKETS + T - BELT PACK

264685	CM					2444.00	2444
1	15115-P8A-A01	2	PKG OIL HOLE		11.49	11.49	11
1	15825-P8A-A01	2	FILTER ASSY SPOOL		41.92	41.92	41
1	15221-RYE-A01	2	RING O		10.62	10.62	10
1	91212-5MR-A01	2	OIL SEAL 41X56X7		26.10	26.10	26
1	19200-RDV-J01	2	PUMP COMP WATER		350.70	350.70	350
1	14520-RCA-A01	2	TENSIONER COMP T/		371.22	371.22	371
1	CA666-88	8	ANTIFR HON TYPE 2		23.71	23.71	23
1	EHC2	ENVIRO FEE			0.38	0.38	0
1	14400-RCA-A01	2	BELT TIMING 197YU		136.91	136.91	136
6	12290-R40-A01	E	S PLUG ILZKR7B11S		33.39	33.39	200

150FFPART15% PARTS DISCOUNT
CR

PARTS: 17 -175 3441

ACURA OF THORNHILL
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
5417343018
WWW.NONE.COM

Cashier: Service

Transaction 1300358

Stock #/RO/Invoice: 60998

Total \$6,480.45

CREDIT CARD SALE \$6,480.45

VISA 0936

Retain this copy for statement validation

24-Jul-2024 5:42:34p.m.

\$6,480.45 | Method: EMV

VISA CREDIT

XXXXXXXXXXXX0916

VLADISLAV TOPA

Reference ID: 420600626861

Auth ID: 070392

MID: *****2319

AID: A0000000031010

AthNtwNm: VISA

PIN VERIFIED

TOTALS

AUTHORIZATION FOR REPAIRS: I hereby authorize the dealer to perform any and all repairs on my vehicle in the case of fire, theft or any other loss. I hereby agree to the cost of repairs and to the cost of any parts or labor required for the repairs. I agree to the cost of any parts or labor required for the repairs. I agree to the cost of any parts or labor required for the repairs.

EXCLUSION OF WARRANTIES: The undersigned party agrees that the dealer is not responsible for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealer with respect to disabling any Recording Equipment.

VIDEO RECORDING EQUIPMENT: The undersigned party agrees that the dealer is not responsible for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealer with respect to disabling any Recording Equipment.

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS, EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.

Terms: methods of payment include, debit, credit, and online payment.

X

Customer Signature

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than 10 per cent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties as the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - S12C - IMAGING


CUSTOMER COPY

Vehicle History Report


Accident/Damage

 There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.


Other Damage Records

RECORD DATE	DETAILS	AMOUNT
 2013 Aug 15	Ontario, Canada	
	Glass Record	\$121.00

Registration


 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

 This vehicle has been registered in the state of **California** in the **United States**. No major title problems were reported.

We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
 2011 Apr 15		AutoNation Acura South Bay Torrance, California, United States	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completedRecommended maintenance performed
2014 Oct 10	23,284 KM	Central Auto Niagara Fonthill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedOil and filter changed
2015 Feb 18	29,045 KM	Central Auto Niagara Fonthill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedOil and filter changed
2015 Jun 12	33,363 KM	Central Auto Niagara Fonthill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedAir filter replacedTire(s) balancedWiper(s) replaced
2015 Nov 6	40,290 KM	Central Auto Niagara Fonthill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedRecommended maintenance performedAir filter replacedCabin air filter replaced/cleaned

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> • Drivability/performance checked
2016 Mar 4	45,713 KM	Central Auto Niagara Fonthill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
2016 Jul 27	52,449 KM	Central Auto Niagara Fonthill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
2018 Sep 12		Avtar Auto Repair Etobicoke, Ontario, Canada	Vehicle serviced
2018 Dec 15	96,886 KM	Great Canadian Oil Change Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Fluids checked • Oil and filter changed
2019 Oct 19	112,545 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2020 May 7		Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Tire(s) changed
2020 Nov 7	118,650 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Brake rotor(s) replaced • Front brake pads replaced • Front brake rotor(s) replaced
2021 Apr 23	126,522 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Air filter checked • Oil and filter changed
2022 Mar 12	133,081 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Transmission fluid changed
2022 Mar 23	133,259 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Drive belt tensioner replaced
2022 Jul 23	137,489 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Alternator replaced
2022 Aug 6	140,018 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Engine checked • Heat shield secured • Oil and filter changed
2022 Sep 2	140,542 KM	Kal Tire - Mississauga Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Battery/charging system checked
2022 Dec 30	143,454 KM	Kal Tire - Mississauga Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire repaired
2023 Dec 8	156,380 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Vehicle serviced
2024 Jul 24	162,037 KM	Acura of Thornhill Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Air filter replaced • Brakes checked • Brake fluid flushed/changed • Cabin air filter replaced/cleaned

ODOMETER		SOURCE	DETAILS
			<ul style="list-style-type: none">Differential fluid flushed/changedDrive belt(s) replacedEngine oil pump replacedHood shocks replacedOil and filter changedPower steering checkedPower steering pump replacedSpark plug(s) replacedStrut(s) replacedTransmission fluid flushedVibration checked
2024 Aug 7	162,240 KM	Acura of Thornhill Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Axle(s) replacedEngine oil/fluid leak checkedOil and filter changedOil pan replaced/repaired
2024 Sep 25	162,262 KM	Acura of Thornhill Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Crankshaft position sensor replacedDrivability/performance checkedOil and filter changed



Open Recalls

✔ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact ACURA or visit [Acura's website](https://www.acura.ca/recalls). (https://www.acura.ca/recalls)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2011 Apr 15		AutoNation Acura South Bay Torrance, California, United States	Service Record	Vehicle serviced
 2011 Apr 19		Motor Vehicle Dept. California, United States	DMV Record Adjustment	Title issued or updated First Owner Reported
2012 Oct 8	1,606 KM	Auto Auction	Auction Announcement	Vehicle sold
2012 Oct 29		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
 2012 Oct 29		Motor Vehicle Dept. Canada	Import Record	From: United States To: Canada This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV

ODOMETER		SOURCE	RECORD TYPE	DETAILS
				www.riv.ca . Imported Into Canada As: Normal Case/Dossier: M332125 Import Date: 10/29/2012 Entered Customs: 10/29/2012 Inspection Date: 11/14/2012
2012 Nov 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Dealer took registration of this vehicle while it was in inventory Vehicle colour noted as black
2013 Feb 13	1,146 KM	Independent Source Fonthill, Ontario, Canada	Odometer reading	
2013 Aug 15		Insurance Records Ontario, Canada	Glass Record	\$121.00
2014 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Oct 10	23,284 KM	Central Auto Niagara Fonthill, Ontario, Canada	Service Record	Vehicle serviced
2015 Feb 18	29,045 KM	Central Auto Niagara Fonthill, Ontario, Canada	Service Record	Vehicle serviced
2015 Jun 12	33,363 KM	Central Auto Niagara Fonthill, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 6	40,290 KM	Central Auto Niagara Fonthill, Ontario, Canada	Service Record	Vehicle serviced
2016 Mar 4	45,713 KM	Central Auto Niagara Fonthill, Ontario, Canada	Service Record	Vehicle serviced
2016 Jul 27	52,449 KM	Central Auto Niagara Fonthill, Ontario, Canada	Service Record	Vehicle serviced
2016 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Apr 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 5	150,528 KM	Auto Auction Toronto, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS US VEHICLE
2018 Sep 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black

2HNYD2H7XBH532675

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Sep 12		Avtar Auto Repair Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 15	96,886 KM	Great Canadian Oil Change Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2019 May 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Oct 19	112,545 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2020 May 7		Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2020 Nov 7	118,650 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 23	126,522 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 12	133,081 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 23	133,259 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2022 Jul 23	137,489 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 6	140,018 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 2	140,542 KM	Kal Tire - Mississauga Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2022 Dec 30	143,454 KM	Kal Tire - Mississauga Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 8	156,380 KM	Star Auto Tech Inc. Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 May 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black

2HNYD2H7XBH532675

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jun 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2024 Jul 24	162,037 KM	Acura of Thornhill Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 7	162,240 KM	Acura of Thornhill Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2024 Sep 25	162,262 KM	Acura of Thornhill Thornhill, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.
Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge
The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>



CUSTOMER #: 1081049

60998

ACURA OF THORNHILL



Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

INVOICE

VLAD TOPA
511-3 ELLESMERE ST
RICHMOND HILL, ON L4B 4N2
HOME: CONT:437-981-2377
BUS: CELL:437-981-2377

PAGE 6

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	11	ACURA MDX	2HNYD2H7XBH532675		162038/162038	T5184	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN11 DD			09:30 22JUL24		188.00	CASH	24JUL24

R.O. OPENED READY OPTIONS: DLR:9141

08:50 22JUL24 16:20 24JUL24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

ESTIMATE: 5,819.64 22JUL24 15:39 SA: 269892

CONTACT:

*****THE FOLLOWING WORK WAS RECOMMENDED BUT NOT PERFORMED*****
,,SUMMARY ASR Tech Recommends - INSTALL LOWER HEAT SHIELDS

AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that neither the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described to secure the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described from freezing due to lack of antifreeze.

EXCLUSION OF WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased, and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of the its systems to perform with reasonable safety, efficiency, or comfort.

VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, located in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any member of the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges and agrees that the dealership shall not be liable for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealership with respect to disabling any Recording Equipment.

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS, EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.

Terms: methods of payment include, debit, credit, and online payment.

X

Customer Signature

DESCRIPTION	TOTALS
LABOUR AMOUNT	3245.45
PARTS AMOUNT	2917.24
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	8.28
TOTAL CHARGES	6170.97
LESS INSURANCE	435.48
SALES TAX	744.96
PLEASE PAY THIS AMOUNT	6480.45

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) per cent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SIZC - IMAGING

CUSTOMER COPY

CUSTOMER #: 1081049

60998

ACURA OF THORNHILL



Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

INVOICE

VLAD TOPA

511-3 ELLESMERE ST

RICHMOND HILL, ON L4B 4N2

HOME:

CONT:437-981-2377

BUS:

CELL:437-981-2377

PAGE 5

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	11	ACURA MDX		2HNYD2H7XBH532675		162038/162038		T5184
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
01JAN11 DD			09:30 22JUL24			188.00	CASH	24JUL24
R.O. OPENED		READY		OPTIONS: DLR:9141				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	264685	CM				188.00	188.00
1	56110-RYE-A05	A PUMP SUB ASSY P/S			1141.73	1141.73	1141.73
1	08285-P99-0CZF3	8 HONDA P/S FLUID			23.98	23.98	23.98
1	08285-P99-0CZF3	8 HONDA P/S FLUID			23.98	23.98	23.98

15OFFPART15% PARTS DISCOUNT

	CR					-178.45	-178.45
PARTS:	1189.69	LABOR:	188.00	OTHER:	-178.45	TOTAL LINE M:	1199.24

N** Miscellaneous Engine - REPLACE ENGINE OIL PUMP'S GASKETS + T - BELT PACK

CAUSE: OIL LEAKING

EN001 Miscellaneous Engine - REPLACE ENGINE OIL

PUMP'S GASKETS + T - BELT PACK

	264685	CM				2444.00	2444.00
1	15115-P8A-A01	2 PKG OIL HOLE			11.49	11.49	11.49
1	15825-P8A-A01	2 FILTER ASSY SPOOL			41.92	41.92	41.92
1	15221-RYE-A01	2 RING O			10.62	10.62	10.62
1	91212-5MR-A01	2 OIL SEAL 41X56X7			26.10	26.10	26.10
1	19200-RDV-J01	2 PUMP COMP WATER			350.70	350.70	350.70
1	14520-RCA-A01	2 TENSIONER COMP T/			371.22	371.22	371.22
1	CA666-88	8 ANTIFR HON TYPE 2			23.71	23.71	23.71
1	EHC2	ENVIRO FEE			0.38	0.38	0.38
1	14400-RCA-A01	2 BELT TIMING 197YU			136.91	136.91	136.91
6	12290-R40-A01	E S PLUG ILZKR7B11S			33.39	33.39	200.34

15OFFPART15% PARTS DISCOUNT

	CR					-175.95	-175.95
PARTS:	1173.01	LABOR:	2444.00	OTHER:	-175.57	TOTAL LINE N:	3441.44

AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that neither the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described to secure the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described from freezing due to lack of antifreeze.

EXCLUSION OF WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased; and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of the its systems to perform with reasonable safety, efficiency, or comfort.

VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, located in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any member of the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges and agrees that the dealership shall not be liable for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealership with respect to disabling any Recording Equipment.

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS. EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.

Terms: methods of payment include, debit, credit, and online payment.

X

Customer Signature

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) per cent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SIZC - IMAGING

CUSTOMER COPY

CUSTOMER #: 1081049

60998

ACURA OF THORNHILL



Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

INVOICE

VLAD TOPA

511-3 ELLESMERE ST

RICHMOND HILL, ON L4B 4N2

HOME:

CONT:437-981-2377

BUS:

CELL:437-981-2377

PAGE 1

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

POS: 1000

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A PERFORM SUB SYMBOL 3 DW-1 (W/TRANSFER CASE OIL CHANGE) SERVICE							
AUTOMATIC TRANS WITH TRANSFER CASE \$244.95 + ENVMNTL DISPOSAL							
FEES + TAXES							
91ACZ230 PERFORM SUB SYMBOL 3 DW-1 (W/TRANSFER							
CASE OIL CHANGE) SERVICE AUTOMATIC TRANS							
WITH TRANSFER CASE \$244.95 ENVMNTL DISPOSAL							
FEES TAXES							
						149.08	149.08
4	08707-ATF-DW1	C	HONDA ATFDW1	205L	12.20	12.20	48.80
4	ENV2 DISPOSAL FEE				0.81	0.81	3.24
1	90471-PX4-000	2	WASHER PLUG DRAIN		5.08	5.08	5.08
1	CA67008	8	75W85 HG0-1HYPO A		35.27	35.27	35.27
1	EHC3 ENVIRO FEE				0.14	0.14	0.14
2	94109-20000	8	WASHER DRAIN PLUG		1.67	1.67	3.34
15OFFPART15% PARTS DISCOUNT							
CR							
						-13.87	-13.87
PARTS: 92.49 LABOR: 149.08 OTHER: -10.49 TOTAL LINE A: 231.08							
162038 SERVICE COMPLETE							

B PERFORM SUB SYMBOL 6 REPLACE REAR DIFF FLUID \$119.95 + ENVMNTL							
DISPOSAL FEES + TAXES							
MM6 MAINTENANCE MINDER SERVICE SYMBOL 6 REAR							
DIFFERENTIAL FLUID FLUSH							
						61.03	61.03
3	08200-900-7AC	ACURA DPF II			17.25	17.25	51.75
					0.14	0.14	0.42
1	90471-PX4-000	2	WASHER PLUG DRAIN		5.08	5.08	5.08
1	94109-20000	8	WASHER DRAIN PLUG		1.67	1.67	1.67
15OFFPART15% PARTS DISCOUNT							
CR							
						-8.78	-8.78
PARTS: 58.50 LABOR: 61.03 OTHER: -8.36 TOTAL LINE B: 111.17							
162038 SERVICE COMPLETE							

C PERFORM MAINTENANCE SYMB A PLUS 5W-20 EST \$ 125.95 + ENVIRONMENTAL		
<p>AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that neither the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described to secure the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described from freezing due to lack of antifreeze.</p> <p>EXCLUSION OF WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased; and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.</p> <p>VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, located in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any member of the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges and agrees that the dealership shall not be liable for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealership with respect to disabling any Recording Equipment.</p> <p>WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS. EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.</p> <p>Terms: methods of payment include: debit, credit, and online payment.</p>	DESCRIPTION	TOTALS
	LABOUR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
PLEASE PAY THIS AMOUNT		
X _____		
Customer Signature		

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) per cent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - S2C - IMAGING

CUSTOMER COPY

CUSTOMER #: 1081049

60998

ACURA OF THORNHILL



ACURA

Thornhill-A, LP O/A Acura of Thornhill

88 STEELES AVENUE WEST

THORNHILL, ON L4J 1A1

Phone: (905) 747-6250

www.acuraofthornhill.com

INVOICE

VLAD TOPA

511-3 ELLESMERE ST

RICHMOND HILL, ON L4B 4N2

HOME:

CONT:437-981-2377

BUS:

CELL:437-981-2377

PAGE 2

ALL ITEMS ARE SUBJECT TO H.S.T.

H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR		YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
		11	ACURA MDX		2HNYD2H7XBH532675		162038/162038		T5184
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
01JAN11 DD			09:30 22JUL24			188.00	CASH	24JUL24	

R.O. OPENED READY OPTIONS: DLR:9141

08:50 22JUL24 16:20 24JUL24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

DISPOSAL FEES PLUS TAX

91ACZ221 PERFORM MAINTENANCE SYMB A PLUS 5W-20

EST \$ 125.95 ENVIRONMENTAL DISPOSAL FEES

PLUS TAX

264685 CM

1 15400-RTA-003 2 OIL FILTER CARTRI

14.72 14.72

55.39

1 EHC1 ENVIRO FEE

0.50 0.50

14.72

1 HO521-ONB-LK C 5W20 BULK OIL

45.60 45.60

0.50

1 ENV OIL AND FILTER DISPOSAL

3.50 3.50

45.60

1 65292 AM DRAIN PLUG'

6.24 6.24

3.50

15OFFPART15% PARTS DISCOUNT

CR

-9.98

PARTS: 66.56 LABOR:

55.39 OTHER:

-5.98 TOTAL LINE C:

-9.98

162038 SERVICE COMPLETE

115.97

PLEASE CHECK OIL LEVEL BEFORE PERFORMING OIL CHANGE. POSSIBLY BURNING OIL

91ACZ300 PLEASE CHECK OIL LEVEL BEFORE PERFORMING

OIL CHANGE. POSSIBLY BURNING OIL

264685 IMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D:

(N/C)

162038 INSPECTED , NO ENGINE OIL ON DIPSTICK . FOUND THE DRAIN PLUG

0.00

LEAKS (AFTER MARKET GASKET) . ENGINE OIL PUMP GASKETS . THE ENGINE

ALSO BURNS OIL . (PISTON RINGS)

ACURA OF THORNHILL COMPLIMENTARY EXTERIOR VEHICLE WASH

05ACZZ08 ACURA OF THORNHILL COMPLIMENTARY

EXTERIOR VEHICLE WASH

264685 IMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E:

(N/C)

** PERFORM SUB SYMBOL 7 REPLACE BRAKE FLUID \$162.95 ENVMTL DISPOSAL FEES + TAXES

91ACZ262 PERFORM SUB SYMBOL 7 REPLACE BRAKE FLUID

AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that neither the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described and secure the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described on freezing due to lack of antifreeze.

DISCLOSURE OF WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased; and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, mounted in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any member of the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges and agrees that the dealership shall not be liable for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of action taken by the dealership with respect to disabling any Recording Equipment.

USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS. EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.

Methods of payment include, debit, credit, and online payment.

X _____
Customer Signature

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than the maximum amount you authorized. In either case, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SIZC - IMAGING

CUSTOMER COPY

CUSTOMER #: 1081049

60998

ACURA OF THORNHILL



ACURA

Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

INVOICE

VLAD TOPA

511-3 ELLESMERE ST

RICHMOND HILL, ON L4B 4N2

HOME:

CONT: 437-981-2377

BUS:

CELL: 437-981-2377

PAGE 3

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR		YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG	
		11	ACURA MDX		2HNYD2H7XBH532675		162038/162038		T5184	
DEL DATE		PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT	INV. DATE
01JAN11 DD				09:30 22JUL24				188.00	CASH	24JUL24

R.O. OPENED READY OPTIONS: DLR:9141

08:50 22JUL24 16:20 24JUL24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
					\$162.95		
					264685		
					CM		
					2 08798-9008C 8 BRAKE FLUID DOT 3	8.95	15.68
					2 EHC5 ENVIRO FEE	0.05	0.10
					15OFFPART15% PARTS DISCOUNT		
					CR		
						-2.35	-2.35

PARTS: 15.68 LABOR: 147.17 OTHER: -2.25 TOTAL LINE F: 160.60
162038 PERFORMED BRAKE FLUID FLUSH

G** CHECK AND REPORT VIBRATION FROM STEERING WHEEL WHEN AT IDLE.

42ACZZ194 POWER STEERING

264685 IMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G: 0.00

162038 INSPECTED , VIBRATION ON STEERING WHEEL WHOLE TURNING AT LOW
SPEED . RECOMMEND TO START WITH REPLACING A STIFF P/S PUMP FLUSHING .
THE ENGINE FRONT AND SIDE MOUNTS ARE WEEK (TRANSFER NOISE , VIBRATION)

I** PLEASE CHECK HOOD STRUTS

03ACZZ52PT GENERAL INSPCETION

264685 IMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H: 0.00

162038 NEED TO REPLACE BOTH STRUTS

J** CUSTOMER REQUEST INSPECTION OF SPARK PLUG AND TIMING BELT TENSIONER

03ACZZ52PT GENERAL INSPCETION

264685 IMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE I: 0.00

162038 RECOMMEND TO REPLACE T- BELT PACK , SPARK PLUGS , OIL PUMP
GASKETS

K** MAINT SUB 2 - MDX/ZDX/RL/RLX - SUB SYMBOL 2 SERVICE FILTERS REPLACE
AIR CLEANER ELEMENT, REPLACE DUST AND POLLEN FILTER \$190.95
PLUS TAXES

AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described to secure the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described on freezing due to lack of antifreeze.

WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased; and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will be able any vehicle or any of the its systems to perform with reasonable safety, efficiency, or comfort.

VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, mounted in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any recording of the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges and agrees that the dealership shall not be liable for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealership with respect to disabling any Recording Equipment.

USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS. EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.

Methods of payment include, debit, credit, and online payment.

X _____
Customer Signature

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than 10% per cent above that estimate. In either case, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you have authorized. The Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDR Global, LLC SERVICE INVOICE TYPE 2 - S12C - IMAGING

CUSTOMER COPY

CUSTOMER #: 1081049

60998

ACURA OF THORNHILL



Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

INVOICE

VLAD TOPA

511-3 ELLESMERE ST

RICHMOND HILL, ON L4B 4N2

HOME: CONT:437-981-2377

BUS: CELL:437-981-2377

PAGE 4

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	11	ACURA MDX		2HNYD2H7XBH532675		162038/162038		T5184
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
01JAN11 DD			09:30 22JUL24			188.00	CASH	24JUL24

R.O. OPENED READY OPTIONS: DLR:9141

08:50 22JUL24 16:20 24JUL24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
91ACZ228	MAINT	SUB 2	- MDX/ZDX/RL/RLX	- SUB			
	SYMBOL 2	SERVICE	FILTERS	REPLACE	AIR CLEANER		
	ELEMENT,	REPLACE	DUST AND POLLEN	FILTER			
	\$190.95	PLUS	TAXES				
	264685	CM				106.78	106.78
1	80292-SDA-407	2	ELEMENT	FILTER	44.67	44.67	44.67
1	A3601CA	AM	ENGINE	AIR FILTER	39.50	39.50	39.50
15OFFPART15%	PARTS	DISCOUNT					
	CR					-12.63	-12.63
PARTS:	84.17	LABOR:	106.78	OTHER:	-12.63	TOTAL LINE J:	178.32

162038 SERVICE COMPLETE

K** REPLACE KEY FOB BATTERY

CAUSE: GENERAL SERVICE REQUEST

91ACZ300 GENERAL SERVICE REQUEST

264685 CM

2 72148-S0A-000EP 2 BATT LITH CR1616

6.99 0.00

0.00

PARTS: 13.98 LABOR: 0.00 OTHER: 0.00

TOTAL LINE K:

13.98

162038 SERVICE COMPLETE

L** Supports / Struts, Hood - Replace BOTH HOOD STRUTS

CAUSE: LEAKING , LEAK

BY62 Supports / Struts, Hood - Replace BOTH HOOD

STRUTS

264685 CM

1 74145-STX-A02 A OPEN STAY ASSY HO

111.58 111.58

111.58

1 74149-STX-A02 A OPEN STAY ASSY HO

111.58 111.58

111.58

15OFFPART15% PARTS DISCOUNT

CR

-33.47

-33.47

PARTS: 223.16 LABOR: 94.00 OTHER: -33.47

TOTAL LINE L:

283.69

M** Pump, Power Steering - Replace + FLUSHING

CAUSE: STIFF , VIBRATING

SR14 Pump, Power Steering - Replace + FLUSHING

AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that neither the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described and the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described from freezing due to lack of antifreeze.

EXCLUSION OF WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased; and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, located in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any member of the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges and agrees that the dealership shall not be liable for any loss, damage, expense, costs, delays or other liability whatsoever which the Customer may incur as a result of any action taken by the dealership with respect to disabling any Recording Equipment.

WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS, EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.

Terms: methods of payment include, debit, credit, and online payment.

X _____
Customer Signature

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than 10% (ten per cent) above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SIZC - IMAGING

CUSTOMER COPY

CUSTOMER #: 1081049

61347

ACURA OF THORNHILL



ACURA

INVOICE

Thornhill-A, LP O/A Acura of Thornhill
88 STEELES AVENUE WEST
THORNHILL, ON L4J 1A1
Phone: (905) 747-6250
www.acuraofthornhill.com

VLAD TOPA

511-3 ELLESMERE ST

RICHMOND HILL, ON L4B 4N2

HOME: CONT:437-981-2377

BUS: CELL:437-981-2377

PAGE 1

ALL ITEMS ARE SUBJECT TO H.S.T.
H.S.T. VENDOR NO 78478 7814 RT0001

SERVICE ADVISOR: 269892 Daveanand Khiali

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	11	ACURA MDX		2HNYD2H7XBH532675		162263/162263		T5427
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN11 DD			18:00 07AUG24		188.00	CASH	08AUG24	

R.O. OPENED READY OPTIONS: DLR:9141

16:26 07AUG24 14:37 08AUG24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	INSPECT	CHECK ENGINE LIGHT/	EMISSION WARNING ON ,	PLEASE ORDER CRANK			
		SHAFT POSITION SENSOR.					
		91ACZ300 ORDER AND REPLACE CRANK POSITION SENSOR					
		264685 CM			0.00		0.00
1	37500-R40-A01	2 SENSOR ASSY CRANK			257.90	257.90	257.90
PARTS:	257.90	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	257.90

150FFPART15%	PARTS DISCOUNT						
	CR				-38.69		-38.69

ESTIMATE: 188.00 07AUG24 16:26 SA: 269892

CONTACT:

28.50	
AUTHORIZATION FOR REPAIRS: I hereby authorize the repair work herein set forth to be done with the necessary tools and material and acknowledge and agree that neither the dealership nor any of its employees, agents or representatives shall be responsible for any loss or damage whatsoever to the vehicle or articles left in the vehicle in the case of fire, theft or any cause beyond their control or for any delays caused by unavailability of parts or delays in parts shipments by the dealership's suppliers or transporters. I hereby grant the dealership and/or dealership employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. The right to a lien under the Repair and Storage Lien Act is hereby acknowledged on the vehicle herein described to secure the cost of repairs thereto. I further acknowledge and agree that the dealership shall not be responsible for any loss or damage to the vehicle herein described from freezing due to lack of antifreeze.	
EXCLUSION OF WARRANTIES: The undersigned purchaser acknowledges and agrees that any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser acknowledges and agrees that the dealership makes no warranties of any kind, express or implied and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts or accessories purchased; and that in no event shall the dealership be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by the dealership, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of the its systems to perform with reasonable safety, efficiency, or comfort.	
VIDEO RECORDING EQUIPMENT: The Customer hereby acknowledges and agrees that all video recording equipment, including, but not limited to, dashboard cameras, located in the vehicle shall be disabled or turned off prior to the commencement of services provided by the dealership. The Customer expressly consents to any and agrees that the dealership disabling or turning off any such Recording Equipment in the event the Customer is unavailable to do so. The Customer further acknowledges any action taken by the dealership with respect to disabling any Recording Equipment.	
WE USE THE FLAT RATE HOUR SYSTEM PUBLISHED IN AN INDUSTRY ACCEPTED GUIDE LISTING REPRESENTATIVE TIME REQUIREMENTS FOR SPECIFIC VEHICLE REPAIRS/SERVICE WHICH MAY BE MORE OR LESS THAN THE ACTUAL CLOCK TIME. SERVICE CUSTOMER LABOUR CHARGES ARE BASED ON A FLAT RATE HOUR. WE WARRANT ALL PARTS AND LABOUR FOR ONE YEAR OR 20,000 KM ON ALL ACURA VEHICLES. ALL PARTS ARE NEW GENUINE ACURA UNLESS OTHERWISE SPECIFIED. DUE TO ENVIRONMENTAL REGULATIONS THERE IS A NOMINAL FEE FOR THE COLLECTION AND DISPOSAL OF HAZARDOUS MATERIALS, EXAMPLE OIL FILTER, ENGINE OIL, GLYCOL, TRANSMISSION FLUID.	
Terms: methods of payment include, debit, credit, and online payment.	
X	Customer Signature
DESCRIPTION	TOTALS
LABOUR AMOUNT	0.00
PARTS AMOUNT	257.90
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	257.90
LESS INSURANCE	38.69
SALES TAX	28.50
PLEASE PAY THIS AMOUNT	247.71

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than the maximum amount you authorized. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize. If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SIZC - IMAGING

CUSTOMER COPY

All About Tire And Wheel LTD.
401 Dissette Street, Unit 1,
Bradford, ON, L3Z 3G9

sales@allabouttire.ca
905-775-3232

All About Tire & Wheel

INVOICE

Arty Group INC

, ON CAN

Tax ID/VATIN: 732951272

Invoice Number: 8701
Customer Number: 2631
Invoice Date: Jun 17, 2024

Description	Quantity	Unit Price	Cost
Front Brake Pads	1	95.00 CAD	107.35 CAD
Front Brake Rotors	2	80.00 CAD	180.80 CAD
Remove and Replace Front Brakes	1.5	80.00 CAD	135.60 CAD
Front Sway Bar Links	2	44.00 CAD	99.44 CAD
Remove and Replace Sway Bar Links	1	80.00 CAD	90.40 CAD
Rear Sway Bar Links	2	41.50 CAD	93.79 CAD
Rear Sway Bar Bushing	2	27.50 CAD	62.15 CAD
Remove and Replace Sway Bar Bushing and Links	1.4	80.00 CAD	126.56 CAD
Oil Change	1	80.00 CAD	90.40 CAD
Tire Rebalance	1	40.00 CAD	45.20 CAD
Wheel Alignment	1	100.00 CAD	113.00 CAD
Subtotal			1,013.00 CAD
HST (13%)			131.69 CAD
Total			1,144.69 CAD

A11 About Tire And Wheel
401 DISSETTE ST
BRADFORD, ON L3Z 3G9
9057753232

TERM # 10064520
RECORD # 0000000011
HOST INVOICE # 0001337
HOST SEQ # 1000000011
MERCH INVOICE 1150

CARD *****4853
DEBIT/CHO C
2024/06/18 12:08:16

PURCHASE TOTAL \$1144.69

AUTH#:001147 B:382
HTS#: 20240618120816
TRANSACTION
APPROVED 000
THANK YOU

INTERAC
AID: A0000002771010
TC: EFB03B77EE74DA36
TVR: 8080008000
TSI: 6800

CUSTOMER COPY

Terms
It is recommended to re-check that torque after a few heat cycles because the metals expand at different rates and the lug nuts can loosen. Retorquing the wheels simply refers to having the lug nuts/wheel bolts on the wheels tightened again. Your lug nuts/wheel bolts were tightened to the manufacturer's torque specifications. It is generally 100 kms or the next day and it is standard practice to always do a retorque when wheels have been removed.