

Vehicle History Report #: 56573955 Report Date: October 1, 2024 | 9:28 a.m. EDT Report Status: Complete

2016 HYUNDAI VELOSTER

Coupe | 4 Cylinders | Gas KMHTC6AD8GU287966 Country of Assembly: Korea (South) Last Reported Odometer: 156,829 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



12 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



available to CARFAX Canada as of October 01, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
 - In the province of Saskatchewan with Normal branding.
 - · In the province of Ontario with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2016 Feb 12		Service Facility Prince Albert, Saskatchewan, Canada	Vehicle serviced • Pre-delivery inspection completed • Mud flaps/splash guards installed • Engine block heater installed	
2017 Mar 10	5,710 KM	Jiffy Lube - Prince Albert Prince Albert, Saskatchewan, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed	
2017 Jul 12	23,205 KM	Jiffy Lube - Prince Albert Prince Albert, Saskatchewan, Canada	Vehicle serviced a • Maintenance inspection completed • Oil and filter changed	
2019 Jan 6	50,475 KM	Jiffy Lube Kitchener, Ontario, Canada	Vehicle serviced - Oil and filter changed	
2019 Mar 20	54,230 KM	Kitchener Hyundai Kitchener, Ontario, Canada	Vehicle serviced • Front wheel bearing(s)/hub(s) replaced	
2019 Jun 22	63,038 KM	Jiffy Lube Kitchener, Ontario, Canada	Vehicle serviced Oil and filter changed	
2019 Oct 19	70,845 KM	Jiffy Lube Kitchener, Ontario, Canada	Vehicle serviced Oil and filter changed	
2020 May 20	82,500 KM	Great Canadian Oil Change Kitchener, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed • Antifreeze/coolant checked • Air filter checked	
2020 Nov 27	89,420 KM	Great Canadian Oil Change Kitchener, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed	

	ODOMETER	SOURCE	DETAILS	
2021 Feb 16	91,430 KM	Active Green & Ross Kitchener, Ontario, Canada	Vehicle serviced • Four wheel alignment performed	
2022 Mar 28	103,862 KM	The 401 Group of Companies - Barrie Kia Barrie, Ontario, Canada	Vehicle serviced	
2022 Dec 19	156,829 KM	London's Airport Kia London, Ontario, Canada	Vehicle serviced Tire(s) balanced Two tires balanced	100000000000000000000000000000000000000



Open Recalls

Recall #: R0204 | KSDS Installation Recall Date: 2021 Aug 02

Recall Description

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects Santa Fe models equipped with a 2.4 L MPI engine, and Veloster models with a 1.6 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)

Recall #: R0177 | Engine Inspection Recall Date: 2021 Sep 02

Recall Description

Issue: On certain vehicles equipped with a 1.6 L GDI, 2.0 L GDI, or 2.4 L MPI engine, the connecting rod bearings could wear prematurely. As a result, there could be an abnormal knocking noise from the engine and/or the oil pressure warning light may turn on. If you continue to drive the vehicle with worn connecting rod bearings, the engine could fail. An engine failure would cause a sudden loss of power with an inability to restart. In some cases, a damaged connecting rod could puncture the engine block and cause an oil leak. Note: For the Sonata model, only the Sonata Hybrid is affected by this recall. Additional Note: Engine compartment fires can happen for many different reasons. In some cases, there is too much damage to find the cause of a fire. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Oil that leaks onto a hot component could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer for an engine inspection test, to determine if there is bearing damage. If damage is found, the engine will be replaced. Dealers will also update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)

Recall #: C0525 - FS | Underbody Corrosion Recall Date: 2023 Mar 08

Recall Description

Issue: Hyundai Auto Canada is conducting a Special Service Campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. In extreme cases, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Feb 12		Service Facility Prince Albert, Saskatchewan, Canada	Service Record	Vehicle serviced
2017 Feb 2		Motor Vehicle Dept. Saskatchewan, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2017 Mar 10	5,710 KM	Jiffy Lube - Prince Albert Prince Albert, Saskatchewan, Canada	Service Record	Vehicle serviced
2017 Jul 12	23,205 KM	Jiffy Lube - Prince Albert Prince Albert, Saskatchewan, Canada	Service Record	Vehicle serviced
2018 jun 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2018 Oct 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2019 Jan 6	50,475 KM	Jiffy Lube Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 20	54,230 KM	Kitchener Hyundai Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 22	63,038 KM	Jiffy Lube Kitchener, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jul 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2019 Oct 19	70,845 KM	Jiffy Lube Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2020 May 20	82,500 KM	Great Canadian Oil Change Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 27	89,420 KM	Great Canadian Oil Change Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 16	91,430 KM	Active Green & Ross Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2021 Aug 2		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0204
2021 Sep 2	отника и су дини очени чен на подат су си те и су дин се на населения од се	HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0177
2022 Jan 1	98,000 KM	Independent Source Kitchener, Ontario, Canada	Odometer reading	
2022 Mar 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2022 Mar 28	103,862 KM	The 401 Group of Companies - Barrie Kia Barrie, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2022 Apr 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial Vehicle colour noted as gray
2022 Dec 19	156,829 KM	London's Airport Kia London, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 8		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0525 - FS
2024 Jun 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for on any errors, inaccuraries or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly oisclaim all warranties, express or implie, including any warranties of timeliness, accuracy, merchantability, merchantabi

© 2024 CARFAX Canada ULC. All rights reserved.

