



Vehicle History Report # 70592488
Report Date: June 15, 2026 | 12:34 p.m. EDT
Report Status: Complete

2012 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas
3VW2K7AJ1CM422683
Country of Assembly: Mexico
Last Reported Odometer: 103,676 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



7 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of June 15, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2015 Oct 9	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage with another motor vehicle Damage to front Damage to left front Damage to right front Vehicle towed	
2015 Dec 8	Ontario, Canada	
	Claim: Collision	\$2,180.00



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 May 4	8,998 KM	Erinwood Ford Sales Ltd Mississauga, Ontario, Canada	Vehicle serviced
2015 Dec 3	58,010 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Tire repaired Tire(s) changed
2016 Mar 31	62,185 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Tire condition and pressure checked
2016 Dec 2	72,392 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed
2017 Nov 16	88,458 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brake fluid flushed/changed

	ODOMETER	SOURCE	DETAILS
2019 Apr 16	101,126 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed Exterior trim checked Front brake pads replaced Front brake rotor(s) replaced Rear brake pads replaced Rear brake rotor(s) replaced
2019 Jun 17	103,676 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Spark plug(s) replaced



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 May 4	8,998 KM	Erinwood Ford Sales Ltd Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2013 May 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as white
2014 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Oct 9		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • minor damage • with another motor vehicle • Damage to front • Damage to left front • Damage to right front • Vehicle towed
2015 Dec 3	58,010 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2015 Dec 8		Insurance Records Ontario, Canada		
2016 Mar 31	62,185 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Dec 2	72,392 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2017 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Nov 16	88,458 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Apr 16	101,126 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jun 17	103,676 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2

3VW2K7A11CM422683

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Apr 27	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Apr 29	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2022 Apr 27	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2024 Apr 27	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2026 Apr 27	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

