



Vehicle History Report #: 68958988
Report Date: April 11, 2026 | 12:03 p.m. EDT
Report Status: Complete

2016 VOLKSWAGEN GOLF S/SE

Hatchback | 4 Cylinders | Gas
3VW217AU6GM069456
Country of Assembly: Mexico
Last Reported Odometer: 215,847 KM

One Owner™ >



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



44 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of April 11, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5GM069456

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
! 2017 Sep 24	Toronto, Ontario, Canada	
	Estimate: Rear Center Estimate Date: 2017 Sep 26 Claim: Other Damage	\$1,233.17 \$1,233.00
! 2018 Mar 31	Toronto, Ontario, Canada	
	Estimate: Left Rear Corner Estimate Date: 2018 Apr 9 Claim: Other Damage	\$1,144.24 \$1,144.00
! 2019 Nov 26	Toronto, Ontario, Canada	
	Estimate: Rear Center Estimate Date: 2019 Dec 4 Claim: Collision	\$1,462.83 \$1,634.00



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Sep 1		Volkswagen Downtown Toronto Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2016 Sep 15	1,279 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Body electrical wiring repaired
2016 Dec 19	8,253 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Four tires replaced Oil and filter changed Tire(s) replaced

3VW217AU6GM069456

	ODOMETER	SOURCE	DETAILS
2017 Apr 19	14,854 KM	Volkswagen Downtown Toronto Toronto, Ontario, Canada	Vehicle serviced
2017 May 25	17,407 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2017 Sep 8	24,391 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced
2017 Sep 19	25,378 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Key(s) (re) programmed Oil and filter changed
2017 Oct 24	27,238 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Drivability/performance checked
2017 Nov 20	28,614 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire(s) mounted
2018 Mar 7	35,108 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2018 Apr 16	38,703 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire repaired Tire(s) mounted
2018 Sep 19	48,496 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2018 Nov 6	51,576 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire(s) mounted
2019 Feb 20	59,600 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tires rotated
2019 Jun 5	66,661 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tires rotated
2019 Oct 8	73,790 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tires rotated
2019 Nov 13	76,048 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Alignment performed Tire(s) mounted
2020 Feb 26	82,995 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tires rotated
2020 Mar 31		Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Cooling system checked Drivability/performance checked Thermostat replaced Transmission computer/module reprogrammed

3VW217AU6GM069456

	ODOMETER	SOURCE	DETAILS
2020 May 17		Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced
2020 Sep 22	91,861 KM	Town and Country Volkswagen Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance reminder reset Oil and filter changed
2021 May 19	106,374 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2021 Oct 14	113,954 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Front brake pads replaced Front brake rotor(s) replaced Parking brake adjusted Rear brake pads replaced Rear brake rotor(s) replaced
2022 Mar 9	120,756 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2022 May 11	123,281 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> A/C system checked Nitrogen fill tires Refrigerant added for leak check checked Tire condition and pressure checked
2022 May 31	124,798 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire(s) replaced Wheel lug nuts torqued
2022 Aug 2	129,316 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter replaced Oil and filter changed
2022 Nov 17	136,722 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire(s) replaced Wheel bearing(s) serviced
2023 May 17	145,573 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2023 Jul 19	150,664 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire condition and pressure checked
2023 Nov 17	158,691 KM	Town and Country Volkswagen Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Inspection performed Alignment checked
2023 Nov 23	158,889 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked

3VW217AU6GM069456

	ODOMETER	SOURCE	DETAILS
2024 Jan 11	163,107 KM	Master Mechanic Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Cabin air filter replaced/cleaned CV boot(s) replaced Headlight bulb(s) replaced Headlight(s) replaced Lights checked Oil and filter changed Tire condition and pressure checked
2024 May 14	172,040 KM	My Mechanic Auto & Tire Centre - Ellesmere Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Axles checked Oil and filter changed
2024 Aug 2	172,322 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Blower motor replaced/repaired Blower motor resistor replaced Blower motor serviced
2024 Oct 9	181,540 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Oil pan replaced/repaired
2025 Mar 14		Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2025 Apr 1	193,984 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Antifreeze/coolant checked Antifreeze/coolant flushed/changed Cooling system checked Thermostat replaced Water pump gasket replaced Water pump replaced
2025 Apr 23	195,820 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Four wheel alignment performed Front strut(s) replaced Strut(s) replaced
2025 Aug 25	203,479 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2025 Sep 26	204,557 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Battery/charging system checked Ignition switch replaced
2025 Nov 13	207,827 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Brake rotor(s) replaced Brakes serviced Four wheel alignment performed Front brake pads replaced Front brake rotor(s) replaced Front brake rotor(s) resurfaced Rear brakes serviced/adjusted Tire(s) changed
2025 Dec 18		Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Drivability/performance checked Emission system checked Oxygen sensor replaced

3WV217AU6GM069456

	ODOMETER	SOURCE	DETAILS
2026 Mar 6	215,847 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Alignment checked • Engine checked • Four wheel alignment performed • Tire condition and pressure checked



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Sep 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2016 Sep 1		Volkswagen Downtown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 15	1,279 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2016 Dec 19	8,253 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced

3VW217AU6GM069456

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Mar 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Apr 19	14,854 KM	Volkswagen Downtown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 May 25	17,407 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Sep 8	24,391 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Sep 19	25,378 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Sep 24		Insurance Records Ontario, Canada		
2017 Sep 26	26,200 KM	Insurance Records Toronto, Ontario, Canada	Estimate Repair	Incident Date: 2017-09-24 Rear Center
2017 Oct 24	27,238 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 20	28,614 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 7	35,108 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 31		Insurance Records Ontario, Canada		
2018 Apr 9	38,044 KM	Insurance Records Toronto, Ontario, Canada	Estimate Repair	Incident Date: 2018-03-31 Left Rear Corner
2018 Apr 16	38,703 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 19	48,496 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 6	51,576 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Feb 20	59,600 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 5	66,661 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 8	73,790 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced

3VW217AU6GM069456

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Nov 13	76,048 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 26		Insurance Records Ontario, Canada		
2019 Dec 4	76,771 KM	Insurance Records Toronto, Ontario, Canada	Estimate Repair	Incident Date: 2019-11-26 Rear Center
2020 Feb 26	82,995 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Mar 31		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 May 17		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 22	91,861 KM	Town and Country Volkswagen Markham, Ontario, Canada	Service Record	Vehicle serviced
2021 May 19	106,374 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 14	113,954 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 9	120,756 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 May 11	123,281 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 May 31	124,798 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 2	129,316 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 17	136,722 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2023 May 17	145,573 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 19	150,664 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 17	158,691 KM	Town and Country Volkswagen Markham, Ontario, Canada	Service Record	Vehicle serviced

3VW217AU6GM069456

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Nov 23	158,889 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 11	163,107 KM	Master Mechanic Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 May 14	172,040 KM	My Mechanic Auto & Tire Centre - Ellesmere Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 2	172,322 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2024 Oct 9	181,540 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Mar 14		Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Apr 1	193,984 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Apr 23	195,820 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Aug 25	203,479 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Sep 26	204,557 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Nov 13	207,827 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2025 Dec 18		Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2026 Mar 6	215,847 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2026 Mar 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

3VW217AU6GM069456

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.



3VW217AU6GM069456