



Vehicle History Report #: 50850381
Report Date: January 20, 2024 | 10:37 AM EST
Report Status: Complete

2016 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas
5N1AR2MM3GC621725
Country of Assembly: United States
Last Reported Odometer: 137,855 KM

No Reported Accidents



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



18 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of January 20, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.
We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Feb 22		Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Bumper guards installed
2016 Jul 7	7,266 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced
2016 Aug 16	8,216 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery/charging system checked Exhaust system checked Driveshaft checked Fluids checked Oil and filter changed Tire condition and pressure checked
2016 Aug 29		Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Fabric protection applied Paint protection applied Accessories installed Window tint installed
2016 Sep 30	11,133 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed
2017 Sep 23	30,169 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2017 Oct 19	30,887 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Transfer case removed to complete repairs
2018 Mar 27	37,379 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Seatbelt(s) repaired Oil and filter changed
2018 Jul 24	45,675 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2019 Jul 30	61,918 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Air filter checked Air filter replaced

5N1AR2MM3GC621725

	ODOMETER	SOURCE	DETAILS
2020 Aug 6	78,335 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2020 Dec 17	86,934 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Air filter checked Air filter replaced
2021 Jul 7	95,571 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed
2021 Oct 9	103,663 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed
2022 Jul 21	111,848 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter replaced Fluids checked Oil and filter changed Air filter checked
2023 Jan 5	128,804 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed
2023 Jun 10	129,497 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter replaced Fluids checked Oil and filter changed Air filter checked
2023 Dec 2	137,855 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed



Open Recalls

Recall #: R22A2 | PATH HOOD LOCK ASSY NTB22053 Recall Date: 2022 Jun 28

Recall Description

ON CERTAIN 2013-2016 PATHFINDER VEHICLES, DUST OR DIRT CONTAMINATION MAY ACCUMULATE ON AND AROUND THE SECONDARY LATCH LEVER PIVOT JOINT. OVER TIME, THE BUILD-UP OF CONTAMINATION, COMBINED WITH A LACK OF PROPER INSPECTION AND MAINTENANCE OF THE SECONDARY LATCH (AS DESCRIBED IN THE OWNER'S MANUAL), CAN CREATE MECHANICAL BINDING THAT COULD CAUSE THE LEVER TO REMAIN IN THE OPEN POSITION AFTER IT HAS BEEN DISENGAGED. IN ADDITION, THIS CONTAMINATION CAN SCRATCH THE SECONDARY LATCH'S PROTECTIVE ANTI-CORROSION COATING, ALLOWING CORROSION OF THE BARE METAL IN THE PIVOT JOINT.

Remedy

NISSAN WILL MAIL AFFECTED OWNERS AN INTERIM OWNER LETTER THAT WILL INSTRUCT THE OWNERS HOW TO PROPERLY INSPECT THE HOOD LOCK AND SECONDARY LATCH FOR PROPER WORKING CONDITION (NO STICKING). IF THE LEVER MOVES FREELY, THE OWNER CAN CLEAN AND CONDITION THE LEVER PER THE OWNER'S MANUAL GENERAL MAINTENANCE REQUIREMENTS IN SECTION 8 MAINTENANCE AND

5N1AR2MM3GC621725

DIY . IF THE LEVER DOES NOT MOVE FREELY, THE CUSTOMER WILL BE INSTRUCTED TO TAKE THEIR VEHICLE TO A NISSAN DEALER. THE DEALER WILL INSPECT THE HOOD LOCK AND SECONDARY LATCH AND, IF FUNCTIONING PROPERLY, CLEAN AND CONDITION BY APPLYING LUBRICANT. IF EITHER OF THESE COMPONENTS DO NOT FUNCTION PROPERLY, THE HOOD LOCK AND/OR SECONDARY LATCH WILL BE REPLACED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Feb 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2016 Feb 22		Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2016 Jul 7	7,266 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2016 Aug 16	8,216 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2016 Aug 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 Aug 29		Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 30	11,133 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Sep 23	30,169 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2017 Oct 19	30,887 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 27	37,379 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced

5N1AR2MM3GC621725

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Jul 24	45,675 KM	Hunt Club Nissan Ltd Nepean, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2019 Jan 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Apr 23	58,244 KM	Independent Source Ottawa, Ontario, Canada	Odometer reading	
2019 Jul 30	61,918 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 6	78,335 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 17	86,934 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 7	95,571 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 9	103,663 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Jun 28		NISSAN	Recall	Manufacturer Recall Issued Recall # R22A2
2022 Jul 21	111,848 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2023 Jan 5	128,804 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 10	129,497 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 2	137,855 KM	Great Canadian Oil Change Ottawa, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

5N1AR2MM3GC621725

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2024 CARFAX Canada ULC. All rights reserved.



5N1AR2MM3GC621725