



Vehicle History Report #: 61332964  
Report Date: May 9, 2025 | 3:49 p.m. EDT  
Report Status: Complete

# 2014 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas  
5N1AR2MM5EC643822  
Country of Assembly: United States  
Last Reported Odometer: 148,645 KM



Accident/Damage Records Found



Last Registered In:  
Ontario (Normal)




3 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 09, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5N1AR2MM5EC643822

# Vehicle History Report



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2015 Feb 12	<b>North York, Ontario, Canada</b>	
	<b>Estimate:</b> Left Side   Estimate Date: 2015 Mar 10	\$1,719.23
	<b>Claim:</b> Other Damage	\$1,719.00



## Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.  
**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2023 Mar 2	147,144 KM	Maple Nissan Maple, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> </ul>
2023 May 9	148,645 KM	Scarborough Toyota Scarborough, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Air filter replaced</li> <li>Brakes serviced</li> <li>Front wiper blades/refills replaced</li> <li>Light bulb(s) replaced</li> <li>Oil and filter changed</li> <li>Oil pan replaced/repaired</li> </ul>
2023 May 21		Scarborough Toyota Scarborough, Ontario, Canada	<b>Vehicle serviced</b>



## Open Recalls

Recall #: R24C6 | PTH HD LTH FNL RPR NTB25-010 Recall Date: 2025 Feb 10

### Recall Description

ON CERTAIN 2013-2016 PATHFINDER VEHICLES, DUST OR DIRT CONTAMINATION MAY ACCUMULATE ON AND AROUND THE SECONDARY LATCH LEVER PIVOT JOINT. OVER TIME, THE BUILD-UP OF CONTAMINATION, COMBINED WITH A LACK OF PROPER INSPECTION AND MAINTENANCE OF THE SECONDARY LATCH (AS DESCRIBED IN THE OWNER S MANUAL), CAN CREATE MECHANICAL BINDING THAT COULD CAUSE THE LEVER TO REMAIN IN THE OPEN POSITION AFTER IT HAS BEEN DISENGAGED. IN ADDITION, THIS CONTAMINATION CAN SCRATCH THE SECONDARY LATCH S PROTECTIVE ANTI-CORROSION COATING, ALLOWING CORROSION OF THE BARE METAL IN THE PIVOT JOINT.

5N1AR2MM5EC643822

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](https://www.nissanusa.com/recalls-vin.html). (https://www.nissanusa.com/recalls-vin.html)



## Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Nov 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as brown
2015 Feb 12		Insurance Records Ontario, Canada		
2015 Mar 10	36,344 KM	Insurance Records North York, Ontario, Canada	Estimate Repair	Incident Date: 2015-02-12 Left Side
2015 May 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 May 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2022 May 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as brown
2023 Mar 2	147,144 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2023 Apr 18	148,639 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2023 May 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as brown
2023 May 9	148,645 KM	Scarborough Toyota Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2023 May 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as brown
2023 May 21		Scarborough Toyota Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2024 Sep 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

5N1AR2MM5EC64382Z

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2025 Feb 10	NISSAN	Recall	Manufacturer Recall Issued Recall # R24C6



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.  
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

