

# 2021 VOLKSWAGEN ATLAS SEL PREMIUM R-LINE

Sport utility vehicle | 6 Cylinders | Gas  
1V2FR2CA2MC515004  
Country of Assembly: United States  
Last Reported Odometer: 128,144 KM



Accident/Damage Records Found



Last Registered In:  
Ontario (Normal)



3 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 06, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2022 Apr 15	Ontario, Canada	
	<b>Police Reported Accident:</b> Accident reported: minor damage It hit a stationary object Damage to right front	
2023 Dec 29	Hamilton, Ontario, Canada	
	<b>Estimate:</b> Total Loss   Estimate Date: 2024 Mar 25 <b>Claim:</b> Theft	\$5,927.74 \$49,642.00



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.  
*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Aug 15		Milton Volkswagen Milton, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li><li>Vehicle washed/detailed</li></ul>
2020 Nov 20		Sarnia Volkswagen Sarnia, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li><li>Wheel locks installed</li><li>Vehicle washed/detailed</li></ul>
2025 Jul 10	128,144 KM	Euromotive Auto Service Niagara On The Lake, Ontario, Canada	<b>Vehicle serviced</b>



## Open Recalls

Recall #: 87H4 | AIR CONDITIONING WATER DRAIN TUBE    Recall Date: 2021 Nov 24

### Recall Description

The water drain tube of the air conditioning system could become blocked. If this happens, water can accumulate and leak inside the vehicle,

and may contact the airbag control module. This can cause airbag system malfunctions, including unwarranted airbag deployment. This may increase the risk for an injury or may lead to a crash without warning. If this condition is present in the vehicle, the airbag warning light may illuminate if a malfunction is detected.

#### Remedy

Affected vehicles will be inspected and, if a blocked drain tube is found, repaired. The airbag control unit will be replaced for those vehicles where a blocked drain tube was found.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

Recall #: 97GF | FRONT DOOR WIRING HARNESS Recall Date: 2022 Mar 18

#### Recall Description

In special side crash situations, the front side airbag may deploy later than designed. This may be caused by excessive micromovement, leading to fretting corrosion of the door wiring harness terminal contacts. In the event of a side crash, when the side airbag deployment may be necessary, the side airbag may deploy later than designed. This may lead to an increased injury to vehicle occupants.

#### Remedy

To identify and correct this defect, authorized Volkswagen dealers will check both front doors to determine if diagnostic trouble (fault) code(s) specific to the affected wiring harness are present. If the fault code(s) are present for a front door, the affected wiring harness will be replaced in that door. Harnesses will be modified with a zip tie to secure them, and a stabilizing compound will be applied to the terminal ends of the affected wiring harness connectors. If fault codes are not found, the existing wiring harness will be modified with a zip tie to secure it and a stabilizing compound will be applied to the terminal ends of the affected wiring harness connector(s). This work will take about two hours to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



## Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Aug 15		Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 20		Sarnia Volkswagen Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Nov 24		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 87H4
2022 Mar 18		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 97GF
2022 Apr 15		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> <li>• minor damage</li> <li>• It hit a stationary object</li> <li>• Damage to right front</li> </ul>
2023 Nov 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2023 Dec 29		Ontario, Canada	Theft	
2023 Dec 29		Insurance Records Hamilton, Ontario, Canada	Estimate Repair	Estimate Date: 2024-03-25 Total Loss
2024 Feb 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2024 Oct 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2024 Nov 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2025 Jul 10	128,144 KM	Euromotive Auto Service Niagara On The Lake, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



1V2FR2CA2MC515004