



Vehicle History Report #: 67897527

Report Date: February 25, 2026 | 6:08 p.m. EST

Report Status: Complete

2011 VOLKSWAGEN JETTA

Sedan | 4 Cylinders | Gas

3VWDK7AJ8BM375496

Country of Assembly: Mexico

Last Reported Odometer: 128,629 KM



Accident/Damage Records Found



Last Registered In:
Alberta (Normal)



7 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of February 25, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VWDK7AJ8BM375496

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2022 Oct 23	Alberta, Canada	
	Police Reported Accident: Accident reported Damage to front	



Registration

This vehicle has been registered in the province of **Alberta** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Oct 4	22,832 KM	Service Facility Calgary, Alberta, Canada	Vehicle serviced
2014 Jul 15		Service Facility Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Interior trim checked
2014 Jul 16		Service Facility Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Trim checked
2014 Jul 25	60,004 KM	Service Facility Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2018 Jul 27	73,225 KM	Southgate Volkswagen Edmonton, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Fuel filter replaced Ignition coil(s) replaced Spark plug wires replaced Spark plug(s) replaced Tire condition and pressure checked
2019 Apr 22	81,008 KM	Fifth Avenue Volkswagen Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery replaced Headlight bulb(s) replaced
2025 Sep 24	200,000 KM	Fifth Avenue Volkswagen Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery replaced No-start/hard start condition checked Serpentine belt replaced

3VWDK7AJ8BM375496



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Apr 27		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as medium brown
2013 Oct 4	22,832 KM	Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2014 Jan 19	23,891 KM	Independent Source Calgary, Alberta, Canada	Odometer reading	
2014 Jul 15		Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2014 Jul 16		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as medium brown
2014 Jul 16		Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced

3VWVK7AJ8BM375496

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Jul 25	60,004 KM	Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2015 Mar 14		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2016 Apr 16		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2017 Apr 21		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2018 Jun 22		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2018 Jul 27	73,225 KM	Southgate Volkswagen Edmonton, Alberta, Canada	Service Record	Vehicle serviced
2019 Mar 23		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2019 Apr 22	81,008 KM	Fifth Avenue Volkswagen Calgary, Alberta, Canada	Service Record	Vehicle serviced
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Mar 5		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2020 Nov 23		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2021 Oct 2		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2022 Oct 3		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium brown
2022 Oct 23		Police Reported Accident Alberta, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> Damage to front
2025 Sep 24	200,000 KM	Fifth Avenue Volkswagen Calgary, Alberta, Canada	Service Record	Vehicle serviced
2026 Jan 10	128,629 KM	Independent Source Calgary, Alberta, Canada	Odometer reading	

3VWDK7AJ8BM375496



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

