



## 2019 HYUNDAI SANTA FE XL SE

Sport utility vehicle | 6 Cylinders | Gas KM8SNDHF3KU303680 Country of Assembly: Korea (South) Last Reported Odometer: 156,761 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



9 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of January 05, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report**



There are no accidents/damage reported on this vehicle.



## Registration

- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
  - In the province of **Québec** with **Normal** branding.
  - In the province of **Ontario** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



### **Service Records**

DATE	ODOMETER	SOURCE	DETAILS	
2018 Dec 27		Genesis Saint-Laurent	Vehicle serviced	
		Saint-Laurent, Québec, Canada	Tire(s) balanced	
2020 Apr 21	48,362 KM	Baril Ford Lincoln, Inc.	Vehicle serviced	
		Saint-Hyacinthe, Québec, Canada	Oil and filter changed	
2020 Nov 16	64,652 KM	Le Nouveau Hyundai Granby Granby, Québec, Canada	Vehicle serviced	
2021 Sep 20	85,273 KM	Jean Dumas Hyundai	Vehicle serviced	
		Saint-Felicien, Québec, Canada	Oil and filter changed	
2022 Aug 19	107,361 KM	Pennzoil 10 Minute Oil Change	Vehicle serviced	
		Burlington, Ontario, Canada	Air filter replaced	
			<ul><li>Oil and filter changed</li><li>Cabin air filter replaced/cleaned</li></ul>	
			Cabiii aii ilitei repiaceu/clearieu	
2023 Aug 19	129,993 KM	Pennzoil 10 Minute Oil Change	Vehicle serviced	
		Burlington, Ontario, Canada	Oil and filter changed	
2024 Apr 13	145,192 KM	Pennzoil 10 Minute Oil Change	Vehicle serviced	
		Burlington, Ontario, Canada	Oil and filter changed	
2024 Apr 24	145,789 KM	Pennzoil 10 Minute Oil Change	Vehicle serviced	
		Burlington, Ontario, Canada	Tires rotated	
2024 Dec 9	156,761 KM	Meadowvale Tirecraft	Vehicle serviced	
		Mississauga, Ontario, Canada	Vehicle washed/detailed	



Recall #: R0188 | Supplemental Canister Installation Recall Date: 2021 Apr 04

#### **Recall Description**

Environment Canada Recall ECR H003-21-002 Affected vehicles may exceed evaporative emissions standards. Dealers will install a supplemental evaporative canister.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**. (https://recall.hyundaicanada.com/)

Recall #: C0525 - NC | Underbody Corrosion Recall Date: 2023 Mar 08


#### **Recall Description**

Issue: Hyundai Auto Canada is conducting a Special Service Campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. In extreme cases, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)



### **Stolen Vehicle Check**





### **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Dec 19		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Québec, Canada		First Owner Reported
				Previous Use: Commercial
2018 Dec 27		Genesis Saint-Laurent	Service Record	Vehicle serviced
		Saint-Laurent, Québec, Canada		
2020 Apr 8		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Québec, Canada		Previous Use: Commercial
2020 Apr 21	48,362 KM	Baril Ford Lincoln, Inc.	Service Record	Vehicle serviced
		Saint-Hyacinthe, Québec,		
		Canada		
2020 Nov 16	64,652 KM	Le Nouveau Hyundai Granby	Service Record	Vehicle serviced
		Granby, Québec, Canada		

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Apr 4		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0188
2021 Apr 7		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2021 Sep 20	85,273 KM	Jean Dumas Hyundai Saint-Felicien, Québec, Canada	Service Record	Vehicle serviced
2021 Dec 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as black
2022 Aug 19	107,361 KM	Pennzoil 10 Minute Oil Change Burlington, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Mar 8		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0525 - NC
2023 Aug 19	129,993 KM	Pennzoil 10 Minute Oil Change Burlington, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 13	145,192 KM	Pennzoil 10 Minute Oil Change Burlington, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 24	145,789 KM	Pennzoil 10 Minute Oil Change Burlington, Ontario, Canada	Service Record	Vehicle serviced
2024 Oct 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as black
2024 Dec 9	156,761 KM	Meadowvale Tirecraft Mississauga, Ontario, Canada	Service Record	Vehicle serviced



# Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

