



Vehicle History Report #: 58756751
Report Date: January 17, 2025 | 4:25 p.m. EST
Report Status: Complete

2015 GMC TERRAIN SLE

Sport utility vehicle | 4 Cylinders | Flexible

2GKALMEK1F6342607

Country of Assembly: Canada

Last Reported Odometer: 129,019 KM



Accident/Damage Records Found



Last Registered In:
Alberta (Rebuilt/Rebuildable)



5 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of January 17, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report

Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2022 Nov 1	Calgary, Alberta, Canada	
	Police Reported Accident: Accident reported: minor damage Damage to rear Damage to left rear	
	Estimate: Total Loss Estimate Date: 2022 Nov 8	\$13,236.75
	Claim: Collision	\$14,593.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2024 Aug 23	n/a	
	Damage Event: Damage reported Damage to rear	

Registration

1 This vehicle has been registered in the following locations in Canada (listed oldest to newest): - In the province of Alberta with Normal branding. - In the province of Alberta with Salvage branding. - In the province of Alberta with Rebuilt/Rebuildable branding. <i>We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.</i>

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Jan 12	59,570 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Vehicle serviced Oil and filter changed
2020 Mar 2	83,440 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Air filter checked
2021 Jan 24	96,548 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Vehicle serviced - Maintenance inspection completed - Fluids checked

ODOMETER	SOURCE	DETAILS
		- Oil and filter changed - Air filter checked
2021 Jul 19	102,494 KM	Great Canadian Oil Change Calgary, Alberta, Canada Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Air filter checked - Radiator checked - Air filter replaced - Cabin air filter checked
2022 May 8	103,420 KM	Great Canadian Oil Change Calgary, Alberta, Canada Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Radiator checked - Fuel injection system checked



Open Recalls

- No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact GMC or visit **GM's website**. (<https://my.gm.ca/gm/en/recalls>)



Stolen Vehicle Check

- This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Dec 22		Motor Vehicle Dept. Calgary, Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Rental Vehicle colour noted as black
2016 Aug 31		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2017 Aug 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2018 Aug 31		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2019 Jan 12	59,570 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Service Record	Vehicle serviced
2019 Aug 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Mar 2	83,440 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Service Record	Vehicle serviced
2020 Aug 31		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2021 Jan 24	96,548 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Service Record	Vehicle serviced
2021 Jul 19	102,494 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Service Record	Vehicle serviced
2021 Aug 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 May 8	103,420 KM	Great Canadian Oil Change Calgary, Alberta, Canada	Service Record	Vehicle serviced
2022 Aug 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 Nov 1		Police Reported Accident Alberta, Canada	Police Report	Accident Reported: • minor damage • Damage to rear • Damage to left rear
2022 Nov 1		Insurance Records Alberta, Canada		
2022 Nov 8	129,019 KM	Insurance Records Calgary, Alberta, Canada	Estimate Repair	Incident Date: 2022-11-01 Total Loss
2022 Nov 28		Alberta, Canada	Registration Event	Salvage
2024 Aug 23			Damage Event	Damage reported Damage to rear
2024 Sep 1		Auto Auction	Auction Announcement	Vehicle sold
2025 Jan 2		Motor Vehicle Dept. Alberta, Canada	Registration Records	Registered/Renewed
2025 Jan 2		Alberta, Canada	Registration Event	Rebuilt/Rebuildable



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information

VIN 2 G K A L M E K 1 F 6 3 4 2 6 0 7

Make

GMC

Model

Terrain

Year

2015

Odometer

129078

Customer Information

Organization Name

Prime Autos

Address

121 42 Ave SE

Postal Code

T2G2L2

Section 1 - Pre-Inspection

Component	P	F	NA	Component	P	F	NA
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓		
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓		
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓		
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓		
1.3a. CV Joint Road Test Result	✓			1.3g. Odometer (if equipped) Operation	✓		
1.3b. Universal Joint Road Test Result	✓						

NOTES:

Section 2 - Onboard Diagnostic Systems

Component	P	F	NA	Component	P	F	NA
2.1a. PCM Codes Present	✓			2.4b. SRS Lamp Fails To Illuminate	✓		
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate	✓			2.4c. SRS Lamp Remains Illuminated	✓		
2.2a. ABS Codes Present	✓			2.4d. Airbag(s) Present	✓		
2.2b. ABS Lamp Fails To Illuminate	✓			2.4e. Airbag Cover Integrity	✓		
2.2c. ABS Lamp Remains Illuminated	✓			2.5. Electronic Stability Control (ESC)	✓		
2.3a. Brake System Warning Lamp Fails To Illuminate	✓			2.6. Powertrain Warning Lamps	✓		
2.3b. Brake System Warning Lamp Remains Illuminated	✓			2.7. Other Safety Systems	✓		
2.4a. SRS Codes Present	✓						

NOTES:

Section 3 - Interior

Component	P	F	NA	Component	P	F	NA
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓		
3.2. Rear View Mirror	✓			3.12. HVAC	✓		
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓		
3.4. Horn	✓			3.14. Accelerator	✓		
3.5. Seats	✓			3.15. Service Brake Pedal	✓		
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly			✓
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓		
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓		
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout	✓		
3.10. Auxiliary Lamp Indicator(s)	✓						

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass								
Component	P	F	NA	Component	P	F	NA	
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓			
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓			
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓			
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓			
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓			

NOTES:

Section 5 - Lamps								
Component	P	F	NA	Component	P	F	NA	
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓			
5.2. Daytime Running Lamps	✓			5.8. Rear Side Marker Lamps	✓			
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓			
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓			
5.5. Auxiliary Lamps	✓			5.11. Emergency Lighting	✓			
5.6. Front Side Marker Lamps	✓							

NOTES:

Section 6 - Exterior, General								
Component	P	F	NA	Component	P	F	NA	
6.1. Fuel Cap	✓			6.3. Bumpers	✓			
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation				✓

NOTES:

Section 7 - Under Hood								
Component	P	F	NA	Component	P	F	NA	
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder				✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓			
7.3. Remote Starter Operation	✓			7.9. Exhaust Manifold(s)	✓			
7.4. Battery	✓			7.10. Oil Leaks	✓			
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓			
7.6. Brake Master Cylinder	✓							

NOTES:

Section 8 - Steering and Suspension								
Component	P	F	NA	Component	P	F	NA	
8.1. Wheel Bearings	✓			8.8. Steering Gear				✓
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion	✓			
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓			
8.4. Pitman Arm			✓	8.11. Control Arms	✓			
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓			
8.6. Steering Stabilizer / Damper			✓	8.13. Springs	✓			
8.7. Steering Shaft Assembly	✓							

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels						
Component	P	F	NA	Component	P	F NA
9.1. Tread Depth- LF:4 mm,RF:4 mm,LR:6 mm,RR:6 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓	
9.2. Tire Condition (general)	✓			9.5. Wheels	✓	
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓	

NOTES:

Section 10 - Brakes						
Component	P	F	NA	Component	P	F NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:190.06 mm,RR:190.00 mm	✓	
10.2. Park Brake Lining- LR:4 mm,RR:4 mm	✓			10.6. Brake Rotor Thickness- LF:30.04 mm,RF:30.00 mm	✓	
10.2. Brake Lining- LF:6 mm,RF:6 mm,LR:5 mm,RR:5 mm	✓			10.7. Brake Drum Condition (general)	✓	
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR:20.00 mm,RR:20.03 mm	✓	
10.4. Brake System Wiring	✓			10.9. Park Brake	✓	
10.5. Brake Rotor Condition (general)	✓					

NOTES:

Section 11 - Under Vehicle						
Component	P	F	NA	Component	P	F NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓	
11.2. Engine	✓			11.6. Floor Pan	✓	
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓	
11.4. Differential(s)	✓			11.8. Exhaust System	✓	

NOTES:



Section 12 - Structural Integrity						
Component	P	F	NA	Component	P	F NA
12.1. Documentation	✓			12.5. Frame	✓	
12.2. Vehicle Identification Number	✓			12.6. Roof	✓	
12.3. Body - General	✓			12.7. Pillars	✓	
12.4. Structural Dimensions - ***Must be attached***	✓			12.8. Floor	✓	

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #5143046) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection(Mechanical) 2024/12/24	Technician Number (Mechanical) C9760	Facility Number (Mechanical) 20294	Signature 
Date of Inspection(Structural) 2024/12/24	Technician Number (Structural) D1320	Facility Number (Structural) 20294	Signature 

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2024/12/24

Customer Signature

