

Vehicle History Report (BC) #: 54785263 Report Date: July 12, 2024 | 4:42 PM EDT Report Status: Complete

2014 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas 5N1AR2MM7EC602382 Country of Assembly: United States

Last Reported Odometer: 169,575 KM



Accident/Damage Records Found



Last Registered In: British Columbia (Normal)



28 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 12, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
① 2015 Feb 21	British Columbia, Canada	
	Estimate: REAR CENTER Estimate Date: n/a	\$563.98
	Claim: COLLISION REAR CENTER	\$523.16

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
1 2022 Oct 15	British Columbia, Canada	
	Glass Record	\$812.74



Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Jul 29		Campus Acura	Vehicle serviced
		Victoria, British Columbia, Canada	Vehicle washed/detailed
2013 Jul 31		Service Facility	Vehicle serviced
		Victoria, British Columbia, Canada	Wheel locks installed
		,	Oil and filter changed
			Engine block heater installed
2014 Mar 28		Campus Acura	Vehicle serviced
		Victoria, British Columbia, Canada	Fabric protection applied
		,	Leather/vinyl treatment performed
			Undercoating/rustproofing applied
			Vehicle serviced
			Fabric protection applied
2014 Apr 3	6,070 KM	Campus Nissan	Vehicle serviced
		Victoria, British Columbia, Canada	Battery/charging system checked
		,	Oil and filter changed
2014 Sep 21	16,396 KM	Campus Nissan	Vehicle serviced
		Victoria, British Columbia, Canada	Maintenance inspection completed
		,	Oil and filter changed
			Tire condition and pressure checked
			Brakes checked
			Fluids checked
			Battery/charging system checked
			Computer reprogrammed
			Tires rotated

		SOURCE	DETAILS
2015 Jan 20	23,714 KM	Kal Tire - Victoria - Langford Victoria, British Columbia, Canada	Vehicle serviced
2015 Mar 20	26,598 KM	Campus Nissan	Vehicle serviced
		Victoria, British Columbia, Canada	Maintenance inspection completed
		victoria, British Colambia, Canada	Tire condition and pressure checked
			Fluids checked
			Ignition system checked
			Battery/charging system checked
			Exhaust system checked
			Air filter replaced
			 Transmission computer/module reprogrammed
			Engine/powertrain computer/module reprogrammed
			PCM reprogrammed
			Brake light switch replaced
			Mass air flow sensor replaced
			Cabin air filter replaced/cleaned
20451.140	24.544.1/24	6 Ni	
2015 Jul 18	34,541 KM	Campus Nissan Victoria, British Columbia, Canada	Vehicle serviced • Maintenance inspection completed
		victoria, britisti Columbia, Callada	
			on and meet enanged
			Brake fluid flushed/changed
			Tire condition and pressure checked
			Tires rotated
			Maintenance reminder reset
			Brakes checked
			Battery/charging system checked
			Fluids checked
			Vehicle washed/detailed
2015 1 20	20.765.1/14	- All	W
2015 Aug 20	39,765 KM	Campus Nissan	Vehicle serviced • Trim repaired
		Victoria, British Columbia, Canada	- ПППТерапец
2015 Oct 7	42,632 KM	Campus Nissan	Vehicle serviced
	•	Victoria, British Columbia, Canada	Tires rotated
		victoria, British Columbia, Canada	Maintenance reminder reset
			Oil and filter changed
			Tire condition and pressure checked
			Fluids checked
			Battery/charging system checked
2016 Feb 12	51,343 KM	Campus Nissan	Vehicle serviced
		Victoria, British Columbia, Canada	Maintenance inspection completed
			Air filter replaced
			Brakes checked
			Oil and filter changed
			Brake fluid flushed/changed
			Brake fluid flushed/changed Tire condition and pressure checked
			Brake fluid flushed/changed
			 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated
			 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked
			 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated
			 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned
2016 Jul 14	60,186 KM	Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced
2016 Jul 14	60,186 KM	Campus Nissan Victoria, British Columbia, Canada	Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed
2016 Jul 14	60,186 KM	'	Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked
2016 Jul 14	60,186 KM	'	Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed
2016 Jul 14	60,186 KM	'	Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked
2016 Jul 14	60,186 KM	'	Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed
2016 Jul 14	60,186 KM	'	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked
·		Victoria, British Columbia, Canada	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed
2016 Jul 14 2016 Nov 16	60,186 KM 71,419 KM	Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced
·		Victoria, British Columbia, Canada	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced
·		Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced
·		Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake possure checked Battery/charging system checked
·		Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake possure checked Battery/charging system checked Oil and filter changed
·		Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Tire condition and pressure checked Tire replaced Rear brake pads replaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked
·		Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Tire condition and pressure checked Fluids checked
·		Victoria, British Columbia, Canada Campus Nissan	Brake fluid flushed/changed Tire condition and pressure checked Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Fluids checked
·		Victoria, British Columbia, Canada Campus Nissan Victoria, British Columbia, Canada Campus Nissan	 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Fluids checked Vehicle washed/detailed Vehicle washed/detailed Vehicle washed/detailed Vehicle serviced
2016 Nov 16	71,419 KM	Victoria, British Columbia, Canada Campus Nissan Victoria, British Columbia, Canada	 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Fluids checked Vehicle washed/detailed Vehicle serviced Battery/charging system checked Wehicle serviced Battery/charging system checked Vehicle serviced Battery/charging system checked Vehicle serviced Battery/charging system checked
2016 Nov 16	71,419 KM	Victoria, British Columbia, Canada Campus Nissan Victoria, British Columbia, Canada Campus Nissan	 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Fluids checked Vehicle washed/detailed Vehicle washed/detailed Vehicle washed/detailed Vehicle serviced
2016 Nov 16	71,419 KM	Victoria, British Columbia, Canada Campus Nissan Victoria, British Columbia, Canada Campus Nissan	 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Fluids checked Vehicle washed/detailed Vehicle serviced Battery/charging system checked Wehicle serviced Battery/charging system checked Vehicle serviced Battery/charging system checked Vehicle serviced Battery/charging system checked
2016 Nov 16	71,419 KM	Victoria, British Columbia, Canada Campus Nissan Victoria, British Columbia, Canada Campus Nissan	 Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Battery/charging system checked Fluids checked Cabin air filter replaced/cleaned Vehicle serviced Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Rear brake pads replaced Rear brake rotor(s) resurfaced Battery/charging system checked Oil and filter changed Tire condition and pressure checked Fluids checked Vehicle washed/detailed Vehicle serviced Battery/charging system checked Fluids checked Vehicle washed/detailed Vehicle serviced Battery/charging system checked Oil and filter changed Vehicle serviced Battery/charging system checked Oil and filter changed

		SOURCE	DETAILS Pattern conjuged
			 Battery serviced Fluids checked Brake fluid flushed/changed
2017 Apr 20	84,186 KM	Service Facility Victoria, British Columbia, Canada	Vehicle serviced Vehicle serviced
2017 Oct 5	94,327 KM	Campus Nissan Victoria, British Columbia, Canada	Vehicle serviced Maintenance inspection completed Maintenance reminder reset Front brake rotor(s) resurfaced Front brake pads replaced Brakes checked Oil and filter changed Tire condition and pressure checked Fluids checked Battery/charging system checked Tire pressure monitoring system reset Cabin air filter replaced/cleaned
2018 Mar 7	103,956 KM	Kal Tire - Victoria - Langford Victoria, British Columbia, Canada	Vehicle serviced Tire condition and pressure checked Four wheel alignment performed One tire mounted One tire balanced
2018 Apr 2	106,119 KM	Campus Nissan Victoria, British Columbia, Canada	Vehicle serviced Oil and filter changed
2018 Aug 14	114,299 KM	Campus Nissan Victoria, British Columbia, Canada	Vehicle serviced • Vehicle washed/detailed
2019 Jan 10	124,008 KM	Campus Nissan Victoria, British Columbia, Canada	Vehicle serviced • Air filter replaced • Rear brake pads replaced • Rear brake rotor(s) resurfaced • Brake fluid flushed/changed
2019 Apr 8	128,625 KM	Campus Acura Victoria, British Columbia, Canada	Vehicle serviced
2019 Jun 17	132,958 KM	Campus Infiniti Victoria, British Columbia, Canada	Vehicle serviced • Front wheel bearing(s)/hub(s) replaced • Wiper(s) replaced • Maintenance reminder reset • Vehicle washed/detailed
2019 Oct 26	142,197 KM	Campus Nissan Victoria, British Columbia, Canada	Vehicle serviced • Vehicle washed/detailed
2020 Feb 5	151,185 KM	Kal Tire - Victoria - Langford Victoria, British Columbia, Canada	Vehicle serviced • Maintenance inspection completed • Power steering fluid flushed/changed • Four wheel alignment performed • Shock absorber(s) replaced • Steering/suspension checked • Battery replaced
2020 Feb 28	152,612 KM	Nissan Of Duncan Duncan, British Columbia, Canada	Vehicle serviced Oil and filter changed Tires rotated
2020 Dec 3	156,312 KM	Nissan Of Duncan Duncan, British Columbia, Canada	Vehicle serviced Maintenance inspection completed Brake fluid flushed/changed Oil and filter changed Wiper(s) replaced Antifreeze/coolant flushed/changed
2021 Nov 4	165,415 KM	Kal Tire - Victoria - Langford Victoria, British Columbia, Canada	Vehicle serviced • Maintenance inspection completed • Four wheel alignment performed • One tire mounted

	ODOMETER	SOURCE	DETAILS
			One tire balanced
			Front brakes replaced
			Rear brakes replaced
			Maintenance reminder reset
			Oil and filter changed
			Steering/suspension checked
2022 Mar 7 169.575	169,575 KM	Nissan Of Duncan	Vehicle serviced
		Duncan, British Columbia, Canada	Maintenance inspection completed
		Danieun, British Columbia, Canada	Alignment checked
			Oil and filter changed
			Air filter replaced

()

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Jul 29		Campus Acura Victoria, British Columbia, Canada	Service Record	Vehicle serviced
2013 Jul 31		Service Facility Victoria, British Columbia, Canada	Service Record	Vehicle serviced
2013 Aug 1		Motor Vehicle Dept. Victoria, British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2014 Mar 28		Campus Acura Victoria, British Columbia, Canada	Service Record	Vehicle serviced
2014 Apr 3	6,070 KM	Campus Nissan Victoria, British Columbia, Canada	Service Record	Vehicle serviced
2014 Apr 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Lease
2014 Sep 21	16,396 KM	Campus Nissan Victoria, British Columbia, Canada	Service Record	Vehicle serviced
2014 Nov 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2015 Jan 20	23,714 KM	Kal Tire - Victoria - Langford Victoria, British Columbia, Canada	Service Record	Vehicle serviced



ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.id

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada UI C. All rights reserved.

