



Vehicle History Report #: 52627820  
Report Date: April 13, 2024 | 12:30 PM EDT  
Report Status: Complete

## 2013 VOLKSWAGEN PASSAT S

Sedan | 5 Cylinders | Gas  
1VWAH7A35DC102488  
Country of Assembly: United States  
Last Reported Odometer: 114,819 KM



No Accident/Damage Records Found



Last Registered In:  
**Ontario (Normal)**



9 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 13, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

## Vehicle History Report



### Accident/Damage

✓ There are no accidents/damage reported on this vehicle.

1VWAH7A35DC102488



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Mar 8		Volkswagen Villa Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li></ul>
2013 Jun 6	8,851 KM	Volkswagen Villa Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2015 Feb 3	55,130 KM	Midas Auto Service Experts Whitby, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li></ul>
2015 Mar 7	58,641 KM	Midas Auto Service Experts Whitby, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li></ul>
2015 Apr 30	59,077 KM	Maple Volkswagen Maple, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Safety inspection performed</li><li>Tire condition and pressure checked</li><li>Four tires mounted</li><li>Four tires replaced</li><li>Wheel bearing(s)/hub(s) replaced</li><li>Front brake pads replaced</li><li>Brake calipers cleaned/serviced</li><li>Rear brake pads replaced</li><li>Tire(s) replaced</li><li>Wiper(s) replaced</li><li>Battery/charging system checked</li><li>Air filter replaced</li><li>Oil and filter changed</li><li>Tires rotated</li><li>Drivability/performance checked</li><li>Cabin air filter replaced/cleaned</li></ul>
2015 Jul 13	62,494 KM	Maple Volkswagen Maple, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Front door trim panel replaced/repared</li><li>Radio speaker(s) replaced</li></ul>
2016 Jan 4	72,295 KM	Maple Volkswagen Maple, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Air filter replaced</li><li>Stabilizer bar links replaced</li><li>Knock sensor(s) replaced</li><li>Fluids checked</li><li>Oil and filter changed</li><li>Tire condition and pressure checked</li><li>Drivability/performance checked</li></ul>
2017 Nov 23	103,196 KM	Cella General Repairs Bolton, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Undercoating/rustproofing applied</li></ul>
2019 Feb 22	114,819 KM	Humberview Volkswagen Toronto, Ontario, Canada	<b>Vehicle serviced</b>



## Open Recalls

Recall #: 94L9 | HEADLAMP CAPS   Recall Date: 2019 Jun 11

### Recall Description

The headlights are not permitted to have a horizontal adjustment for vehicles certified according to regulatory requirements. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not have the required cap installed. Incorrectly adjusted headlights may result in reduced visibility (for the driver and other motorists) which could increase the risk of a crash.

### Remedy

Inspect and, if necessary install missing headlight adjusting screw caps.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).



## Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Mar 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Fleet Vehicle colour noted as gray
2013 Mar 8		Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2013 Jun 6	8,851 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2015 Feb 3	55,130 KM	Midas Auto Service Experts Whitby, Ontario, Canada	Service Record	Vehicle serviced
2015 Mar 7	58,641 KM	Midas Auto Service Experts Whitby, Ontario, Canada	Service Record	Vehicle serviced
2015 Apr 30	59,077 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 May 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2015 Jul 13	62,494 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 4	72,295 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Nov 23	103,196 KM	Cella General Repairs Bolton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jun 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Feb 22	114,819 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 11		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 94L9
2020 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2022 Jul 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2023 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>