


Vehicle History Report #: 59018724 Report Date: January 30, 2025 | 5:28 p.m. EST Report Status: Complete

## 2016 NISSAN PATHFINDER S


Sport utility vehicle | 6 Cylinders | Gas 5N1AR2MM9GC627531 Country of Assembly: United States Last Reported Odometer: 69,971 KM



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of January 30, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

(i)

# **Vehicle History Report**



| INCIDENT DATE | DETAILS  | AMOUNT     |
|---------------|--|------------|
| 2019 Apr 2    | Brampton, Ontario, Canada                              |            |
|               | Estimate: Left Rear Corner   Estimate Date: 2019 Apr 5 | \$4,181.71 |
|               | Claim: Unknown   | \$4,182.00 |

### **Other Damage Records**

| RECORD DATE          | DETAILS         | AMOUNT   |
|----------------------|-----------------|----------|
| <b>()</b> 2020 Jul 2 | Ontario, Canada |          |
|                      | Glass Record    | \$570.00 |

### Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

### Open Recalls

Recall #: R24B7 | PATH HOOD LATCH NTB22-053 Recall Date: 2024 Dec 06

#### **Recall Description**

On certain 2013-2016 Pathfinder vehicles, dust or dirt contamination may accumulate on and around the secondary latch lever pivot joint. Over time, the build-up of contamination, combined with a lack of proper inspection and maintenance of the secondary latch (as described in the Owner s Manual), can create mechanical binding that could cause the lever to remain in the open position after it has been disengaged. In addition, this contamination can scratch the secondary latch s protective anti-corrosion coating, allowing corrosion of the bare metal in the pivot joint.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)



This vehicle is not actively declared stolen.

### Detailed History

| DATE        | ODOMETER  | SOURCE   | RECORD TYPE      | DETAILS   |
|-------------|-----------|--|------------------|---|
| 2016 Mar 28 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>First Owner Reported<br>Vehicle colour noted as white   |
| 2016 Sep 29 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal                                  |
| 2017 Oct 9  |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal                                  |
| 2018 Oct 2  |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal                                  |
| 2019 Apr 2  |           | Ontario, Canada                                | Unknown          |   |
| 2019 Apr 5  | 69,971 KM | Insurance Records<br>Brampton, Ontario, Canada | Estimate Repair  | Incident Date: 2019-04-02<br>Left Rear Corner   |
| 2019 Oct 18 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal                                  |
| 2020 Jul 2  |           | Insurance Records<br>Ontario, Canada           | Glass Record     | \$570.00  |
| 2021 Jan 28 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal                                  |
| 2022 Aug 18 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal<br>Vehicle colour noted as white |
| 2024 Sep 23 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | Registration Issued or Renewed<br>Previous Use: Personal                                  |
| 2024 Nov 14 |           | Motor Vehicle Dept.<br>Ontario, Canada         | Canadian Renewal | New Owner reported<br>Vehicle colour noted as white                                       |
| 2024 Dec 6  |           | NISSAN   | Recall           | Manufacturer Recall Issued<br>Recall # R24B7  |



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information of mexternal sources believed to be reliable, but no responsibility is assumed by CARFAX Canada providers or the information or any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers for there expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada and use the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about two vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada and User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2025 CARFAX Canada ULC. All rights reserved.

