



Vehicle History Report # 71264722
Report Date: July 15, 2026 | 12:06 p.m. EDT
Report Status: Complete

2019 VOLKSWAGEN ATLAS SE

Sport utility vehicle | 6 Cylinders | Gas
1V2LR2CA5KC556341
Country of Assembly: United States
Last Reported Odometer: 214,320 KM

No Reported
Accidents™ >



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



20 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 15, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Jul 2		Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Cargo tray/mat installed - Floor mats installed - Vehicle washed/detailed
2019 Oct 15	7,697 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Airbag clockspring/reel replaced - Cabin air filter replaced/cleaned - Fluids checked - Oil and filter changed
2019 Nov 11		Krown Palmerston Palmerston, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2019 Dec 16	7,699 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Four tires balanced - Four tires mounted - Four tires replaced - Tire(s) balanced - Tire(s) mounted
2020 Jan 31	18,540 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed
2020 Jun 4	25,210 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Tire(s) changed - Tire(s) mounted
2020 Sep 1	31,833 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Cabin air filter replaced/cleaned - Fluids checked

ODOMETER		SOURCE	DETAILS
			- Fuel system cleaned/serviced - Oil and filter changed
2020 Nov 18	38,280 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced Tire(s) mounted
2020 Nov 19		Krown Palmerston Palmerston, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2021 Apr 7	46,130 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire(s) mounted
2021 Sep 24	60,188 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced
2021 Oct 21	62,248 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Fluids checked - Oil and filter changed
2021 Nov 3		Krown Palmerston Palmerston, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2021 Dec 13	66,590 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Door lock cylinder(s) replaced - Door lock(s) replaced/repared - Front door trim panel replaced/repared
2022 Apr 14	76,172 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Brakes checked - Fluids checked - Oil and filter changed - Rear brake rotor(s) replaced - Tire(s) mounted
2022 Oct 24	96,248 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Antifreeze/coolant flushed/changed - Fluids checked - Oil and filter changed
2022 Nov 1		Krown Palmerston Palmerston, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2022 Nov 15	98,279 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Vehicle serviced - Air filter replaced - Front brake pads replaced - Front brake rotor(s) replaced - Water pump gasket replaced - Water pump replaced
2023 Nov 1		Krown Palmerston Palmerston, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2025 Oct 21		Krown Palmerston Palmerston, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied

Recall #: 69FB | PASSENGER OCCUPANT DETECTION SYSTEM (PODS) Recall Date: 2023 Apr 05

Recall Description

A wire with a contact fault may cause the Passenger Occupant Detection System (PODS) to detect a malfunction and switch off the passenger airbag, even though the seat may be occupied. In a crash, there would be an increased risk of injury to the occupant seated in the front passenger seat if the passenger frontal airbag is switched off or not working..Should a malfunction occur, vehicle occupants will be alerted by illumination of the airbag warning light, an acoustic warning sound, an error message displayed in the instrument cluster and by the status of the Passenger Airbag OFF indicator light. If this happens, owners are advised to make an appointment with an authorized Volkswagen dealer to have the vehicle inspected without delay and discontinue use of the front passenger seat.

Remedy

Replace the PODS sensor mat and seat harness.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jul 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white
2019 Jul 2		Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 15	7,697 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 11		Krown Palmerston Palmerston, Ontario, Canada	Service Record	Vehicle serviced
2019 Dec 16	7,699 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 31	18,540 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Jun 4	25,210 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 1	31,833 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 18	38,280 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 19		Krown Palmerston Palmerston, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Apr 7	46,130 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 24	60,188 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 21	62,248 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 3		Krown Palmerston Palmerston, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 13	66,590 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 14	76,172 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 24	96,248 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 1		Krown Palmerston Palmerston, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 15	98,279 KM	Easthill Volkswagen Walkerton, Ontario, Canada	Service Record	Vehicle serviced
2023 Apr 5		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 69FB
2023 Nov 1		Krown Palmerston Palmerston, Ontario, Canada	Service Record	Vehicle serviced
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Jan 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Oct 21		Krown Palmerston Palmerston, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2025 Nov 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2026 Jan 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2026 Feb 14	214,320 KM	Independent Source North York, Ontario, Canada	Odometer reading	
2026 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

