



Vehicle History Report #: 64859352
Report Date: October 6, 2025 | 3:42 p.m. EDT
Report Status: Complete

2015 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas

3VW2K7AJ3FM203342

Country of Assembly: Mexico

Last Reported Odometer: 141,815 KM



No Accident/Damage Records
Found



Last Registered In:
Ontario (Normal)



10 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of October 06, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Alberta** with **Normal** branding.
- In the province of **Ontario** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2021 Jun 14	108,825 KM	MIDAS AUTO SERVICE EXPERTS Calgary, Alberta, Canada	Vehicle serviced - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed - Two wheel alignment performed
2022 May 9	121,451 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Oil and filter changed - Oil pan replaced/repaired - Tire(s) balanced - Tire(s) replaced
2022 Dec 7	125,407 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Tire(s) balanced - Tire(s) replaced
2023 Feb 24	126,733 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Ignition coil(s) replaced - Spark plug wires replaced - Spark plug(s) replaced
2023 Apr 27	128,231 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Four tires replaced - Oil and filter changed - Tire(s) balanced - Tire(s) replaced
2023 Jun 16		True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Alignment performed - Lower ball joint(s) replaced

	ODOMETER	SOURCE	DETAILS
2023 Dec 1	132,510 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Four tires balanced - Four tires mounted - Four tires replaced - Front axle(s) replaced/repared - Front strut(s) replaced - Stabilizer bar links replaced
2024 Apr 24	135,164 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Four tires balanced - Four tires mounted - Four tires replaced - Oil and filter changed
2024 Dec 12	139,583 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Four tires balanced - Four tires mounted - Oil and filter changed - Tire(s) mounted
2025 Mar 27	141,815 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Blower motor replaced/repared - Blower motor resistor replaced - Four tires balanced - Four tires mounted - Four tires replaced - Tire(s) mounted - Vehicle washed/detailed



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website. (<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)



Stolen Vehicle Check

☒ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Dec 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2015 May 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 May 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 May 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 May 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Jan 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as gray
2019 Feb 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Mar 19		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium gray
2020 Nov 21		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium gray
2021 Jun 14	108,825 KM	MIDAS AUTO SERVICE EXPERTS Calgary, Alberta, Canada	Service Record	Vehicle serviced
2021 Nov 4		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium gray
2021 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 May 9	121,451 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2022 Dec 7	125,407 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2023 Feb 24	126,733 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced

CARFAX Canada Vehicle History Report

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Apr 27	128,231 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 16		True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 1	132,510 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 24	135,164 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2024 May 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2024 Dec 12	139,583 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced
2025 Mar 27	141,815 KM	True-Centre Auto Service Pembroke, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

