Vehicle History Report #: 51978290 Report Date: March 14, 2024 | 2:42 PM EDT

Report Status: Complete

2021 NISSAN SENTRA SR

Sedan | 4 Cylinders | Gas 3N1AB8DV8MY223730 Country of Assembly: Mexico Last Reported Odometer: 151,673 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



22 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca




This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 14, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage





This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.




Service Records

DATE	ODOMETER	SOURCE	DETAILS
2021 Sep 15	15,606 KM	Derbyshire's Auto Repair and Sales,	Vehicle serviced
		Inc.	Oil and filter changed
		Smiths Falls, Ontario, Canada	
2021 Oct 22	22,355 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	 Tire(s) replaced
			Tire(s) mounted
			Nitrogen fill tires
			Four tires balancedFour tires mounted
			Oil and filter changed
			On and inter-changed
2022 Mar 1	42,448 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	Oil and filter changed
2022 Apr 22	50,595 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	Oil and filter changed
			 Tire(s) mounted
			Nitrogen fill tires Tim(s) shows a discount.
			Tire(s) changed
2022 Jun 16	59,955 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	Oil and filter changedTires rotated
2022 Sep 14	74,086 KM	Precision Automotive	Vehicle serviced
•		Orleans, Ontario, Canada	Oil and filter changed
		, ,	Brakes checked
2022 Oct 14	79,215 KM	Speedy Auto Service	Vehicle serviced
		Ottawa, Ontario, Canada	Tire repaired
2022 Oct 19	79,384 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	Wiper(s) replaced
		,	Tire(s) mounted
			Nitrogen fill tires
			Tire(s) changed
2022 Nov 2	81,307 KM	Trans Canada Nissan	Vehicle serviced
		Peterborough, Ontario, Canada	Brakes checked
2022 Nov 28	85,203 KM	Great Canadian Oil Change	Vehicle serviced
		Orleans, Ontario, Canada	Maintenance inspection completed
			Oil and filter changed
			Air filter checked
			Fluids checked
2023 Feb 23	97,158 KM	Great Canadian Oil Change	Vehicle serviced
		Orleans, Ontario, Canada	 Maintenance inspection completed
			Oil and filter changed
3 Feb 23	97,158 KM	_	Maintenance inspection completed

Fluids checked

	ODOMETER	SOURCE	• Splash shield replaced/repaired
			Splash shield replaced/repaired
2023 Mar 31	102,773 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	 Tire(s) replaced
			 Tire(s) mounted
			Nitrogen fill tires
			Four tires replaced
			Four tires balanced
.023 May 12	108,919 KM	Great Canadian Oil Change	Vehicle serviced
	,		Maintenance inspection completed
		Orleans, Ontario, Canada	·
			on and meet changed
			Fluids checked
			Air filter checked
023 Jun 17	114,944 KM	Great Canadian Oil Change	Vehicle serviced
		Orleans, Ontario, Canada	Maintenance inspection completed
		oricaris, oritario, cariada	Oil and filter changed
			Air filter checked
			Fluids checked
			Fiulds Criecked
023 Aug 11	123,340 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	Oil and filter changed
.023 Sep 15	128,978 KM	Precision Automotive	Vehicle serviced
.025 SCP 15	120,570 KW		
		Orleans, Ontario, Canada	Wiper(s) replaced
			 Oil and filter changed
			Tires rotated
			Brakes checked
023 Oct 19	134,527 KM	Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	Tire(s) mounted
		Oricans, Oricano, Canada	Nitrogen fill tires
			Exterior lights checked
			5
			Tire(s) changed
023 Oct 27		Gibsons Garage Corporation Ltd	Vehicle serviced
		Cobden, Ontario, Canada	Battery replaced
			Battery/charging system checked
023 Nov 23	140,184 KM	Great Canadian Oil Change	Vehicle serviced
	•	Orleans, Ontario, Canada	Maintenance inspection completed
		Offearis, Officario, Carrada	Oil and filter changed
			-
			Fluids checked
024 Jan 12		Precision Automotive	Vehicle serviced
		Orleans, Ontario, Canada	
024 Feb 15	151,673 KM	Great Canadian Oil Change	Vehicle serviced
	•	Orleans, Ontario, Canada	Maintenance inspection completed
		Officario, Officario, Carlada	Oil and filter changed
			Fluids checked
		Consider Time	Vahiala samiaad
024 Eab 22			
.024 Feb 23		Canadian Tire Kanata, Ontario, Canada	Vehicle serviced • Inspection performed



Recall Description

THE TIE ROD STRENGTH MAY BE INSUFFICIENT UNDER CERTAIN REAL WORLD CONDITIONS WITH HIGH INPUT FORCE.

Remedy

ONCE THE REMEDY AND PARTS ARE AVAILABLE, DEALERS WILL REPLACE BOTH THE LEFT-HAND AND RIGHT-HAND TIE RODS. ONCE THE REMEDY AND PARTS ARE AVAILABLE, THIS SERVICE, WHICH IS CONDUCTED AT NO CHARGE TO YOU FOR PARTS AND LABOR, COULD TAKE UP TO TWO AND ONE HALF (2.5) HOURS TO COMPLETE. HOWEVER, YOUR NISSAN DEALER MAY REQUIRE YOUR VEHICLE FOR A LONGER PERIOD OF TIME BASED UPON THEIR WORK SCHEDULE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website.

Recall #: R23C3 | ALT STRA REAR CAM NTB23-070 Recall Date: 2023 Sep 12

Recall Description

Over time, the rear view camera harness connector in the affected vehicles could become damaged from harness movement and vibration during vehicle operation.

Remedy

The dealer will inspect the function of the rear view camera. If the rear view camera harness is damaged, the dealer will replace the rear view camera and harness assembly. If not damaged, the dealer will apply protective tape and reroute the rearview camera harness to prevent the harness from being damaged.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Jun 24		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		First Owner Reported
				Previous Use: Commercial
				Vehicle colour noted as black
2021 Sep 15	15,606 KM	Derbyshire's Auto Repair and	Service Record	Vehicle serviced
		Sales, Inc.		
		Smiths Falls, Ontario, Canada		
2021 Oct 22	22,355 KM	Precision Automotive	Service Record	Vehicle serviced
		Orleans, Ontario, Canada		
2021 Dec 1		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Commercial

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
				Vehicle colour noted as black
2022 Mar 1	42,448 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 22	50,595 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 16	59,955 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 14	74,086 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 14	79,215 KM	Speedy Auto Service Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 19	79,384 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 2	81,307 KM	Trans Canada Nissan Peterborough, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 28	85,203 KM	Great Canadian Oil Change Orleans, Ontario, Canada	Service Record	Vehicle serviced
2022 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2023 Feb 23	97,158 KM	Great Canadian Oil Change Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 31	102,773 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 May 12	108,919 KM	Great Canadian Oil Change Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 17	114,944 KM	Great Canadian Oil Change Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 Aug 11	123,340 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 Aug 18		NISSAN	Recall	Manufacturer Recall Issued Recall # R23B3
2023 Sep 12		NISSAN	Recall	Manufacturer Recall Issued Recall # R23C3
2023 Sep 15	128,978 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 19	134,527 KM	Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Oct 27		Gibsons Garage Corporation Ltd Cobden, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 23	140,184 KM	Great Canadian Oil Change Orleans, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Jan 12		Precision Automotive Orleans, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 15	151,673 KM	Great Canadian Oil Change Orleans, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 23		Canadian Tire Kanata, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracion or missions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use

© 2024 CARFAX Canada ULC. All rights reserved.

