

2011 HONDA ODYSSEY LX

Van passenger | 6 Cylinders | Gas
 5FNRL5H20BB503100
 Country of Assembly: United States
 Last Reported Odometer: 198,422 KM

No Reported
 Accidents™ >



No Accident/Damage Records Found



Last Registered In:
 Ontario (Normal)



54 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 15, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Jan 3	21,000 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tire repaired
2013 Jun 27	26,406 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2013 Jun 27	26,407 KM	Mufflerman Ontario, Canada	Vehicle serviced
2014 Mar 19	36,769 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2014 Mar 19	36,770 KM	Mufflerman Ontario, Canada	Vehicle serviced
2014 May 14	37,499 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Tire condition and pressure checked
2014 May 14	37,500 KM	Mufflerman Ontario, Canada	Vehicle serviced
2014 Sep 17		Krown Rust Control Burlington, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2014 Nov 12		Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tire condition and pressure checked - Tire repaired

	ODOMETER	SOURCE	DETAILS
2014 Dec 15	44,716 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2014 Dec 15	44,717 KM	Mufflerman Ontario, Canada	Vehicle serviced
2015 May 6		Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2015 Aug 25	58,084 KM	Image Honda Hamilton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Rear leaf spring(s) replaced
2015 Sep 25	59,749 KM	Image Honda Hamilton, Ontario, Canada	Vehicle serviced
2015 Dec 8	62,956 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced Tires rotated
2016 May 2	66,854 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2016 May 16	67,248 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2016 Dec 16	75,621 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Battery replaced - Tires rotated
2017 Jan 13	76,489 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced - Brakes checked - Oil and filter changed
2017 Mar 23	78,908 KM	Image Honda Hamilton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Drive belts checked - Tire condition and pressure checked
2017 May 5	80,202 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2017 Aug 22	86,158 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2017 Dec 21	91,971 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2018 Jan 31	93,035 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced - Front brake pads replaced - Front brake rotor(s) replaced - Oil and filter changed
2018 Feb 22	93,677 KM	Halton Autolease Burlington, Ontario, Canada	Vehicle serviced

	ODOMETER	SOURCE	DETAILS
2018 May 10	96,332 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Alignment checked - Four tires balanced - Four tires mounted - Four wheel alignment performed - Tire condition and pressure checked - Tire repaired
2018 Jun 26	97,735 KM	Image Honda Hamilton, Ontario, Canada	Vehicle serviced Maintenance inspection completed
2018 Oct 26	102,563 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2018 Dec 11	103,930 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2019 Jan 17	105,274 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Front brake rotor(s) replaced
2019 Apr 25	110,694 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2019 Jun 25	113,489 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Oil and filter changed
2019 Jul 11	114,669 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Vehicle serviced Front brake pads replaced
2019 Dec 13	127,536 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
2019 Dec 23	127,829 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Brakes checked - Rear brake pads replaced - Rear brake rotor(s) replaced
2020 Mar 14	133,609 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tire repaired
2020 Apr 2		Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2020 Aug 20	138,824 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Brakes checked - Four wheel alignment performed - Front brake pads replaced - Front brake rotor(s) replaced - Lower ball joint(s) replaced - Tire condition and pressure checked
2020 Sep 21	140,111 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed

	ODOMETER	SOURCE	DETAILS
2020 Dec 4	143,478 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2021 May 11	149,048 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2021 Jul 30	151,591 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Air filter replaced - Alignment performed - Antifreeze/coolant flushed/changed - Brake fluid checked - Brake fluid flushed/changed - Brakes serviced - Cabin air filter replaced/cleaned - Cooling system serviced - Engine serviced - Front brakes serviced - Fuel system cleaned/serviced - Lights checked - Oil and filter changed - Power steering fluid flushed/changed - Power steering system serviced - Rear brakes serviced/adjusted - Rear shock absorber(s) replaced - Rear wiper blade replaced - Serpentine belt replaced - Spark plug(s) replaced - Steering shaft replaced/repared - Timing belt tensioner/idler checked - Timing belt replaced - Timing belt tensioner/idler replaced - Tire repaired - Tire(s) balanced - Transmission fluid flushed - Transmission serviced - Water pump gasket replaced - Water pump replaced - Wheel bearing(s) serviced
2021 Sep 17	153,815 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - One tire mounted - Tire condition and pressure checked - Tire(s) replaced
2021 Dec 6	156,885 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2022 Jan 26	158,334 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Engine mount(s) replaced - Oil and filter changed - Power steering cooler replaced - Power steering fluid flushed/changed - Power steering hose(s)/line(s) replaced - Washer hose/line replaced/repared
2022 Apr 14	161,322 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tire(s) balanced - Tire(s) mounted

ODOMETER		SOURCE	DETAILS
2022 Nov 14	168,584 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
2023 May 4	171,762 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2023 Jun 8	172,298 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Brakes checked - Brake pads replaced - Lights checked - Oil and filter changed - Rear brake pads replaced - Rear brake rotor(s) replaced
2023 Nov 20	177,440 KM	Active Green & Ross Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2023 Nov 27		Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Air intake hose replaced - Cabin air filter replaced/cleaned - Induction system checked - Stabilizer bar links replaced - Sway bar link(s) replaced - Wiper(s) replaced
2024 Apr 30	181,317 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire(s) changed
2025 Mar 28	191,678 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Brakes checked - Brake caliper(s) replaced - Brake fluid checked - Brake fluid flushed/changed - Brake pads replaced - Brake rotor(s) replaced - Drain plug gasket replaced - Drive belt(s) replaced - Engine cleaned - Fluids checked - Oil and filter changed - Power steering fluid flushed/changed - Power steering pump replaced - Power steering system bled - Power steering system serviced - Rear brake caliper(s) replaced - Rear brake pads replaced - Rear brake rotor(s) replaced - Rear wiper blade replaced - Serpentine belt replaced - Tire(s) changed
2025 Oct 14	198,422 KM	Stop N Go Services Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Drive belt tensioner pulley replaced - Drive belt tensioner replaced - Drive belt(s) replaced - Drive belts checked - Light bulb(s) replaced - Noise checked - Oil and filter changed

ODOMETER	SOURCE	DETAILS
		- Serpentine belt replaced - Serpentine tensioner replaced - Tire(s) changed



Open Recalls

- ✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact HONDA or visit [Honda's website](https://www.honda.ca/recalls). (https://www.honda.ca/recalls)



Stolen Vehicle Check

- ✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Jan 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as white
2012 Nov 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as white
2012 Nov 15	19,081 KM	Independent Source Brampton, Ontario, Canada	Odometer reading	
2013 Jan 3	21,000 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2013 Mar 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Jun 27	26,407 KM	The Mufflerman Ontario, Canada	Odometer reading	
2013 Jun 27	26,406 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2014 Mar 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Mar 19	36,770 KM	The Mufflerman Ontario, Canada	Odometer reading	
2014 Mar 19	36,769 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2014 May 14	37,500 KM	The Mufflerman Ontario, Canada	Odometer reading	
2014 May 14	37,499 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2014 Sep 17		Krown Rust Control Burlington, Ontario, Canada	Service Record	Vehicle serviced
2014 Nov 12		Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2014 Dec 15	44,717 KM	The Mufflerman Ontario, Canada	Odometer reading	
2014 Dec 15	44,716 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2015 Mar 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 May 6		Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2015 Aug 25	58,084 KM	Image Honda Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2015 Sep 25	59,749 KM	Image Honda Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2015 Dec 8	62,956 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2016 Mar 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 May 2	66,854 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2016 May 16	67,248 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Dec 16	75,621 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 13	76,489 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2017 Mar 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Mar 23	78,908 KM	Image Honda Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 May 5	80,202 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 22	86,158 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2017 Dec 21	91,971 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 31	93,035 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Feb 22	93,677 KM	Halton Autolease Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 May 10	96,332 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Jun 26	97,735 KM	Image Honda Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Oct 26	102,563 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 11	103,930 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 17	105,274 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Apr 25	110,694 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 25	113,489 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Jul 11	114,669 KM	Speedy Auto Service Burlington #1 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Dec 13	127,536 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Dec 23	127,829 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Mar 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Mar 14	133,609 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Apr 2		Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 20	138,824 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 21	140,111 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 4	143,478 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2021 May 11	149,048 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 30	151,591 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 17	153,815 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 6	156,885 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2022 Jan 26	158,334 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
				Vehicle colour noted as white
2022 Apr 14	161,322 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 14	168,584 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2023 May 4	171,762 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 8	172,298 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 20	177,440 KM	Active Green & Ross Burlington, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 27		Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2024 Mar 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Apr 30	181,317 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2025 Mar 28	191,678 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2025 Oct 14	198,422 KM	Stop N Go Services Burlington, Ontario, Canada	Service Record	Vehicle serviced
2026 Mar 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>