

2013 VOLKSWAGEN JETTA SE

Sedan | 4 Cylinders | Gas
3VWDK7AJ1DM407370
Country of Assembly: Mexico
Last Reported Odometer: 108,455 KM

No Reported Accidents™ >



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



33 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 26, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 May 29	11,689 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Oil and filter changed
2013 Dec 2	24,781 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Brakes checkedOil and filter changedTire condition and pressure checkedTire(s) changedTire(s) replaced
2014 May 22	31,321 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedDrivability/performance checkedTire(s) changed
2014 Nov 17	36,601 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Four tires balancedOil and filter changed
2015 May 12	40,618 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completed
2015 Sep 24	43,480 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Key(s) (re) programmed
2015 Nov 23	44,830 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Air filter replacedBrake fluid flushed/changedBrake rotor(s) replacedOil and filter changedRear brake pads replacedRear brake rotor(s) replacedTire condition and pressure checkedTires rotatedWiper(s) replaced

	ODOMETER	SOURCE	DETAILS
2016 May 5	47,995 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire condition and pressure checked • Tire(s) changed
2016 May 25	48,509 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Door weatherstrip repaired • Oil and filter changed • Window repaired • Wiper(s) replaced
2016 Nov 26	53,229 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire(s) changed
2017 Feb 16	55,196 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2017 May 18	56,998 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire(s) changed
2017 Nov 9	60,917 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Wiper(s) replaced
2017 Nov 17	61,094 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Brake rotor(s) replaced • Brakes serviced • Front brake pads replaced • Front brake rotor(s) replaced • Tire condition and pressure checked • Tire(s) changed
2018 Jun 18	64,546 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire condition and pressure checked • Tire(s) changed
2018 Nov 5	67,420 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced
2019 May 21	71,730 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Alignment checked • Brakes checked • Brakes serviced • Four wheel alignment performed • Front brakes serviced • Oil and filter changed • Rear brake pads replaced • Rear brake rotor(s) replaced • Tire condition and pressure checked • Wiper(s) replaced
2019 Nov 26	75,078 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire condition and pressure checked
2020 Jun 9	77,789 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Tire condition and pressure checked
2020 Nov 11	81,404 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Four wheel alignment performed • Front strut(s) replaced

	ODOMETER	SOURCE	DETAILS
2021 Apr 28	84,212 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Battery replaced • Headlight bulb(s) replaced • Headlight(s) replaced • Oil and filter changed • PCV hose replaced
2021 Nov 8	88,976 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed
2022 Jun 7	94,023 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Antifreeze/coolant flushed/changed • Oil and filter changed • Serpentine belt replaced • Timing belt tensioner/idler checked • Timing belt replaced • Timing belt tensioner/idler replaced
2022 Aug 2	94,621 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Drivability/performance checked • Emission system checked • Fuel injection system flushed/serviced • Fuel system cleaned/serviced • Ignition coil(s) replaced • Spark plug wires replaced • Spark plug(s) replaced
2022 Nov 14	95,548 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed
2022 Dec 5	95,716 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Drivability/performance checked • Emission system checked • Exhaust repaired
2023 Mar 1	96,244 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Drivability/performance checked • Emission system checked • Spark plug wires replaced
2023 Apr 24	96,657 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Brake fluid flushed/changed • Brake pads replaced • Brake rotor(s) replaced • Brakes serviced • Four tires balanced • Four tires mounted • Four wheel alignment performed • Front brake pads replaced • Front brake rotor(s) replaced • Tire condition and pressure checked • Tire repaired • Tire(s) balanced • Tire(s) replaced
2023 Nov 18	98,772 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Door lock actuator(s) replaced
2024 May 16	100,380 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Four wheel alignment performed • Front strut(s) replaced • Rear shock absorber(s) replaced • Shock absorber(s) replaced

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> Sway bar link(s) replaced Tire condition and pressure checked
2024 Jul 19	100,914 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Drivability/performance checked Emission system checked Engine/powertrain computer/module checked Ignition coil(s) replaced Spark plug wires replaced
2024 Nov 27	102,744 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2025 Jun 24	108,455 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Jan 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2013 Mar 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 May 29	11,689 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2013 Dec 2	24,781 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Apr 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 May 22	31,321 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Nov 17	36,601 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Mar 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 May 12	40,618 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Sep 24	43,480 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 23	44,830 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2016 Mar 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 May 5	47,995 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2016 May 25	48,509 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 26	53,229 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2017 Feb 16	55,196 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2017 May 18	56,998 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2017 Jul 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Nov 9	60,917 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 17	61,094 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2018 Jun 18	64,546 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Nov 5	67,420 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 May 21	71,730 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2019 Nov 26	75,078 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 9	77,789 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 11	81,404 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 28	84,212 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 8	88,976 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 7	94,023 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 2	94,621 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2022 Nov 14	95,548 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Dec 5	95,716 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 1	96,244 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Apr 24	96,657 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 18	98,772 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 May 16	100,380 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jul 19	100,914 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Nov 27	102,744 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2025 Mar 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Jun 24	108,455 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2025 Nov 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



3VWDK7AJ1DM407370