



Vehicle History Report #: 60306110
Report Date: March 29, 2025 | 1:09 p.m. EDT
Report Status: Complete


2013 HYUNDAI ELANTRA GLS

Sedan | 4 Cylinders | Gas
5NPDH4AEXDH385216
Country of Assembly: United States
Last Reported Odometer: 125,476 KM

One Owner™ >



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



15 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 29, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5NPDH4AEXDH385216

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2014 Sep 23	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage Vehicle involved in a rear-end collision with another motor vehicle Damage to rear	



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.
We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 May 18	6,198 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2016 Feb 28	28,022 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2016 Aug 6	43,536 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2017 Sep 5		Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2018 Mar 13	63,009 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Wipers/washers checked Vehicle washed/detailed
2019 Apr 22	73,803 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2020 Jan 11	82,521 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Air filter replaced Oil and filter changed Vehicle washed/detailed

5NPDH4AEXDH385216

	ODOMETER	SOURCE	DETAILS
2020 Dec 3	89,999 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2021 Feb 11	91,605 KM	Active Green & Ross Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Alignment checked Four wheel alignment performed Tie rod end(s) replaced Tire condition and pressure checked Tire(s) replaced Tires rotated Two tires replaced
2021 Aug 25	96,096 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2021 Dec 8	101,036 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2022 Apr 13	105,999 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2022 Jul 28	109,999 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2022 Nov 16	114,199 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Vehicle washed/detailed
2023 Nov 8	125,476 KM	Russell Automotive Signature Tire Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Engine/powertrain computer/module checked



Open Recalls

Recall #: R0246-1 | Anti-lock Brake System (ABS) Module Recall Date: 2024 Apr 01

Recall Description

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai Canada recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.

5NPDH4AEXDH385216



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Sep 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2014 May 18	6,198 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2014 Aug 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Sep 23		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • minor damage • Vehicle involved in a rear-end collision • with another motor vehicle • Damage to rear
2015 Aug 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Feb 28	28,022 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2016 Aug 6	43,536 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Sep 5		Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 13	63,009 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 22	73,803 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Jan 11	82,521 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 3	89,999 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 11	91,605 KM	Active Green & Ross Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Aug 25	96,096 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced

5NPDH4AEXDH385216

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Dec 8	101,036 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 13	105,999 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Jul 28	109,999 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 16	114,199 KM	Pennzoil 10 Minute Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 8	125,476 KM	Russell Automotive Signature Tire Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 1		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0246-1
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



5NPDH4AEXDH385216