



Vehicle History Report #: 68919034
Report Date: April 9, 2026 | 4:52 p.m. EDT
Report Status: Complete

2016 VOLKSWAGEN GOLF S/SE

Hatchback | 4 Cylinders | Gas

3VW217AUXGM015271

Country of Assembly: Mexico

Last Reported Odometer: 142,919 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



9 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 09, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2023 Apr 3	107,931 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Air filter replaced - Oil and filter changed - Rear brake pads replaced - Rear brake rotor(s) replaced
2023 Jul 28	110,433 KM	MD Auto Care Inc Limoges, Ontario, Canada	Vehicle serviced - Engine cleaned - Oil and filter changed - Oil pressure sender/switch replaced
2024 Dec 4	129,198 KM	THE AUTOWORKS Elliot Lake, Ontario, Canada	Vehicle serviced - Fluids checked - Oil and filter changed
2025 Jan 2		THE AUTOWORKS Elliot Lake, Ontario, Canada	Vehicle serviced
2025 Mar 17	132,058 KM	THE AUTOWORKS Elliot Lake, Ontario, Canada	Vehicle serviced - Headlight bulb(s) replaced - Headlight(s) replaced - Headlights adjusted
2025 Jun 4	136,400 KM	THE AUTOWORKS Elliot Lake, Ontario, Canada	Vehicle serviced - Fluids checked - Front brake pads replaced - Front brake rotor(s) replaced - Front brakes replaced - Oil and filter changed
2025 Aug 4		THE AUTOWORKS Elliot Lake, Ontario, Canada	Vehicle serviced Rear shock absorber(s) replaced

3VW217AUXGM015271

ODOMETER		SOURCE	DETAILS
2025 Nov 11	142,919 KM	MD Auto Care Inc Limoges, Ontario, Canada	Vehicle serviced Tire condition and pressure checked
2026 Mar 6		THE AUTOWORKS Elliot Lake, Ontario, Canada	Vehicle serviced



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Fleet Vehicle colour noted as red
2016 Oct 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Sep 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed

3VW217AUXGM015271

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Sep 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Jul 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as red
2023 Apr 3	107,931 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 28	110,433 KM	MD Auto Care Inc Limoges, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Sep 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2024 Dec 4	129,198 KM	THE AUTOWORKS Elliot Lake, Ontario, Canada	Service Record	Vehicle serviced
2025 Jan 2		THE AUTOWORKS Elliot Lake, Ontario, Canada	Service Record	Vehicle serviced
2025 Mar 17	132,058 KM	THE AUTOWORKS Elliot Lake, Ontario, Canada	Service Record	Vehicle serviced
2025 Jun 4	136,400 KM	THE AUTOWORKS Elliot Lake, Ontario, Canada	Service Record	Vehicle serviced
2025 Aug 4		THE AUTOWORKS Elliot Lake, Ontario, Canada	Service Record	Vehicle serviced
2025 Sep 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2025 Nov 11	142,919 KM	MD Auto Care Inc Limoges, Ontario, Canada	Service Record	Vehicle serviced
2026 Mar 6		THE AUTOWORKS Elliot Lake, Ontario, Canada	Service Record	Vehicle serviced
2026 Mar 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as red



Questions? We're here to help.
Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a

particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

