



Vehicle History Report #: 61178243
Report Date: May 3, 2025 | 10:27 a.m. EDT
Report Status: Complete

2017 VOLKSWAGEN GOLF S

Hatchback | 4 Cylinders | Gas
3VW217AU1HM010025
Country of Assembly: Mexico
Last Reported Odometer: 134,240 KM

No Reported
Accidents™ >



No Accident/Damage Records
Found



Last Registered In:
Ontario (Normal)



20 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 03, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VW217AU1HM010025

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Oct 11		Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced
2017 Jan 11		Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced
2017 Feb 7		Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed
2017 May 17		Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Oil and filter changed
2017 Nov 23	20,548 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Tire(s) mounted
2018 May 14	30,024 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completed
2018 May 28	30,267 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Brakes checkedCabin air filter replaced/cleanedInterior cleanedMaintenance reminder resetOil and filter changedTires rotated
2018 Nov 10	44,143 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedOil and filter changedTire(s) mountedTires rotated
2018 Dec 8	47,386 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">One tire balancedOne tire mountedTire(s) balanced

3W217AU1HM010025

ODOMETER		SOURCE	DETAILS
2019 Jan 17	49,476 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced
2019 Apr 27	56,667 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Brakes checked• Brake fluid flushed/changed• Maintenance reminder reset• Oil and filter changed• Tire(s) mounted• Tires rotated
2019 Dec 7	57,000 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Brakes checked• Cabin air filter replaced/cleaned• Maintenance reminder reset• Oil and filter changed• One tire balanced• Tire(s) mounted• Tires rotated• Wheel(s) repaired
2020 Jun 24	72,351 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Maintenance inspection completed• Oil and filter changed• Tire(s) mounted• Tires rotated
2021 Jun 22	85,794 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Oil and filter changed
2022 Jun 25	104,788 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Oil and filter changed
2023 Jan 14	123,984 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Oil and filter changed
2023 Jan 23	124,560 KM	Leavens Volkswagen Inc London, Ontario, Canada	Vehicle serviced
2023 Jul 26	127,140 KM	Leavens Volkswagen Inc London, Ontario, Canada	Vehicle serviced
2023 Nov 18	133,395 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Oil and filter changed
2023 Dec 13	134,240 KM	Leavens Volkswagen Inc London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Battery replaced



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Oct 11		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2017 Jan 11		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 31	9,300 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2017 Feb 7		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 May 17		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 23	20,548 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 May 14	30,024 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 May 28	30,267 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 10	44,143 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 8	47,386 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced

3W217AU1HM010025

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jan 17	49,476 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 27	56,667 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Dec 7	57,000 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Jun 24	72,351 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2021 Jun 22	85,794 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2022 Jun 25	104,788 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2023 Jan 14	123,984 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2023 Jan 23	124,560 KM	Leavens Volkswagen Inc London, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 26	127,140 KM	Leavens Volkswagen Inc London, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 18	133,395 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 13	134,240 KM	Leavens Volkswagen Inc London, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Aug 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



3W217AU1HM010025