



Vehicle History Report (BC) #: 69939399
Report Date: May 19, 2026 | 5:09 p.m. EDT
Report Status: Complete
Reference:

2015 TOYOTA HIGHLANDER LIMITED

Sport utility vehicle | 6 Cylinders | Gas

5TDDKRFH0FS191986

Country of Assembly: United States

Last Reported Odometer: 97,133 KM



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



7 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of May 19, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)

 Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
④ 2022 Jan 13	British Columbia, Canada	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00

 Registration

② This vehicle has been registered in the province of **British Columbia** in Canada with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

 Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Dec 10	34,279 KM	Kal Tire 661 North Vancouver, British Columbia, Canada	Vehicle serviced - One tire balanced - One tire mounted
2023 Dec 30		Kal Tire 080 North Vancouver, British Columbia, Canada	Vehicle serviced Tire repaired
2024 May 22	84,788 KM	Kal Tire - Burnaby Burnaby, British Columbia, Canada	Vehicle serviced Four wheel alignment performed
2025 Jan 10	93,685 KM	Kal Tire 661 North Vancouver, British Columbia, Canada	Vehicle serviced Wipers/washers checked
2025 Mar 21	95,545 KM	Variety Auto Solution Coquitlam, British Columbia, Canada	Vehicle serviced - Air filter replaced - Brakes checked - Cabin air filter replaced/cleaned - Front brake pads replaced - Oil and filter changed - Rear brake pads replaced
2025 Apr 8	96,345 KM	Variety Auto Solution Coquitlam, British Columbia, Canada	Vehicle serviced - A/C refrigerant recharged - A/C system flushed

ODOMETER	SOURCE	DETAILS
		- A/C system serviced - Front brake pads replaced - Rear brake pads replaced
2025 May 8	97,129 KM	Murray Hyundai WhiteRock Surrey, British Columbia, Canada Vehicle serviced - Oil and filter changed - Vehicle washed/detailed



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact TOYOTA or visit Toyota's website. (<https://www.toyota.ca/toyota/en/owners/recalls>)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Aug 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2016 Aug 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Dec 10	34,279 KM	Kal Tire 661 North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2019 Aug 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 Jan 13		Insurance Records British Columbia, Canada	COLLISION	
2022 Jan 13		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2022 Aug 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Aug 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Dec 30		Kal Tire 080 North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2024 May 22	84,788 KM	Kal Tire - Burnaby Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2024 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2025 Jan 10	93,685 KM	Kal Tire 661 North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2025 Mar 21	95,545 KM	Variety Auto Solution Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2025 Apr 8	96,345 KM	Variety Auto Solution Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2025 Apr 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2025 May 8	97,129 KM	Murray Hyundai WhiteRock Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2025 May 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2025 Jul 10	97,133 KM	Independent Source Surrey, British Columbia, Canada	Odometer reading	
2025 Jul 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.



VEHICLE INSPECTION

KABANI AUTO

240 12th Street
New Westminster, BC
V3M 4H2

YEAR: 2015
MAKE: Toyota
MODEL: Highlander
STOCK#: KA191986
KMS: 97,173

G- GOOD

S- SATISFACTORY

P- POOR

REPLACED*/ REPAIRED*/NOTE*

1. FLUID LEVELS	G	FULL
2. INSPECT COOLANT SYSTEM / LEAKS	G	
3. DRIVE BELTS	G	
4. BATTERY / CHARGING SYSTEM	G	Starting Battery Load Test Pass
5. FLUID LEAKS (VISUAL)	G	
6. AIR FILTER	G	
7. ENGINE OIL	G	Next at 102200
8. FUEL SYSTEM (VISUAL)	G	
9. EXHAUST SYSTEM	G	
10. ANTIFREEZE -C	G	
11. F/BRAKE LININGS %	G	Aprox. 90% life Remaining 11mm
12. R/BRAKE LININGS %	G	Aprox. 80% life Remaining 8mm
13. FRONT TIRES	G	7mm 35psi
14. REAR TIRES	G	6mm 35psi
15. SHOCKS/STRUTS/SUSPENSION	G	
16. AWD/4X4 OPERATION	G	AWD
17. HEATER FAN & POWER WINDOWS	G	
18. HAND BRAKE	G	
19. DRIVE SHAFTS/U JOINTS	G	
20. SPARE TIRE JACK AND WRENCH	G	Spare Tire Removal In Rear Compartment
21. HEADLIGHTS/LENS	G	
22. TURN LIGHTS/LENS	G	
23. STOP LIGHTS/LENS	G	One Rear Tail Lamp Bulb Replaced
24. BACK UP/LIN. PLATE/LIGHTS	G	
25. WINDSHIELD	G	
26. WINDSHIELD WIPER MOTOR	G	New Wipers Installed
27. REAR VIEW MIRRORS	G	
28. DOOR LOCKS	G	
29. SEAT BELTS	G	
30. ENGINE LAMP	G	Off
31. GENERAL PERFORMANCE	G	
32. ROAD TEST	G	PASS

COMMENTS/ NOTE:

*2 KEY FOB

* TIRES RATED M+S

SO # 151784

SERVICE ORDER
CUSTOMER COPY

Printed 05/08/2025 8:28:18 AM

User 436 Page 1

Customer No	1	Advisor	LANE GOBERT	Promised	05/07/2025 7:19 PM	Tag#	
		Shop	S1	Opened	05/07/2025 2:18 PM	Location	
		Priority	10	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
	97128	97130		M4363
Year	Make	Model	Model Number	Colour
2015	TOYOTA	HIGHLANDER	DKRFHT	BLACK
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
5TDDKRFH0FS191986				
Engine	3.5L 6-Cylinder VVT DOHC -Inc:	Fleet #		

Request	Description	Job	CSR	Status
UVI	USED VEHICLE INSPECTION UVI	1	514	Original
Labour	Description		Type	Amount
UVI			IRPR	
Part	Description	Shp	Bin	Type
11-WWF-PI	BULK WASHE	3	BULK	1
Technician	308 - JASON YAP-CHUNG			
Cause	Perform used vehicle inspection.			
Correction	Used vehicle inspection completed. Vehicle road tested for safety and drivability.			
	Safety and performance inspections completed.			
	Tire depth:			
	FRONT LEFT: 8/32 FRONT RIGHT: 8/32			
	REAR LEFT: 7/32 REAR RIGHT: 7/32			
	Tire wear pattern/damage			
	Battery cold cranking amps factory spec 650cca			actual
	743cca			
	Front brakes 10 mm			
	Rear brakes 8 mm			

Technician recommends and notes:

***wheel lock key in glove box

Request	Description	Job	CSR	Status
ILOF	LUBE OIL AND FILTER CHANGE ILOF	2	514	Original
Labour	Description		Type	Amount
ILOF			1	
Part	Description	Shp	Bin	Type
2004B-HY	HYUNDAI FU	1	13B	1
INT020	0W20 SYNTH OIL AND FILTER KIT	1		1
21513 23001	GASKET-OIL	1	14B	1
000QU 0W20B LK	QUAKER STATE FULL SYNTH 0W20 BULK	5	BULK	1
CH9972	OIL FILTER	1		1
ENVIRO	ENVIRO FEES	1		1
Technician	308 - JASON YAP-CHUNG			

STATEMENT OF DISCLAIMER

THE FACTORY WARRANTY CONSTITUTES ALL OF THE WARRANTIES WITH RESPECT TO THE SALES OF THIS ITEM/ITEMS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR LIABILITY IN CONNECTION WITH THE SALE OF THIS ITEM.

THANK YOU FOR BRINGING YOUR CAR TO US FOR SERVICE.

SUPPLIES ARE SMALL ITEMS, NOT INDIVIDUALLY PRICED, USED TO REPAIR YOUR VEHICLE. IE: COTTER PINS, GEAR LUBES, WHEEL WEIGHTS, SHIMS, CLEANING SOLVENTS AND RAGS, NUTS, BOLTS, WASHERS, SUNDRY, LUBRICANTS, DISPOSAL CHARGES FOR ANTIFREEZE, OIL FILTERS AND OIL, ETC. SOME OF THE ABOVE ITEMS WERE APPLICABLE TO THE REPAIR OF YOUR VEHICLE.

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF \$_____ BEING THE TOTAL AMOUNT OWING, OR BALANCE OWING, AS SHOWN HEREIN.

DATE _____ SIGNATURE X _____

THANK YOU FOR ALLOWING US TO CARE FOR YOUR VEHICLE.

SO # 151784

SERVICE ORDER
CUSTOMER COPY

Printed 05/06/2025 8:28:19 AM

User 436

Page 2

Customer No	Advisor	LANE GOBERT	Promise	05/07/2025 7:19 PM	Tag#
	Shop	S1	Opened	05/07/2025 2:18 PM	Location
	Priority	10	Cashiered		PO #
Term Charge	License	Odom In	Odom Out	In Service Date	Stock No
		97128	97130		M4363
	Year	Make	Model	Model Number	Colour
	2015	TOYOTA	HIGHLANDER	DKRFHT	BLACK
	Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
	5TDDKRFH0FS191986				
	Engine	3.5L 6-Cylinder VVT DOHC -inc:			Fleet #

Cause Perform oil change
Correction Oil change completed. Lubed all hinges and topped up all fluids.

Request	Description	Job	CSR	Status
HY-CPO	Hyundai CPO inspection checklist	3	514	Approved
Labour	Description	Type	Amount	
INFO		1		
Technician	308 - JASON YAP-CHUNG			
Cause				
Correction				

Labour	0.00
Parts	0.00
Supplies	0.00
Sub-Total	0.00
GST	0.00
PST	0.00
Total Invoice	0.00

STATEMENT OF DISCLAIMER
THE FACTORY WARRANTY CONSTITUTES ALL OF THE WARRANTIES WITH RESPECT TO THE SALES OF THIS ITEM/ITEMS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS ITEM.

THANK YOU FOR BRINGING YOUR CAR TO US FOR SERVICE.
SUPPLIES ARE SMALL ITEMS, NOT INDIVIDUALLY PRICED, USED TO REPAIR YOUR VEHICLE. IE: COTTER PINS, GEAR LUBES, WHEEL WEIGHTS, SHIMS, CLEANING SOLVENTS AND RAGS, NUTS, BOLTS, WASHERS, SUNDRIES, LUBRICANTS, DISPOSAL CHARGES FOR ANTIFREEZE, OIL FILTERS AND OIL, ETC. SOME OF THE ABOVE ITEMS WERE APPLICABLE TO THE REPAIR OF YOUR VEHICLE.

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF \$ _____ BEING THE TOTAL AMOUNT OWING, OR BALANCE OWING, AS SHOWN HEREIN.

DATE _____ SIGNATURE _____

THANK YOU FOR ALLOWING US TO CARE FOR YOUR VEHICLE.

VEHICLE DESCRIPTION Stock/ID # **M4363** Odometer reading (km) **97128**
 Year **2015** Model **HIGHLANDER** Colour **BLACK** Engine Type _____ Transmission Type _____
 Inspection Repair Order # **151784** In-Service Date **05/07/2025** Original Owners Literature ☒ Complete ☐ Missing: _____
3:51:37 PM

Mechanical Inspection

1. Road Test

OK	Needs Repair	Description/Condition
☒	☐	Engine Start-Up Cold
☒	☐	Engine Warm-Up
☒	☐	Engine Start-Up Warm
☒	☐	Transaxle Shifting (Vehicle stopped)
☒	☐	Acceleration (Light, Moderate, Hard)
☒	☐	Transaxle Shifting (City, Highway)
☒	☐	Braking (Light, Moderate, Hard)
☒	☐	Driving Speed (Slow, Moderate, Highway)
☒	☐	Directional Stability (Alignment)
☒	☐	Noise/Vibration/Harshness
☒	☐	Cruise Control (Operation)
☒	☐	Rattles/Wind Noise
☒	☐	Accessory/Component Operation.
☒	☐	Other _____

2. Engine Compartment

OK	Needs Repair	Description/Condition
☒	☐	VIN Stamp (Complete)
☒	☐	Engine
☒	☐	Transaxle
☒	☐	Electrical System
☒	☐	Cooling System
☒	☐	Cooling Fan
☒	☐	Steering System
☒	☐	Brake System (Master Cylinder, Lines)
☒	☐	Spark Plug Wires
☒	☐	Ignition Coil(s)
☒	☐	Fuel System (Injectors, Filters, Lines)
☒	☐	Air Conditioning System (Hoses, Refrigerant)
☒	☐	Air Inlet Systems/Filters
☒	☐	Passed Emission Test (If required)
☒	☐	Other _____

3. Under Vehicle

OK	Needs Repair	Description/Condition
☒	☐	Unifit Carriage Inspection
☒	☐	Radiator/Hoses/Cooling Lines
☒	☐	Fuel tank/Lines
☒	☐	Catalytic Converter/O2 Sensors
☒	☐	Exhaust Pipes/Muffler
☒	☐	Wheels
☒	☐	Tires (4/32" minimum tread depth remaining)

FRONT LEFT: 8/32 FRONT RIGHT: 8/32
 REAR LEFT: 7/32 REAR RIGHT: 7/32

BRAKES

☒	☐	Rotors, Pads, Shoes, Drums (4mm minimum lining)	F-10mm R-8mm
☒	☐	Hydraulics (Calipers, Lines, Hoses)	

DRIVELINE

☒	☐	Engine
☒	☐	Clutch (If equipped)
☒	☐	Transaxle
☒	☐	CV Joints & Boots
☒	☐	Transfer Case (If equipped)
☒	☐	Rear Differential (If equipped)

SUSPENSION

☒	☐	Control Arms/Link
☒	☐	Springs & Sway Bars & Bushings
☒	☐	Shock Absorbers

STEERING

☒	☐	Rack & Pinion
☒	☐	Hydraulics (Hoses, Seals)
☒	☐	Linkage (Tie Rods/Ends)
☒	☐	Other _____

4. Exterior

OK	Needs Repair	Description/Condition
☒	☐	Head Lamps
☒	☐	Tail/Brake Lamps
☒	☐	Signal/Marker Lights
☒	☐	Wipers/Washers
☒	☐	Outside Mirrors
☒	☐	Other _____

5. Interior

OK	Needs Repair	Description/Condition
☒	☐	Gauges & Instrumentation
☒	☐	Primary Controls (Steering, Shift, Brakes)
☒	☐	Controls (WS/Wiper, Washer, etc.)
☒	☐	Safety Restraints (SRS, Seatbelts, Child Seat Anchors)
☒	☐	Climate Control System
☒	☐	Fuel Door Control
☒	☐	Sound System (Radio/Tape/CD, Speakers, Antenna)
☒	☐	Windows
☒	☐	Seats
☒	☐	Doors/Door Locks (Keys, Lock, Child Locks)
☒	☐	Mirrors
☒	☐	Interior Lights
☒	☐	Keyless Entry & Alarm
☒	☐	Cargo Area (Spare Tire, Tools)
☒	☐	Sun/Moon Roof
☒	☐	Other _____

Appearance Inspection

Exterior

OK	Needs Repair	Description/Condition
☐	☐ Front Bumper	
☐	☐ Grille	
☐	☐ Hood	
☐	☐ LF Fender	
☐	☐ LF Wheel Well	
☐	☐ LF Door	
☐	☐ LR Door	
☐	☐ LR Fender	
☐	☐ LR Wheel Well	
☐	☐ Trunk Lid, Tailgate	
☐	☐ Spoiler (if equipped)	
☐	☐ Rear Bumper	
☐	☐ RR Fender	
☐	☐ RR Door	
☐	☐ RR Wheel Well	
☐	☐ RF Door	
☐	☐ RF Fender	
☐	☐ RF Wheel Well	
☐	☐ Roof	
☐	☐ Windshield/Door/Rear Glass	
☐	☐ Wheels/Wheel Covers	
☐	☐ Other	

7. Interior

OK	Needs Repair	Description/Condition
☐	☐ VIN Plate/Sticker	
☐	☐ Instrument Panel	
☐	☐ Dash Panel	
☐	☐ Glove Box (Owners Literature)	
☐	☐ Drivers Seat	
☐	☐ Driver Door Panel	
☐	☐ Passenger Seat	
☐	☐ Passenger Door Panel	
☐	☐ Sport Carpet	
☐	☐ Floor Mats	
☐	☐ Rear Seat	
☐	☐ LR Door Panel	
☐	☐ LR Quarter Trim	
☐	☐ RR Door Panel	
☐	☐ RR Quarter Trim	
☐	☐ Rear Carpet	
☐	☐ Floor Mats	
☐	☐ Headliner	
☐	☐ Trunk/Cargo Area	
☐	☐ Other	

8. Servicing (Required for all CPO vehicles)

Maintenance Services (Required)

- ☐ Engine (Engine Oil & Filter Inspections/Change)
- ☐ Mechanical Services (Within 3 months/6,000/mi)
- ☐ Outstanding Recalls
- ☐ Diagnostic Code Check (Scan test, ECM, TCM, SRS, ABS)
- ☐ Appearance (Exterior clean, wax Interior clean)

9. Quality Inspection

I certify that I have inspected this vehicle and made an evaluation against Hyundai Certification Standards

Technician's Signature _____

Date _____

10. Certification

I certify that this vehicle meets or exceeds all Hyundai Certification Standards

Dealership Name _____ Dealer Code _____

Used Vehicle Manager _____ Date _____