



Vehicle History Report #: 69139316
Report Date: April 17, 2026 | 1:57 p.m. EDT
Report Status: Complete

2022 VOLKSWAGEN ATLAS SEL

Sport utility vehicle | 6 Cylinders | Gas
1V2BR2CA6NC524966
Country of Assembly: United States
Last Reported Odometer: 129,845 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



21 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of April 17, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2022 Mar 24		Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Oil and filter changed Wheel locks installed
2022 Apr 8		Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced
2022 Jun 20	7,088 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2022 Aug 10	12,030 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced
2022 Oct 6	17,320 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2023 Mar 17	30,090 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Fluids checked Oil and filter changed Windshield washer checked
2023 Jul 6	41,326 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Cabin air filter replaced/cleaned Fluids checked Oil and filter changed

1V2BR2CA6NC524966

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> Windshield washer checked
2023 Aug 10	45,216 KM	Volkswagen Villa Thornhill, Ontario, Canada	Vehicle serviced
2023 Oct 8	51,596 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2023 Oct 17		Town Country Volkswagen Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Inspection performed Alignment checked Tire checked
2023 Oct 27	52,910 KM	Town and Country Volkswagen Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed
2023 Nov 7	55,233 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire repaired
2024 Jan 7	60,788 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2024 Apr 18	70,369 KM	Town and Country Volkswagen Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Oil and filter changed Spark plug(s) replaced Steering/suspension checked Sunroof drain hoses serviced
2024 Jul 25	80,768 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Air filter replaced Fluids checked Oil and filter changed Windshield washer checked
2024 Oct 18	90,637 KM	Hanna Motor Sales Co LTD Collingwood, Ontario, Canada	Vehicle serviced
2024 Oct 22	91,234 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2025 Feb 6	101,620 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2025 May 13	110,324 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Cabin air filter replaced/cleaned Fluids checked Oil and filter changed Tire condition and pressure checked

1V2BR2CA6NCS24966

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> Windshield washer checked
2025 Aug 24	120,627 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked
2025 Dec 6	129,845 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Windshield washer checked



Open Recalls

Recall #: 69PZ | PODS Recall Date: 2024 Jun 25

Recall Description

A wire with a contact fault may cause the Passenger Occupant Detection System (PODS) to detect a malfunction and switch off the passenger airbag, even though the seat may be occupied. In a crash with frontal airbag deployment, there would be an increased risk of injury to the occupant seated in the front passenger seat if the passenger frontal airbag is switched off or not working. Should a malfunction occur, vehicle occupants will be alerted by illumination of the airbag warning light, an acoustic warning sound, an error message displayed in the instrument cluster and by the status of the Passenger Airbag OFF indicator light. If this happens, owners are advised to make an appointment with an authorized Volkswagen dealer to have the vehicle inspected without delay.

Remedy

Replace the PODS sensor mat and wiring harness.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Mar 24		Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Apr 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as gray
2022 Apr 8		Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 20	7,088 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 10	12,030 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 6	17,320 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 17	30,090 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 6	41,326 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Aug 10	45,216 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 8	51,596 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 17		Town Country Volkswagen Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 27	52,910 KM	Town and Country Volkswagen Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 7	55,233 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 7	60,788 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 18	70,369 KM	Town and Country Volkswagen Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 25		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 69PZ
2024 Jul 25	80,768 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Oct 18	90,637 KM	Hanna Motor Sales Co LTD Collingwood, Ontario, Canada	Service Record	Vehicle serviced
2024 Oct 22	91,234 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced

1V2BR2CA6NC524966

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2025 Feb 6	101,620 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2025 May 13	110,324 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2025 Aug 24	120,627 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced
2025 Dec 6	129,845 KM	Jiffy Lube #2869 Markham, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

