

Vehicle History Report #: 53446796 Report Date: May 18, 2024 | 4:26 PM EDT Report Status: Complete

2009 HONDA CR-V EXL

Sport utility vehicle | 4 Cylinders | Gas 5J6RE48769L807470 Country of Assembly: United States Last Reported Odometer: 153,271 KM

One Owner™ >





Last Registered In: Ontario (Normal)



2 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at **support.carfax.ca**



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 18, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
① 2014 Jul 16	Brampton, Ontario, Canada	
	Estimate: Left Front Corner Estimate Date: 2014 Aug 12	\$2,011.08
	Claim: Other Damage	\$2,011.00
9 2016 May 16	East York, Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage with another motor vehicle Damage to left front	
	Estimate: Left Front Corner Estimate Date: 2016 May 19	\$2,120.19
	Claim: Collision	\$1,121.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2019 Feb 6	Ontario, Canada	
	Glass Record	\$350.00



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2022 Oct 13	153,271 KM	M & S Auto Centre	Vehicle serviced
		East York, Ontario, Canada	Oil and filter changed
		, ,	 Exhaust pipe replaced
			 Battery/charging system checked
			 Fuel system cleaned/serviced
			 Fuel injection system flushed/serviced
			 Antifreeze/coolant checked
			Fluids checked

ODOM	METER SOURCE	DETAILS
2023 Oct 24	M & S Auto Centre	Vehicle serviced
	East York, Ontario, Ca	nada • Oil and filter changed
	,,,,	Air filter replaced
		Brake fluid flushed/changed
		Fuel system cleaned/serviced
		Fuel injection system flushed/serviced
		Antifreeze/coolant checked
		Fluids checked
		Brakes checked
		 Antifreeze/coolant flushed/changed
		Cabin air filter replaced/cleaned



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact HONDA or visit Honda's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2009 May 11		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		First Owner Reported
				Vehicle colour noted as silver
2009 Jul 19		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Personal
2010 Aug 4		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Personal
2011 Jul 19		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Personal
2012 Jul 31		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Personal
2014 Jul 16		Insurance Records		
		Ontario, Canada		
2014 Jul 16	90,101 KM	Insurance Records	Estimate Repair	Estimate Date: 2014-08-12
-		Brampton, Ontario, Canada		Left Front Corner
2014 Aug 5		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Personal
2015 Jul 19		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 May 16		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage with another motor vehicle Damage to left front
2016 May 16		Ontario, Canada	Collision	
2016 May 16	107,823 KM	Insurance Records East York, Ontario, Canada	Estimate Repair	Estimate Date: 2016-05-19 Left Front Corner
2016 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Feb 6		Insurance Records Ontario, Canada	Glass Record	\$350.00
2019 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Apr 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as silver
2022 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as silver
2022 Oct 13	153,271 KM	M & S Auto Centre East York, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 24		M & S Auto Centre East York, Ontario, Canada	Service Record	Vehicle serviced



CARFAX Canada One Owner™ Badge
The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

