

Vehicle History Report #: 55645945
Report Date: August 20, 2024 | 7:33 p.m. EDT
Report Status: Complete

2017 FORD EXPLORER XLT

Sport utility vehicle | 6 Cylinders | Gas 1FM5K8D81HGA24952 Country of Assembly: United States Last Reported Odometer: 37,317 KM





Last Registered In: Ontario (Normal)



1 Service Record Found







5 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 20, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
① 2020 Feb 19	Thornhill, Ontario, Canada	
	Estimate: Rear Center Estimate Date: 2020 Mar 4	\$10,558.80
	Claim: Unknown	\$10,559.00
① 2020 Nov 9	Ontario, Canada	
	Claim: Collision	\$0.00



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Dec 19		Colony Ford Lincoln Sales Inc. Brampton, Ontario, Canada	Vehicle serviced Oil and filter changed Tires rotated



Open Recalls

Recall #: 21S22 | ROOF RACK TRIM DETACHMENT Recall Date: 2021 May 10

Recall Description

THE ROOF RAIL COVERS MAY BECOME DETACHED FROM YOUR VEHICLE.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND SECURE THE ROOF RAIL COVER FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)

Recall #: 21S32 | REAR TOE LINK REPLACEMENT Recall Date: 2022 Feb 23

Recall Description

VEHICLES EXPOSED TO A CORROSIVE ENVIRONMENT WHERE ROAD SALT IS USED EXTENSIVELY DURING WINTER MONTHS COULD EXPERIENCE A SEIZED REAR SUSPENSION TOE LINK BALL IOINT RESULTING IN A FRACTURED REAR SUSPENSION TOE LINK.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE BOTH REAR TOE LINKS AND ADJUST REAR TOE FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)

Recall #: 20S62 | REAR TOE LINK BALL JOINT INSPECTION Recall Date: 2022 Feb 23

Recall Description

OUR RECORDS INDICATE THAT A FORD SAFETY RECALL WAS PREVIOUSLY PERFORMED ON YOUR VEHICLE TO REPLACE THE REAR SUSPENSION TOE LINKS. ASSESSMENT OF FIELD DATA INDICATES THAT THE BALL JOINT USED TO ATTACH THE REAR TOE LINK MAY BE SUSCEPTIBLE TO SEIZING IN CERTAIN HIGH CORROSION AREAS. A SEIZED TOE LINK BALL JOINT CAN INCREASE BENDING STRESSES IN THE TOE LINK AND POTENTIALLY LEAD TO A FRACTURE.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT BOTH REAR TOE LINK BALL JOINTS AND, IF NECESSARY, REPLACE THE REAR WHEEL KNUCKLE(S), AND ADJUST REAR TOE FREE OF CHARGE (PARTS AND LABOR).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)

Recall #: 24S02 | EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION Recall Date: 2024 Jan 23

Recall Description

IN SOME OF THE AFFECTED VEHICLES IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPAIR ANY LOOSE OR MISSING EXTERIOR A-PILLAR TRIM MOLDINGS FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)

Recall #: 19S29 | SEAT FRAME BURRED EDGE Recall Date: 2019 Sep 12

Recall Description

ON YOUR VEHICLE, THE INBOARD POWER SEAT TRACK MAY HAVE A SHARP BURR DUE TO AN IMPROPERLY FINISHED EDGE.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSTALL FLOCKED TAPE OVER SEAT TRACK EDGE FREE OF CHARGE (PARTS AND LABOR).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Aug 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2017 Nov 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Sep 12		FORD	Recall	Manufacturer Recall Issued Recall # 19S29
2019 Nov 8	32,374 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2019 Dec 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as black
2020 Feb 19		Ontario, Canada	Unknown	
2020 Mar 4	37,317 KM	Insurance Records Thornhill, Ontario, Canada	Estimate Repair	Incident Date: 2020-02-19 Rear Center
2020 Aug 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Nov 9		Insurance Records Ontario, Canada		
2020 Dec 19		Colony Ford Lincoln Sales Inc.	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Brampton, Ontario, Canada	1	
2021 May 10		FORD	Recall	Manufacturer Recall Issued Recall # 21S22
2021 Aug 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 Feb 23		FORD	Recall	Manufacturer Recall Issued Recall # 20S62
2022 Feb 23		FORD	Recall	Manufacturer Recall Issued Recall # 21S32
2022 Aug 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2024 Jan 23		FORD	Recall	Manufacturer Recall Issued Recall # 24S02
2024 Aug 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information from rediscrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

