Vehicle History Report #: 55471353

Report Date: August 13, 2024 | 2:00 p.m. EDT

Report Status: Complete

### 2013 HYUNDAI ELANTRA GLS

Sedan | 4 Cylinders | Gas 5NPDH4AE3DH434773

Country of Assembly: United States Last Reported Odometer: 170,763 KM





Last Registered In: **Ontario (Normal)** 



18 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



Questions? We're hare to help.

Visit us at support.carfax.ca

Visit us at support.carfax.ca reported and available to CARFAX Canada as of August 13, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report**



# Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
① 2014 May 5	Brampton, Ontario, Canada	
	Estimate: Right Rear Corner   Estimate Date: 2014 Jun 2	\$2,600.12
	Claim: Unknown	\$1,050.00
<b>1</b> 2019 Jun 14	Brampton, Ontario, Canada	
	Estimate: Rear Center   Estimate Date: 2019 Jul 5	\$961.05
	Claim: Unknown	\$1,223.00

# **Other Damage Records**

RECORD DATE	DETAILS	AMOUNT		
① 2014 Sep 24	Ontario, Canada			
	Glass Record	\$121.00		
1 2024 Jan 31	Ontario, Canada			
	Glass Record	\$701.00		



# Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.




### **Service Records**

DATE	ODOMETER	SOURCE	DETAILS	
2016 Nov 18	66,735 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  • Light bulb(s) replaced	

			<ul><li>Front brake rotor(s) replaced</li><li>Front brake pads replaced</li><li>Brakes checked</li></ul>
2016 Dec 22	69,519 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  • Air filter replaced  • Light bulb(s) replaced  • Cabin air filter replaced/cleaned
2018 Sep 19	102,695 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced     Oil and filter changed     Fluids checked
2018 Dec 1	64,786 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  Tire(s) replaced  Tire(s) balanced  Tire(s) mounted  One tire mounted  One tire balanced  POTENTIAL ODOMETER ROLLBACK
2019 Jan 2	67,993 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  Rear brake pads replaced Rear brake rotor(s) replaced Brake rotor(s) replaced Brakes checked Rear brakes replaced
2019 Apr 23		IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  • Wiper(s) replaced  • Oil and filter changed  • Spark plug(s) replaced  • Engine/powertrain computer/module checked  • Wipers/washers checked
2019 Sep 13	115,134 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  • Light bulb(s) replaced  • Oil and filter changed
2020 Mar 10	122,037 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  Light bulb(s) replaced  Oil and filter changed  Brake light bulb(s) replaced
2020 Jun 3	123,401 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  • A/C refrigerant recharged  • A/C hose/line replaced  • A/C system checked  • Cabin air filter replaced/cleaned
2020 Nov 14	129,003 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  Oil and filter changed
2021 Apr 1	133,587 KM	Top Notch Motors Inc. Brampton, Ontario, Canada	Vehicle serviced  Rear brake pads replaced Brake pads replaced Front brake rotor(s) replaced Front brake pads replaced
2021 Sep 23	143,356 KM	Top Notch Motors Inc. Brampton, Ontario, Canada	Vehicle serviced  • Light bulb(s) replaced

2023 Jan 13	162,692 KM	Great Canadian Oil Change Brampton, Ontario, Canada	<ul> <li>Vehicle serviced</li> <li>Maintenance inspection completed</li> <li>Fluids checked</li> <li>Oil and filter changed</li> </ul>
2023 Mar 22	166,617 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced
2023 Jun 30	170,763 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced  • Maintenance inspection completed  • Fluids checked  • Oil and filter changed  • Cabin air filter replaced/cleaned
2023 Jul 11		IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  Alignment checked  Tie rod end(s) replaced  Ignition coil(s) replaced  Spark plug(s) replaced  Crankshaft position sensor replaced  Engine/powertrain computer/module checked
2024 Apr 8		IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced
2024 Aug 12		IPG Kennedy Auto Service Brampton, Ontario, Canada	Vehicle serviced  Tire condition and pressure checked Tire(s) replaced Tire(s) balanced One tire mounted One tire balanced



Recall #: R0136 | Elantra Brake Pedal Stopper Replacement Recall Date: 2018 Jan 10

#### **Recall Description**

In some vehicles, the brake pedal stopper material may be deteriorated. This may cause unintended illumination of the stop lamp, traction control warning lamp, activation of the engine management system's brake override feature, and/or movement of the shift lever out of Park without depressing the brake pedal. Correction: Dealers will replace the brake pedal stopper pad.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**. (https://recall.hyundaicanada.com/)

Recall #: C0525 - (UD/MD/JK) | Underbody Corrosion Recall Date: 2023 Mar 08

#### **Recall Description**

Issue: Hyundai Auto Canada is conducting a Special Service Campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. In extreme cases, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**. (https://recall.hyundaicanada.com/)

Recall #: R0246-1 | Anti-lock Brake System (ABS) Module Recall Date: 2024 Jun 21

#### **Recall Description**

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai Canada recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**. (https://recall.hyundaicanada.com/)



### Stolen Vehicle Check

This vehicle is not actively declared stolen.



### **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Nov 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as gray
2014 Jan 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use:

2014 May 5		Ontario, Canada	Unknown	
2014 Jun 2	11,128 KM	Insurance Records Brampton, Ontario, Canada	Estimate Repair	Incident Date: 2014 05-05 Right Rear Corner
2014 Sep 24		Insurance Records Ontario, Canada	Glass Record	\$121.00
2016 Jan 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Nov 18	66,735 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2016 Dec 22	69,519 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 10		HYUNDAI	Recall	Manufacturer Recal Issued Recall # R0136
2018 Jan 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 19	102,695 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 1	64,786 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 2	67,993 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 23		IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 14		Ontario, Canada	Unknown	
2019 Jul 5	112,032 KM	Insurance Records Brampton, Ontario, Canada	Estimate Repair	Incident Date: 2019 06-14 Rear Center
2019 Sep 13	115,134 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced

2020 Jan 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2020 Mar 10	122,037 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 3	123,401 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 14	129,003 KM	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 1	133,587 KM	Top Notch Motors Inc. Brampton, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 23	143,356 KM	Top Notch Motors Inc. Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 Jan 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2022 Sep 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2023 Jan 13	162,692 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 8		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0525 - (UD/MD/JK)
2023 Mar 22	166,617 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 30	170,763 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 11		IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 31		Insurance Records	Glass Record	\$701.00

	Ontario, Canada		
2024 Apr 8	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 21	HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0246-1
2024 Jul 4	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Aug 12	IPG Kennedy Auto Service Brampton, Ontario, Canada	Service Record	Vehicle serviced



# Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, ownere readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use

© 2024 CARFAX Canada ULC. All rights reserved.

