



Vehicle History Report #: 59632147
Report Date: March 2, 2025 | 10:29 a.m. EST
Report Status: Complete

2019 VOLKSWAGEN ATLAS SEL

Sport utility vehicle | 6 Cylinders | Gas
1V2MR2CAXKC582213
Country of Assembly: United States
Last Reported Odometer: 96,482 KM

No Reported Accidents™ >



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



10 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 02, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

1V2MR2CAXKC582213

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

| DATE | ODOMETER | SOURCE | DETAILS |
|-------------|-----------|--|--|
| 2019 Jul 12 | | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Wheel locks installed |
| 2019 Oct 25 | | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed |
| 2020 Jan 21 | 6,519 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed |
| 2020 Jun 15 | 11,740 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Battery charged Engine/powertrain computer/module reprogrammed |
| 2020 Aug 26 | 15,681 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced |
| 2021 Oct 20 | 41,668 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Inspection performed Vehicle serviced <ul style="list-style-type: none"> Alignment checked |
| 2022 Sep 20 | 61,767 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Brakes checked Oil and filter changed |
| 2023 Jan 24 | 73,191 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced |
| 2023 Mar 1 | 75,995 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Brakes checked Oil and filter changed |
| 2023 Oct 20 | 96,482 KM | Volkswagen Villa Thornhill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Brakes checked Front brake pads replaced Front wiper blades/refills replaced |

1V2MR2CAXKC582213

| ODOMETER | SOURCE | DETAILS |
|----------|--------|-------------------------------|
| | | • Safety inspection performed |



Open Recalls

Recall #: 69FB | PASSENGER OCCUPANT DETECTION SYSTEM (PODS) Recall Date: 2023 Apr 05

Recall Description

A wire with a contact fault may cause the Passenger Occupant Detection System (PODS) to detect a malfunction and switch off the passenger airbag, even though the seat may be occupied. In a crash, there would be an increased risk of injury to the occupant seated in the front passenger seat if the passenger frontal airbag is switched off or not working..Should a malfunction occur, vehicle occupants will be alerted by illumination of the airbag warning light, an acoustic warning sound, an error message displayed in the instrument cluster and by the status of the Passenger Airbag OFF indicator light. If this happens, owners are advised to make an appointment with an authorized Volkswagen dealer to have the vehicle inspected without delay and discontinue use of the front passenger seat.

Remedy

Replace the PODS sensor mat and seat harness.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|-----------|--|------------------|---|
| 2019 Jul 12 | | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Oct 23 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed First Owner Reported Vehicle colour noted as black |
| 2019 Oct 25 | | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jan 21 | 6,519 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jun 15 | 11,740 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jun 27 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |

1V2MR2CAXKC582213

| | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|-----------|--|------------------|---|
| 2020 Aug 26 | 15,681 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 Jun 27 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black |
| 2021 Oct 20 | 41,668 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2022 Feb 26 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black |
| 2022 Jun 27 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black |
| 2022 Sep 20 | 61,767 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2023 Jan 24 | 73,191 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2023 Mar 1 | 75,995 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2023 Apr 5 | | VOLKSWAGEN | Recall | Manufacturer Recall Issued Recall # 69FB |
| 2023 Oct 20 | 96,482 KM | Volkswagen Villa Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2024 Jul 4 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

