



Vehicle History Report (BC) #: 62406133
Report Date: June 24, 2025 | 3:13 p.m. EDT
Report Status: Complete

2018 VOLKSWAGEN GTI S/SE

Hatchback | 4 Cylinders | Gas
3VW447AU5JM254461
Country of Assembly: Mexico
Last Reported Odometer: 128,327 KM



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



9 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.
Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 24, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2019 May 18	British Columbia, Canada	
	Estimate: FRONT CENTER Estimate Date: n/a	\$4,572.19
	Claim: ANIMAL COLLISION FRONT CENTER	\$4,355.40
2020 Aug 15	British Columbia, Canada	
	Estimate: LEFT REAR CORNER Estimate Date: n/a	\$1,200.55
	Claim: COLLISION LEFT REAR CORNER	\$1,110.14

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2019 Dec 14	British Columbia, Canada	
	Glass Record	\$882.37
2024 Jun 27	British Columbia, Canada	
	Glass Record	\$1,010.53



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.
We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Sep 24		Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Nitrogen fill tires
2018 Apr 26		Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced

3VW447AU5JM254461

	ODOMETER	SOURCE	DETAILS
2018 Nov 7	13,108 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Lights checked Maintenance reminder reset Oil and filter changed Tire condition and pressure checked
2019 Feb 11	25,320 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Lights checked Maintenance reminder reset Oil and filter changed Tire condition and pressure checked
2019 Jun 21		Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Lights checked Maintenance reminder reset Oil and filter changed Tire condition and pressure checked
2019 Nov 22	54,251 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Lights checked Maintenance reminder reset Oil and filter changed Tire condition and pressure checked
2019 Dec 27	59,926 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Key(s) (re) programmed
2020 Mar 13	70,267 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Door lock(s) replaced/repaired Interior trim repaired Lights checked Maintenance reminder reset Oil and filter changed Tire condition and pressure checked
2023 Sep 14	128,327 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Vehicle serviced



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.


Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

 This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Sep 24		Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2018 Apr 26		Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2018 Jul 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2018 Nov 7	13,108 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2019 Feb 11	25,320 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2019 May 18		Insurance Records British Columbia, Canada	ANIMAL COLLISION	FRONT CENTER
2019 May 18		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a FRONT CENTER
2019 Jun 21		Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jul 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Nov 22	54,251 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2019 Dec 14		Insurance Records British Columbia, Canada	Glass Record	\$882.37
2019 Dec 27	59,926 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2020 Mar 13	70,267 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2020 Jul 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Aug 15		Insurance Records British Columbia, Canada	COLLISION	LEFT REAR CORNER

3VW447AU5JM254461

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Aug 15		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT REAR CORNER
2021 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2022 Jul 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2023 Jul 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2023 Sep 14	128,327 KM	Volkswagen Of Kamloops Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jun 27		Insurance Records British Columbia, Canada	Glass Record	\$1,010.53
2024 Jul 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2025 Apr 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as blue



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

