

Vehicle History Report #: 58451618 Report Date: January 3, 2025 | 10:30 a.m. EST

Report Status: Complete

2014 NISSAN ROGUE S

Sport utility vehicle | 4 Cylinders | Gas 5N1AT2MV7EC760313 Country of Assembly: United States Last Reported Odometer: 137,636 KM





No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



18 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of January 03, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

| DATE ODOMETER | | SOURCE | DETAILS | | |
|---------------|-----------|----------------------------|---|--|--|
| 2014 Nov 11 | 11,539 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Oil and filter changed | | |
| | | | Tires rotated | | |
| 2014 Nov 20 | 11,685 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Rear wiper motor replaced | | |
| 2015 Jun 22 | 18,367 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Oil and filter changed | | |
| | | | Tires rotated | | |
| 2016 Jan 25 | 27,185 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Oil and filter changed | | |
| | | | Tires rotated | | |
| 2016 Jul 25 | 34,240 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Oil and filter changed | | |
| | | | Tires rotated | | |
| | | | Computer reprogrammed | | |
| | | | Vehicle serviced | | |
| | | | Oil and filter changed | | |
| | | | Tires rotated Gomester represented | | |
| | | | Computer reprogrammed | | |
| 2016 Nov 8 | 40,753 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Front brakes serviced | | |
| | | | Vehicle serviced | | |
| | | | Front brakes serviced | | |
| 2017 Jan 20 | 43,835 KM | Service Facility | Vehicle serviced | | |
| | | Thornhill, Ontario, Canada | Fuel pump replaced | | |
| | | | Engine/powertrain computer/module reprogrammed Transmission computer/module reprogrammed | | |
| | | | Vehicle serviced | | |
| | | | Fuel pump replaced | | |
| | | | Engine/powertrain computer/module reprogrammed | | |

· Transmission computer/module reprogrammed

| | ODOMETER | SOURCE | DETAILS |
|-------------|------------|--------------------------------|--|
| 2017 Feb 14 | 45,271 KM | Willowdale Nissan | Vehicle serviced |
| | | Thornhill, Ontario, Canada | Oil and filter changed |
| | | | Tires rotated |
| | | | Vehicle serviced |
| | | | Oil and filter changedTires rotated |
| | | | |
| 2017 Sep 7 | 55,439 KM | Willowdale Nissan | Vehicle serviced |
| | | Thornhill, Ontario, Canada | Oil and filter changed |
| | | | Tires rotated |
| | | | Vehicle serviced |
| | | | Oil and filter changed Time material |
| | | | Tires rotated |
| 2018 Mar 12 | 64,482 KM | Willowdale Nissan | Vehicle serviced |
| | | Thornhill, Ontario, Canada | Oil and filter changed |
| | | | Tires rotated |
| 2018 Apr 26 | 66,424 KM | Willowdale Nissan | Vehicle serviced |
| 20.07.4.20 | 55, 12 1 1 | Thornhill, Ontario, Canada | |
| | | THORITIMI, Officiatio, Carlada | |
| 2018 Sep 28 | 76,000 KM | Willowdale Nissan | Vehicle serviced |
| | | Thornhill, Ontario, Canada | Oil and filter changed |
| | | | Tires rotated |
| 2018 Dec 31 | 79,827 KM | Willowdale Nissan | Vehicle serviced |
| | | Thornhill, Ontario, Canada | |
| 2019 Jan 31 | 82,241 KM | Willowdale Nissan | Vehicle serviced |
| 2019 Jan 31 | 02,241 KW | | Radio replaced |
| | | Thornhill, Ontario, Canada | · Natio replaced |
| 2019 Jun 3 | 87,680 KM | Willowdale Nissan | Vehicle serviced |
| | | Thornhill, Ontario, Canada | Oil and filter changed |
| | | | Tire condition and pressure checked |
| | | | Vehicle washed/detailed |
| | | | Radio replaced |
| 2019 Sep 5 | 92,898 KM | Mister Transmission #169 | Vehicle serviced |
| ' | • | Richmond Hill, Ontario, Canada | Transmission fluid changed |
| | | , Sittario, Cariada | |
| 2020 Jan 6 | 98,168 KM | Midas Auto Service Experts | Vehicle serviced |
| | | Richmond Hill, Ontario, Canada | Maintenance inspection completed |
| | | | Oil and filter changed |
| | | | • Fluids checked |
| | | | Tire repaired |
| 2022 Oct 14 | 137,636 KM | Avenue Nissan | Vehicle serviced |
| | | | |



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)



Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|-----------|---|------------------|---|
| 2013 Dec 9 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed First Owner Reported Vehicle colour noted as white |
| 2014 Jul 21 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2014 Nov 11 | 11,539 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2014 Nov 20 | 11,685 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2015 Jun 22 | 18,367 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Jan 25 | 27,185 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Mar 24 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2016 Jul 25 | 34,240 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Nov 8 | 40,753 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Jan 20 | 43,835 KM | Service Facility Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Feb 14 | 45,271 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Jun 4 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2017 Sep 7 | 55,439 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2018 Mar 12 | 64,482 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2018 Apr 26 | 66,424 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2018 Jun 15 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2018 Sep 28 | 76,000 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |

| | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|------------|---|------------------|---|
| 2018 Dec 31 | 79,827 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Jan 31 | 82,241 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Jun 3 | 87,680 KM | Willowdale Nissan Thornhill, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Jun 4 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2019 Sep 5 | 92,898 KM | Mister Transmission #169 Richmond Hill, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jan 6 | 98,168 KM | Midas Auto Service Experts Richmond Hill, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jun 11 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2020 Jul 16 | 103,000 KM | Independent Source Toronto, Ontario, Canada | Odometer reading | |
| 2020 Jul 22 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | New Owner Reported |
| 2020 Sep 4 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2020 Oct 2 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | New Owner reported Vehicle colour noted as white |
| 2021 Sep 17 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white |
| 2022 Oct 14 | 137,636 KM | Avenue Nissan North York, Ontario, Canada | Service Record | Vehicle serviced |
| 2023 Sep 4 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |



CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information from rediscrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Set this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2025 CARFAX Canada ULC. All rights reserved.

