

(i)

2015 LAND ROVER RANGE ROVER **EVOQUE PURE PREMIUM** Sport utility vehicle | 4 Cylinders | Gas SALVR2BG5FH966168 Country of Assembly: United Kingdom Last Reported Odometer: 121,758 KM LIEN CHECK One Owner™ > No Lien Records Found Accident/Damage Records Found Last Registered In: 21 Service Records Found **Ontario** (Normal) No U.S. History Found No Open Recalls Found Not Actively Declared Stolen Questions? We're here to help. Visit us at support.carfax.ca No Import Record Found

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 11, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check

🔍 Lien Check

No lien records found in Ontario.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

실 Accident/Damage

Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

| 5 | | SOURCE | DETAILS | | |
|------------|----------|---|--|--|--|
| | | Grand Touring Automobiles Toronto, Ontario, Canada | Vehicle serviced Pre-delivery inspection completed Vehicle washed/detailed | | |
| 2015 Mar 5 | 9,233 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Vehicle serviced Transmission checked | | |

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount

of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

| 2015 Mar 19 | | Grand Touring Automobiles | Vehicle serviced |
|-------------|-----------|---------------------------|---|
| | | Toronto, Ontario, Canada | |
| 2015 Aug 24 | 15,329 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | 10,000 mile service performed Engine/powertrain computer/module reprogrammed |
| 2015 Sep 23 | 16,623 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | |
| 2016 Jan 19 | 21,585 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | Transmission checkedBody computer/module checked |
| 2016 Feb 17 | 21,725 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | Computer(s) checked CDS (Nextension and the section of th |
| | | | GPS/Navigation system servicedComputer reprogrammed |
| 2016 Mar 21 | 22,515 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | Computer(s) checkedBlind spot warning sensor replaced |
| 2016 Apr 7 | 23,084 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | Body computer/module checked |
| 2016 Oct 31 | 31,714 KM | Grand Touring Automobiles | Vehicle serviced |
| | | Toronto, Ontario, Canada | Maintenance inspection completed |
| | | | Recommended maintenance performed 32,000 kilometer service performed |
| | | | Wiper(s) replaced |
| | | | Brake fluid checked |
| | | | Brakes checked |
| | | | Drive belts checkedBody electrical system checked |
| | | | Antifreeze/coolant checked |
| | | | Exhaust system checked |
| | | | Fuel system checked |
| | | | Exterior lights checked |
| | | | Wipers/washers checked |
| | | | Hood operation checkedHorns checked |
| | | | Parking brake system checked |
| | | | Power steering checked |
| | | | Driveshaft checked |
| | | | Seatbelts checkedSteering/suspension checked |
| | | | Tire condition and pressure checked |
| | | | Instrument cluster checked |
| | | | Fluids checked |
| | | | Windshield washer checked |
| | | | Battery servicedBody lubricated |
| | | | Steering/suspension lubricated |
| | | | Front brake rotor(s) replaced |
| | | | Front brake pads replaced |
| | | | Rear brakes replaced Wheels shocked |
| | | | Wheels checkedAir filter replaced |
| | | | Oil and filter changed |
| | | | Maintenance reminder reset |
| | | | Drivability/performance checked |
| | | | Computer(s) checkedCabin air filter replaced/cleaned |

SALVR2BG5FH966168

| | ODOMETER | SOURCE | DETAILS | | |
|--|-----------|--|---|--|--|
| 2017 Feb 22 | 35,888 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Vehicle serviced Computer reprogrammed Tire repaired | | |
| 2018 Mar 6 | 50,601 KM | Jaguar Land Rover Metro West Etobicoke, Ontario, Canada | Vehicle serviced Tire(s) balanced Four tires balanced Computer(s) checked Power window computer/module replaced | | |
| 2019 Feb 14 | 66,717 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Vehicle serviced • Maintenance inspection completed • Recommended maintenance performed • Battery replaced • Two wheel alignment performed • Alignment checked • Brake fluid checked • Brake fluid checked • Drive belts checked • Drive belts checked • Antifreeze/coolant checked • Fuel system checked • Fuel system checked • Klipers/washers checked • Hood operation checked • Hood operation checked • Horns checked • Parking brake system checked • Power steering checked • Driveshaft checked • Driveshaft checked • Steering/suspension checked • Tire condition and pressure checked • Steering/suspension lubricated • Body lubricated • Steering/suspension lubricated • Oil and filter changed • Rear brakes replaced • Air filter replaced • Maintenance reminder reset • Drivability/performance checked • Steering gear replaced | | |
| 2019 Nov 8 80,688 KM Grand Touring Automobiles Toronto, Ontario, Canada | | | Vehicle serviced • Maintenance inspection completed • Recommended maintenance performed • Vehicle washed/detailed • Brake fluid checked • Brakes checked • Body electrical system checked • Exhaust system checked • Fuel system checked • Wipers/washers checked • Parking brake system checked • Power steering checked • Driveshaft checked • Steering/suspension checked • Tire condition and pressure checked • Tire condition and pressure checked • Fluids checked • Windshield washer checked | | |

SALVR2BG5FH966168

| | ODOMETER | SOURCE | DETAILS | | |
|-------------|------------|---------------------------|---|--|--|
| | | | Steering/suspension lubricated | | |
| | | | Oil and filter changed | | |
| | | | Floor mats installed | | |
| | | | Wheels checked | | |
| | | | Maintenance reminder reset | | |
| | | | Drivability/performance checked | | |
| | | | Computer(s) checked | | |
| | | | Cabin air filter replaced/cleaned | | |
| 2020 Jul 3 | 89,599 KM | Sisca`s Auto Service | Vehicle serviced | | |
| 5 | · | Toronto, Ontario, Canada | Tire repaired | | |
| 2020 Jul 6 | 90,069 KM | Grand Touring Automobiles | Vehicle serviced | | |
| 2020 Jul 0 | 50,005 100 | | | | |
| | | Toronto, Ontario, Canada | Maintenance inspection completed Decommonded maintenance performed | | |
| | | | Recommended maintenance performed Brake fluid checked | | |
| | | | Brake fluid checked Brakes checked | | |
| | | | | | |
| | | | Body electrical system checked Exhaust system checked | | |
| | | | Exhaust system checked Evel system checked | | |
| | | | Fuel system checked Exterior lights checked | | |
| | | | Exterior lights checked Wipers/washers checked | | |
| | | | Wipers/wasners checked Horns checked | | |
| | | | | | |
| | | | Parking brake system checked Power steering checked | | |
| | | | Power steering checked Driveshaft checked | | |
| | | | | | |
| | | | Steering/suspension checkedTire condition and pressure checked | | |
| | | | The condition and pressure checked Instrument cluster checked | | |
| | | | Instrument cluster checked Fluids checked | | |
| | | | Fluids checked Windshield washer checked | | |
| | | | | | |
| | | | Steering/suspension lubricated Oil and filter changed | | |
| | | | Oil and filter changed Pear brakes replaced | | |
| | | | Rear brakes replaced Wheels checked | | |
| | | | Wheels checked Maintenance reminder reset | | |
| | | | | | |
| | | | Drivability/performance checked Computer(c) checked | | |
| | | | Computer(s) checkedCabin air filter replaced/cleaned | | |
| 2020 Jul 16 | 90,498 KM | Sisca`s Auto Service | Vehicle serviced | | |
| 5 | , | Toronto, Ontario, Canada | Tire repaired | | |
| 2020 Sep 10 | 94,486 KM | Grand Touring Automobiles | Vehicle serviced | | |
| · | | Toronto, Ontario, Canada | | | |
| 2020 Sep 24 | 95,186 KM | Grand Touring Automobiles | Vehicle serviced | | |
| | · | Toronto, Ontario, Canada | | | |
| 2021 Oct 18 | 112,191 KM | Grand Touring Automobiles | Vehicle serviced | | |
| | , | Toronto, Ontario, Canada | Maintenance inspection completed | | |
| | | Toronto, Ontario, Canada | Recommended maintenance performed | | |
| | | | Front brake pads replaced | | |
| | | | · · · · · · · · · · · · · · · · · · · | | |
| | | | Brake fluid checked | | |
| | | | Brake fluid checked Brakes checked | | |
| | | | Brakes checked | | |
| | | | Brakes checkedBody electrical system checked | | |
| | | | Brakes checkedBody electrical system checkedExhaust system checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked Parking brake system checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked Parking brake system checked Power steering checked Driveshaft checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked Parking brake system checked Power steering checked Driveshaft checked Steering/suspension checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked Parking brake system checked Power steering checked Driveshaft checked | | |
| | | | Brakes checked Body electrical system checked Exhaust system checked Fuel system checked Exterior lights checked Wipers/washers checked Horns checked Parking brake system checked Power steering checked Driveshaft checked Steering/suspension checked Tire condition and pressure checked | | |

| | ODOMETER | SOURCE | DETAILS | |
|------------|------------|---------------------------|-----------------------------------|--|
| | | | Steering/suspension lubricated | |
| | | | Oil and filter changed | |
| | | | Rear brake pads replaced | |
| | | | Wheels checked | |
| | | | Maintenance reminder reset | |
| | | | Drivability/performance checked | |
| | | | Computer(s) checked | |
| | | | Cabin air filter replaced/cleaned | |
| 2022 May 7 | 121,758 KM | Grand Touring Automobiles | Vehicle serviced | |
| - | | Toronto, Ontario, Canada | | |

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact LAND ROVER or visit Land Rover's website.

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|-----------|---|------------------|--|
| 2014 Aug 1 | | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2015 Feb 10 | | Police Reported Accident Ontario, Canada | Police Report | Accident Reported: moderate damage Vehicle involved in a sideswipe collision with another motor vehicle Damage to right side |
| 2015 Mar 5 | 9,233 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2015 Mar 19 | | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2015 May 31 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2015 Aug 24 | 15,329 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2015 Sep 23 | 16,623 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Jan 19 | 21,585 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |

| | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|------------|--|------------------|---|
| 2016 Feb 17 | 21,725 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Mar 21 | 22,515 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Apr 7 | 23,084 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Oct 31 | 31,714 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Feb 22 | 35,888 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 May 31 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2018 Mar 6 | 50,601 KM | Jaguar Land Rover Metro West Etobicoke, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Feb 14 | 66,717 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 May 31 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2019 Nov 8 | 80,688 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jul 3 | 89,599 KM | Sisca`s Auto Service Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jul 6 | 90,069 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jul 16 | 90,498 KM | Sisca`s Auto Service Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Sep 10 | 94,486 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Sep 24 | 95,186 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 Aug 25 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as brown |
| 2021 Oct 18 | 112,191 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2022 May 7 | 121,758 KM | Grand Touring Automobiles Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2023 Nov 11 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |



@Attribute.Encode(CARFAX Canada One Owner™ Badge)

Attribute.Encode(The CARFAX Canada One Owner[™] badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registrated in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEL)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and Its source data providers or bere liable, but no responsibility is assumed by CARFAX Canada providers or the signets for any errors, inaccuracies or omissions as there is basis, and CARFAX Canada and its source data providers or the support or its contents. Neither CARFAX Canada nor any of its source data providers or provides report or its contents. Neither CARFAX Canada nor any of its source data providers or provides regording this report or its contents. Neither CARFAX Canada nor any of its source data providers or shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including provider or for any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions of Use and any CARFAX canada and User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

