

2007 TOYOTA CAMRY CE

Sedan | 4 Cylinders | Gas

4T1BE46K17U091109

Country of Assembly: United States

Last Reported Odometer: 172,459 KM

No Reported Accidents™ >



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



19 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of October 06, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

| DATE | ODOMETER | SOURCE | DETAILS |
|-------------|------------|--|---|
| 2010 Nov 16 | 74,358 KM | DPD Auto Ctr Inc Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completed |
| 2014 Aug 5 | 105,092 KM | D & D Auto Service Ltd. Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Recommended maintenance performedCooling system checkedDrive belt(s) replacedEngine cleanedSerpentine belt replacedWater pump replaced |
| 2015 Aug 19 | | Krown Kingston Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Undercoating/rustproofing applied |
| 2016 Jan 11 | 114,263 KM | Action Auto Service Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Front brake pads replacedRear brake pads replaced |
| 2016 Nov 17 | | Krown Kingston Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Undercoating/rustproofing applied |
| 2017 Aug 23 | 125,292 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Oil and filter changed |
| 2017 Aug 28 | 125,464 KM | Action Auto Service Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Brakes servicedFront brake pads replaced |
| 2017 Oct 20 | 128,313 KM | Speedy Auto Service Kingston, Ontario, Canada | Vehicle serviced |
| 2018 Feb 2 | 130,437 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Air filter checkedAntifreeze/coolant checkedOil and filter changed |
| 2018 Sep 11 | 135,590 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none">Oil and filter changed Vehicle serviced <ul style="list-style-type: none">Emissions system serviced |

| ODOMETER | SOURCE | DETAILS |
|-------------|---|---|
| 2019 Feb 13 | 139,184 KM Midas Auto Service Experts Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Windshield washer checked |
| 2019 Jul 12 | 144,266 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed |
| 2020 Jun 16 | 150,483 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Air filter replaced Oil and filter changed |
| 2021 Aug 20 | 156,285 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Cabin air filter replaced/cleaned Fluids checked Oil and filter changed Vehicle washed/detailed |
| 2021 Sep 30 | 157,140 KM Speedy Auto Service Kingston, Ontario, Canada | Vehicle serviced |
| 2021 Dec 1 | 157,778 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed |
| 2023 Apr 18 | 161,572 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Antifreeze/coolant checked Cabin air filter checked Drain plug gasket replaced Fluids checked Oil and filter changed Radiator checked Vehicle washed/detailed |
| 2024 Jan 10 | 168,136 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Air filter replaced Drain plug gasket replaced Fluids checked Fuel injection system checked Oil and filter changed Radiator checked Vehicle washed/detailed |
| 2025 Apr 13 | 172,459 KM Great Canadian Oil Change Kingston, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Antifreeze/coolant checked Fluids checked Oil and filter changed Radiator checked Vehicle washed/detailed |



Open Recalls

Recall #: CAN011 | 011 - Remedy Notice - Certain 2007-2010 model year Camry vehicles - Pedal Modification, Floor Modification and Brake Override

Recall Date: 2010
Mar 05

Recall Description

The condition involves the potential risk for the accelerator pedal to get stuck in the wide open position due to an unsecured or incompatible drivers floor mat. A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death. Toyota Canada has confirmed that the potential risk for accelerator pedal entrapment due to an incompatible or unsecured drivers side floor mat in vehicles included in the safety improvement is not due to a vehicle defect. It has also been determined that genuine Toyota Canada drivers side all weather

floor mats sold and distributed by Toyota Canada for the affected vehicles are compatible with the specific vehicle model for which the floor mat was designed and intended to be used. Also, when the correct Toyota drivers side all-weather floor mat is properly secured using the retaining clips provided with the vehicle and installed following the proper installation instructions, there is no risk of pedal entrapment.

Remedy

To help avoid the risk that an unsecured or incompatible drivers floor mat can interfere with the accelerator pedal on your vehicle, any Toyota dealer will provide certain vehicle improvements for your vehicle. The improvements will involve modification to both the accelerator pedal and the floor surface in the drivers foot-well. As an additional measure, independent of the vehicle-based improvements indicated above, Toyota will also install a newly designed brake override system in your vehicle to provide an extra measure of confidence. This system will cut engine power in case of simultaneous application of both accelerator and brake pedals at certain speeds and driving conditions.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit [Toyota's website](https://www.toyota.ca/toyota/en/owners/recalls). (<https://www.toyota.ca/toyota/en/owners/recalls>)

Recall #: CAN177 | 177 - Remedy Notice - Certain 2007-2009 MY Yaris, RAV4, Tundra, Camry/HV, Sequoia, Highlander/HV, Corolla, Matrix vehicles - Power Window Master Switch

Recall Date: 2012 Oct 10

Recall Description

The Power Master Switch (PWMS), located on the drivers door, controls the windows for the driver and passengers. Over time, the sliding electrical contact module in the drivers side PWMS may experience a notchy or sticking feeling during operation due to uneven application of a grease lubricant to certain switch components.

Remedy

Any Toyota dealership will inspect the PWMS and apply a specialized grease. The electrical circuit board for the PWMS may be replaced if your dealership determines it requires replacement during the inspection.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit [Toyota's website](https://www.toyota.ca/toyota/en/owners/recalls). (<https://www.toyota.ca/toyota/en/owners/recalls>)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|----------|--|------------------|---|
| 2007 Jan 6 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed First Owner Reported Vehicle colour noted as red |
| 2007 Sep 11 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2008 Sep 6 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2010 Mar 5 | | TOYOTA | Recall | Manufacturer Recall Issued Recall # CAN011 |
| 2010 Sep 7 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |

| | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|------------|---|------------------|---|
| 2010 Nov 16 | 74,358 KM | DPD Auto Ctr Inc Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2011 Mar 29 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as red |
| 2011 Nov 19 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2012 Oct 10 | | TOYOTA | Recall | Manufacturer Recall Issued Recall # CAN177 |
| 2012 Nov 19 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2013 Nov 19 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2014 Aug 5 | 105,092 KM | D & D Auto Service Ltd. Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2014 Nov 19 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2015 Aug 19 | | Krown Kingston Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Jan 11 | 114,263 KM | Action Auto Service Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Nov 17 | | Krown Kingston Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Nov 19 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2017 Aug 23 | 125,292 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Aug 28 | 125,464 KM | Action Auto Service Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Oct 20 | 128,313 KM | Speedy Auto Service Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2018 Feb 2 | 130,437 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2018 Sep 11 | 135,590 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Feb 13 | 139,184 KM | Midas Auto Service Experts Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Jul 12 | 144,266 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2020 Jun 16 | 150,483 KM | Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |

| ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|--|------------------|---|
| 2020 Nov 19 | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as red |
| 2021 Aug 20 | 156,285 KM Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 Sep 30 | 157,140 KM Speedy Auto Service Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 Dec 1 | 157,778 KM Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2022 Nov 19 | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as red |
| 2023 Apr 18 | 161,572 KM Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2024 Jan 10 | 168,136 KM Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |
| 2024 Nov 19 | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2025 Apr 13 | 172,459 KM Great Canadian Oil Change Kingston, Ontario, Canada | Service Record | Vehicle serviced |



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

