



2018 FORD EXPLORER POLICE INTERCEPTOR

Sport utility vehicle | 6 Cylinders | Gas 1FM5K8AR1JGC57488 Country of Assembly: United States Last Reported Odometer: 212,086 KM





Last Registered In: Ontario (Normal)



0 Service Records Found







1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 28, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



🥌 Accident/Damage



There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2024 May 9	Ottawa, Ontario, Canada	
	Auction Announcement: AUCTION ANNOUNCED AS STRUCTURAL DAMAGE	



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Open Recalls

Recall #: 24S02 | EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION Recall Date: 2024 Jan 23

Recall Description

IN SOME OF THE AFFECTED VEHICLES IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPAIR ANY LOOSE OR MISSING EXTERIOR A-PILLAR TRIM MOLDINGS FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Sep 9		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		First Owner Reported
				Vehicle colour noted as white
2021 Jun 1		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Fleet
				Vehicle colour noted as white
2022 Jun 1		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Fleet
				Vehicle colour noted as white
2024 Jan 23		FORD	Recall	Manufacturer Recall Issued
				Recall # 24S02
2024 May 9		Auto Auction	Auction Announcement	AUCTION ANNOUNCED AS
		Ottawa, Ontario, Canada		PREVIOUS POLICE VEHICLE
2024 May 9	212,086 KM	Auto Auction	Auction Announcement	AUCTION ANNOUNCED AS
		Ottawa, Ontario, Canada		STRUCTURAL DAMAGE
2024 May 15		Motor Vehicle Dept.	Canadian Renewal	New Owner reported
		Ontario, Canada		Vehicle colour noted as white



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Set this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

