



Vehicle History Report #: 60608413
Report Date: April 9, 2025 | 5:02 p.m. EDT
Report Status: Complete

2015 TOYOTA SIENNA LE

Van passenger | 6 Cylinders | Gas
5TDJK3DC9FS124651
Country of Assembly: United States
Last Reported Odometer: 225,352 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



52 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 09, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5TDJK3DC9FS124651

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2017 Nov 16	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage with another motor vehicle Damage to left rear Claim: Other Damage	\$0.00
2023 Mar 2	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage with another motor vehicle Damage to left front	

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2016 Apr 24	Ontario, Canada	
	Damage Event: Accident reported Vehicle involved in a rear-end collision Damage to rear	
2016 Jun 3	n/a	
	Damage Event: Damage repairs performed Repairs to rear	



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

***We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Jan 12	2,409 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Tire condition and pressure checked

	ODOMETER	SOURCE	DETAILS
2016 Apr 19	13,913 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire condition and pressure checked
2016 Jul 19	24,308 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Lights checked
2016 Aug 2	26,058 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2016 Aug 19	28,221 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2016 Nov 18	34,142 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2017 Feb 6	38,372 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2017 Apr 25	46,813 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2017 Jun 1	51,494 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2017 Oct 5	63,114 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2017 Nov 16	68,301 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2017 Dec 22	72,984 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2018 Jan 5	73,185 KM	Service Facility	Vehicle serviced
2018 Apr 9	83,593 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Brake pads replaced Brake rotor(s) replaced Brakes serviced Front brake pads replaced Front brake rotor(s) replaced Oil and filter changed Rear brake pads replaced
2018 May 3	84,491 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Four tires balanced Four tires mounted Tire condition and pressure checked Tire(s) replaced
2018 Jun 21	89,077 KM	Service Facility	Vehicle serviced
2018 Sep 5	93,976 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Air system checked

ODOMETER		SOURCE	DETAILS
			<ul style="list-style-type: none"> Oil and filter changed
2018 Oct 29	99,256 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire(s) balanced Tire(s) mounted Tire(s) replaced
2018 Dec 10	103,407 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Brakes serviced Front brakes serviced Oil and filter changed Tire condition and pressure checked Tires rotated Wiper(s) replaced
2019 Jan 26	105,876 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Brakes checked
2019 Jan 29		CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brake pads replaced Brakes serviced Rear brake pads replaced
2019 Feb 28	107,665 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Charcoal/vapor canister replaced Fuel system checked Wipers/washers checked Wiper(s) replaced
2019 Apr 12	109,812 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire(s) balanced Tire(s) mounted Tire(s) replaced
2019 Jun 26	114,553 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air system checked Air filter replaced Cabin air filter replaced/cleaned Oil and filter changed Tire condition and pressure checked Tires rotated
2019 Aug 16	114,642 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Battery/charging system checked Electrical system checked Ignition system checked
2019 Sep 18	115,622 KM	Service Facility	Vehicle serviced
2019 Oct 7	116,792 KM	Active Green & Ross Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked

	ODOMETER	SOURCE	DETAILS
2019 Nov 13	125,059 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire condition and pressure checked • Tire(s) balanced • Tire(s) mounted • Tire(s) replaced
2020 Feb 10	127,475 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
2020 May 26	129,512 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Tire condition and pressure checked
2020 Jun 3	129,518 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Tire(s) changed
2020 Nov 2	134,858 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Air system checked • Air filter replaced • Brakes checked • Brake pads replaced • Brake rotor(s) replaced • Brakes serviced • Four wheel alignment performed • Front brake pads replaced • Front brake rotor(s) replaced • Front strut(s) replaced • Oil and filter changed • Rear brake pads replaced • Serpentine belt replaced • Steering/suspension checked • Sway bar link(s) replaced • Tire condition and pressure checked • Tire(s) balanced • Tire(s) mounted • Tire(s) replaced
2021 Mar 4	136,089 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire condition and pressure checked • Tire repaired
2021 Apr 14	138,165 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Tire condition and pressure checked • Tire(s) balanced • Tire(s) mounted • Tire(s) replaced
2021 Aug 27	146,516 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Cabin air filter replaced/cleaned • Oil and filter changed • Tire condition and pressure checked • Tires rotated
2021 Sep 20	147,255 KM	Service Facility	Vehicle serviced
2021 Nov 18	150,908 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tire condition and pressure checked • Tire(s) balanced • Tire(s) mounted • Tire(s) replaced

	ODOMETER	SOURCE	DETAILS
2022 Mar 3	153,554 KM	CRS Automotive Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire repaired
2022 Apr 5	154,782 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire condition and pressure checked
2022 Sep 1	166,189 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Brakes checked
2022 Nov 1	170,079 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire condition and pressure checked
2023 Apr 17	178,431 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire condition and pressure checked
2023 Oct 24	182,805 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2024 Mar 1	189,475 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Air system checked Air filter replaced Cabin air filter replaced/cleaned Oil and filter changed
2024 Mar 15	191,496 KM	Midas London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Brakes checked Brake calipers cleaned/serviced Four wheel alignment performed Steering/suspension checked
2024 Apr 8	193,424 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2024 May 14	198,772 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2024 Aug 30	210,026 KM	Take 5 Oil Change London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2024 Nov 4	217,844 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2024 Nov 22	219,989 KM	Midas London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery replaced Ignition system checked
2025 Jan 14	224,389 KM	Take 5 Oil Change Milton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Wiper(s) replaced
2025 Jan 23	225,352 KM	Midas London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Steering/suspension checked Tire condition and pressure checked



Open Recalls

5TDJK3DC9FS124651

✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact TOYOTA or visit [Toyota's website](https://www.toyota.ca/toyota/en/owners/recalls). (https://www.toyota.ca/toyota/en/owners/recalls)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Nov 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as gray
2016 Jan 12	2,409 KM	Service Facility	Service Record	Vehicle serviced
2016 Apr 19	13,913 KM	Service Facility	Service Record	Vehicle serviced
2016 Apr 24		Ontario, Canada	Damage Event	Accident Reported: <ul style="list-style-type: none">Vehicle involved in a rear-end collisionDamage to rear
2016 Jun 3			Damage Event	Damage repairs performed Repairs to rear
2016 Jul 19	24,308 KM	Service Facility	Service Record	Vehicle serviced
2016 Aug 2	26,058 KM	Service Facility	Service Record	Vehicle serviced
2016 Aug 19	28,221 KM	Service Facility	Service Record	Vehicle serviced
2016 Nov 18	34,142 KM	Service Facility	Service Record	Vehicle serviced
2017 Feb 6	38,372 KM	Service Facility	Service Record	Vehicle serviced
2017 Apr 25	46,813 KM	Service Facility	Service Record	Vehicle serviced
2017 Jun 1	51,494 KM	Service Facility	Service Record	Vehicle serviced
2017 Oct 5	63,114 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 16		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none">minor damagewith another motor vehicleDamage to left rear
2017 Nov 16		Insurance Records Ontario, Canada		
2017 Nov 16	68,301 KM	Service Facility	Service Record	Vehicle serviced

5TDJK3DC9FS124651

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Dec 22	72,984 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 5	73,185 KM	Service Facility	Service Record	Vehicle serviced
2018 Apr 9	83,593 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 May 3	84,491 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jun 21	89,077 KM	Service Facility	Service Record	Vehicle serviced
2018 Sep 5	93,976 KM	Service Facility	Service Record	Vehicle serviced
2018 Oct 29	99,256 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 10	103,407 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 26	105,876 KM	Service Facility	Service Record	Vehicle serviced
2019 Jan 29		CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Feb 28	107,665 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 12	109,812 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 26	114,553 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 16	114,642 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 18	115,622 KM	Service Facility	Service Record	Vehicle serviced
2019 Oct 7	116,792 KM	Active Green & Ross Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 13	125,059 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 10	127,475 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 May 26	129,512 KM	Service Facility	Service Record	Vehicle serviced
2020 Jun 3	129,518 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 2	134,858 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Mar 4	136,089 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 14	138,165 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Aug 27	146,516 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 20	147,255 KM	Service Facility	Service Record	Vehicle serviced
2021 Nov 18	150,908 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 3	153,554 KM	CRS Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 5	154,782 KM	Service Facility	Service Record	Vehicle serviced
2022 Sep 1	166,189 KM	Service Facility	Service Record	Vehicle serviced
2022 Nov 1	170,079 KM	Service Facility	Service Record	Vehicle serviced
2023 Mar 2		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • moderate damage • with another motor vehicle • Damage to left front
2023 Apr 17	178,431 KM	Service Facility	Service Record	Vehicle serviced
2023 Oct 24	182,805 KM	Service Facility	Service Record	Vehicle serviced
2024 Mar 1	189,475 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2024 Mar 15	191,496 KM	Midas London, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 8	193,424 KM	Service Facility	Service Record	Vehicle serviced
2024 May 14	198,772 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 30	210,026 KM	Take 5 Oil Change London, Ontario, Canada	Service Record	Vehicle serviced
2024 Nov 4	217,844 KM	Service Facility	Service Record	Vehicle serviced
2024 Nov 22	219,989 KM	Midas London, Ontario, Canada	Service Record	Vehicle serviced
2025 Jan 14	224,389 KM	Take 5 Oil Change Milton, Ontario, Canada	Service Record	Vehicle serviced
2025 Jan 23	225,352 KM	Midas London, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

