



Hatchback | 4 Cylinders | Gas JM1BL1H59A1273259 Country of Assembly: Japan Last Reported Odometer: 156,721 KM



(i)



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 12, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
() 2011 Jun 19	Ontario, Canada	
	Glass Record	\$113.00

Registration

🕑 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Dec 31	50,722 KM	Wilson`s Service Centre	Vehicle serviced
		Guelph, Ontario, Canada	Oil and filter changed
			• Wiper(s) replaced
2015 Dec 28	69,784 KM	Meineke Car Care Center	Vehicle serviced
		Georgetown, Ontario, Canada	
2016 Mar 17	72,192 KM	Bratin Auto/Muffler LTD	Vehicle serviced
		Georgetown, Ontario, Canada	Maintenance inspection completed
		,,,,	Oil and filter changed
			Tire(s) replaced

2019 Jan 4	96,911 KM	Meineke Car Care Center	Vehicle serviced
		Georgetown, Ontario, Canada	Maintenance inspection completed
			Air filter checked
			Battery/charging system checked
			Drive belts checked
			Engine/powertrain computer/module checked
			Exhaust system checked
			Fluids checked
			Lens replaced
			Oil and filter changed
			Parking brake system checked
			 Tire condition and pressure checked
			Window(s) checked
			Wipers/washers checked
2040 4 42			
2019 Aug 13	104,841 KM	Bratin Auto/Muffler LTD	Vehicle serviced
		Georgetown, Ontario, Canada	Brakes checked
		-	Brakes serviced
			Front brake pads replaced
			Front brake rotor(s) replaced
2020 Jan 2	100 862 KM	Bratin Auto/Muffler LTD	Vehicle serviced
2020 Jan 3	109,862 KM	Georgetown, Ontario, Canada	Shock absorber(s) replaced
2021 Jun 29	113,439 KM	Bratin Auto/Muffler LTD	Vehicle serviced
		Georgetown, Ontario, Canada	Maintenance inspection completed
		5	Brake pads replaced
			Brakes serviced
			Drive belt(s) replaced
			Drive belts checked
			Fluids checked
			Front brake pads replaced
			 Front brake rotor(s) replaced
			Oil and filter changed
			Rear brake pads replaced
			 Rear brake rotor(s) replaced
			Serpentine belt replaced
			Tire(s) changed
			Tire(s) mounted
2021 Dec 20	119 422 KM	Pratin Auto Muffler LTD	Vehicle serviced
2021 Dec 29	118,422 KM	Bratin Auto/Muffler LTD	
		Georgetown, Ontario, Canada	Maintenance inspection completed
			 Drive belt(s) replaced
			Drive belts checked
			Fluids checked
			Oil and filter changed
			Serpentine belt replaced
			Tire(s) changed
			Two wheel alignment performed
2023 Jul 21	137,615 KM	HASSELL AUTOMOTIVE SALES AND	Vehicle serviced
		SERVICE	Catalytic converter replaced
			Emission system checked
		Georgetown, Ontario, Canada	Exhaust system checked
			-
			Exhaust pipe replaced
			Exhaust pipe replaced Exhaust repaired
			 Exhaust pipe replaced Exhaust repaired Oil and filter changed
			Exhaust repairedOil and filter changed
2024 Mar 26	146,119 KM	Bratin Auto/Muffler LTD	Exhaust repaired Oil and filter changed Vehicle serviced
2024 Mar 26	146,119 KM	Bratin Auto/Muffler LTD Georgetown, Ontario, Canada	Exhaust repaired Oil and filter changed Vehicle serviced Brakes checked
2024 Mar 26	146,119 KM		 Exhaust repaired Oil and filter changed Vehicle serviced Brakes checked Brake fluid flushed/changed
2024 Mar 26	146,119 KM		Exhaust repaired Oil and filter changed Vehicle serviced Brakes checked
	· · · · · · · · · · · · · · · · · · ·	Georgetown, Ontario, Canada	 Exhaust repaired Oil and filter changed Vehicle serviced Brakes checked Brake fluid flushed/changed Brakes serviced Rear brake caliper(s) replaced
2024 Mar 26 2024 Dec 6	146,119 KM 153,390 KM	Georgetown, Ontario, Canada Master Mechanic Georgetown	 Exhaust repaired Oil and filter changed Vehicle serviced Brakes checked Brake fluid flushed/changed Brakes serviced Rear brake caliper(s) replaced Vehicle serviced
	· · · · · · · · · · · · · · · · · · ·	Georgetown, Ontario, Canada	 Exhaust repaired Oil and filter changed Vehicle serviced Brakes checked Brake fluid flushed/changed Brakes serviced Rear brake caliper(s) replaced

	ODOMETER	SOURCE	DETAILS	
			Fluids checked	
			Four tires balanced	
			Oil and filter changed	
			One wheel replaced	
			Tire(s) balanced	
			Tire(s) changed	
			Wheel bearing(s)/hub(s) replaced	
2025 Apr 3	156,721 KM	Master Mechanic Georgetown	Vehicle serviced	
		Georgetown, Ontario, Canada	Four tires balanced	
		5, , ,	 Four wheel alignment performed 	
			 Rear shock absorber(s) replaced 	
			Steering/suspension checked	
			Tire(s) balanced	
			Tire(s) changed	

Open Recalls

Recall #: 9916H | LIFTGATE STAY DAMPER CONCERN Recall Date: 2016 Sep 09

Recall Description

Insufficient corrosion protective coating was applied to the ends of the external cylinders of the rear hatch/lift gate gas stay dampers (lift supports). If water containing road salt enters, it can cause corrosion. Over time, increased corrosion may eventually cause it to break as the rear hatch or lift gate is opened.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MAZDA or visit Mazda's website. (https://www.mazda.ca/en/owners/recalls/)

Recall #: 0917B | SEAT LIFTER LINK CONCERN Recall Date: 2017 Mar 01

Recall Description

On the driver seat, due to insufficient strength of the seat height adjustment lifter link, or, due to inadequate attachment method of the lifter link push nuts, the lifter link may become cracked or the push nuts may become separated.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MAZDA or visit Mazda's website. (https://www.mazda.ca/en/owners/recalls/)

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Feb 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as gray
2011 Mar 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2011 Jun 19		Insurance Records Ontario, Canada	Glass Record	\$113.00
2013 Mar 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Dec 14	50,000 KM	Independent Source Guelph, Ontario, Canada	Odometer reading	
2013 Dec 31	50,722 KM	Wilson`s Service Centre Guelph, Ontario, Canada	Service Record	Vehicle serviced
2014 Jan 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2015 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Dec 28	69,784 KM	Meineke Car Care Center Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2016 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Mar 17	72,192 KM	Bratin Auto/Muffler LTD Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 9		MAZDA	Recall	Manufacturer Recall Issued Recall # 9916H
2017 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Mar 1		MAZDA	Recall	Manufacturer Recall Issued Recall # 0917B
2018 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jan 4	96,911 KM	Meineke Car Care Center Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 13	104,841 KM	Bratin Auto/Muffler LTD Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 3	109,862 KM	Bratin Auto/Muffler LTD	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Jun 29	113,439 KM	Bratin Auto/Muffler LTD Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 29	118,422 KM	Bratin Auto/Muffler LTD Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2022 Feb 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2023 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Jul 21	137,615 KM	HASSELL AUTOMOTIVE SALES AND SERVICE Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2024 Mar 26	146,119 KM	Bratin Auto/Muffler LTD Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2024 Jul 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Dec 6	153,390 KM	Master Mechanic Georgetown Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2025 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Apr 3	156,721 KM	Master Mechanic Georgetown Georgetown, Ontario, Canada	Service Record	Vehicle serviced
2025 Jun 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents^M badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and Its source data providers receive data and information mexternal sources believed to be reliable, but no responsibility is assumed by CARFAX Canada and providers or the information or may nerors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including provider a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions of Use and any CARFAX canada fuel User Licence Agreements as each may be amended from time to time by CARFAX canada.

© 2025 CARFAX Canada ULC. All rights reserved.

