


2014 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas 5N1AR2MM1EC707824 Country of Assembly: United States Last Reported Odometer: 112,191 KM



(i)



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 05, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



실 Accident/Damage

There are no accidents/damage reported on this vehicle.

Registration

🥑 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Jul 30		Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	
2014 Sep 4	4,999 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	
2014 Nov 22		Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	
2015 Feb 7	6,527 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	
2015 Mar 20	8,636 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	Air filter checked
			Oil and filter changed
			Rear wiper motor replaced
2015 Nov 21	25,888 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	Tire condition and pressure checked
2016 Apr 23	33,062 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	Air filter checked
			Oil and filter changed
2016 Nov 29	47,152 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	Air filter checked
			Air filter replaced
			Cabin air filter replaced/cleaned
			Oil and filter changed
			 Rear brake pads replaced Tire condition and pressure checked
			 Transmission computer/module reprogrammed
2017 May 4	53,025 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	

	ODOMETER	SOURCE	DETAILS
2017 Jul 4	57,074 KM	401 Dixie Nissan	Vehicle serviced
		Mississauga, Ontario, Canada	Maintenance inspection completed
2017 Nov 28	67,137 KM	401 Dixie Nissan	Vehicle serviced
		Mississauga, Ontario, Canada	Maintenance inspection completed
2018 Mar 29	72,044 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	Battery serviced
		-	Cabin air filter replaced/cleaned
			Oil and filter changed
2018 Apr 21	72,910 KM	Alta Nissan Woodbridge	Vehicle serviced
		Woodbridge, Ontario, Canada	
2020 May 26	94,848 KM	Agincourt Infiniti Nissan	Vehicle serviced
		Scarborough, Ontario, Canada	Maintenance inspection completed
		5	Intercooler checked
			Transaxle replaced
			Transmission checked
			Transmission computer/module reprogrammed
2022 Mar 3	104,083 KM	VILLAGE NISSAN	Vehicle serviced
		Markham, Ontario, Canada	Maintenance inspection completed
			Vehicle washed/detailed
2023 Aug 17	112,191 KM	VILLAGE NISSAN	Vehicle serviced
-		Markham, Ontario, Canada	Maintenance inspection completed
		, ,	Vehicle washed/detailed

)) Open Recalls

Recall #: R24C6 | PTH HD LTH FNL RPR NTB25-010 Recall Date: 2025 Feb 10

Recall Description

ON CERTAIN 2013-2016 PATHFINDER VEHICLES, DUST OR DIRT CONTAMINATION MAY ACCUMULATE ON AND AROUND THE SECONDARY LATCH LEVER PIVOT JOINT. OVER TIME, THE BUILD-UP OF CONTAMINATION, COMBINED WITH A LACK OF PROPER INSPECTION AND MAINTENANCE OF THE SECONDARY LATCH (AS DESCRIBED IN THE OWNER S MANUAL), CAN CREATE MECHANICAL BINDING THAT COULD CAUSE THE LEVER TO REMAIN IN THE OPEN POSITION AFTER IT HAS BEEN DISENGAGED. IN ADDITION, THIS CONTAMINATION CAN SCRATCH THE SECONDARY LATCH S PROTECTIVE ANTI-CORROSION COATING, ALLOWING CORROSION OF THE BARE METAL IN THE PIVOT JOINT.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)

Stolen Vehicle Check

This vehicle is not actively declared stolen.



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as white
2014 Jul 30		Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2014 Sep 4	4,999 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2014 Nov 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Nov 22		Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2015 Feb 7	6,527 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2015 Mar 20	8,636 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 21	25,888 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 23	33,062 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Nov 29	47,152 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2017 May 4	53,025 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2017 Jul 4	57,074 KM	401 Dixie Nissan Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 28	67,137 KM	401 Dixie Nissan Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 29	72,044 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 21	72,910 KM	Alta Nissan Woodbridge Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 May 26	94,848 KM	Agincourt Infiniti Nissan Scarborough, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Nov 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2022 Mar 3	104,083 KM	VILLAGE NISSAN Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 May 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2023 Aug 17	112,191 KM	VILLAGE NISSAN Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Nov 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Feb 10		NISSAN	Recall	Manufacturer Recall Issued Recall # R24C6



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents^M badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or ther information or more vehicles, accuracy, merrors, inaccuracies or omission as uncertained sources believed to be reliable, but no responsibility is assumed by CARFAX Canada providers or the is agents for any errors, inaccuracies or omission any or event as uncertained as the reliable, but no responsibility is assumed by CARFAX Canada providers or the signets for any errors, inaccuracies or omission and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including provider or or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about two vehicle that is the subject matter of this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canadas. Conditions of Use and any CARFAX canada and User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2025 CARFAX Canada ULC. All rights reserved.

