

Vehicle History Report #: 39401677
Report Date: May 7, 2022 | 06:28 PM EST
Report Status: Complete




2011 VOLKSWAGEN JETTA TDI

Sedan | 4 Cylinders | Diesel
3VWDL7AJ6BM005340
Country of Assembly: Mexico
Last Reported Odometer: 156,637 KM



Accident/Damage Records Found




Last Registered In:
Ontario (Normal)



11 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of May 07, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

| INCIDENT DATE | DETAILS | AMOUNT |
|---------------|--|--------|
| 2016 Aug 22 | <p>Ontario, Canada</p> <p>Police Reported Accident: Accident reported: moderate damage with another motor vehicle Damage to left side</p> | |



Registration

✓ This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Québec** with **Normal** branding.
- In the province of **Ontario** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

| DATE | ODOMETER | SOURCE | DETAILS |
|-------------|------------|---|--|
| 2012 May 7 | 42,054 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |
| 2012 Aug 28 | 55,028 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |
| 2013 Feb 6 | 66,791 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |
| 2013 Mar 28 | 68,254 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |
| 2013 May 21 | 74,039 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced <ul style="list-style-type: none"> • Recommended maintenance performed • Fuel filter replaced |
| 2013 Jun 17 | 77,689 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |
| 2014 Dec 10 | 99,115 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced <ul style="list-style-type: none"> • Engine/powertrain computer/module checked |
| 2015 Feb 4 | 101,427 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |
| 2015 Jun 19 | 105,499 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Vehicle serviced |

| DATE | ODOMETER | SOURCE | DETAILS |
|------------|------------|--|---|
| 2021 May 3 | 153,660 KM | Kellco Car Care Ottawa, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Exhaust repaired Rear brakes replaced Sway bar link(s) replaced |
| 2021 Jul 6 | 156,637 KM | Kellco Car Care Ottawa, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Wheel speed sensor(s) replaced/repaired |



Open Recalls

Recall #: 23U3 | 2.0L TDI ENGINE (GEN 1) EMISSIONS MODIFICATION Recall Date: 2017 Aug 11

Recall Description

The Environmental Protection Agency and California Air Resources Board have determined that Volkswagen vehicles equipped with a 2.0L 4-cylinder TDI engine do not comply with applicable emissions regulations. The emissions control systems on the vehicles will not control emissions under off-cycle conditions as effectively as during the federal test procedure. The extent of the emissions increase under off-cycle conditions depends upon how the vehicles are driven.

Remedy

Install updated emissions control system parts and software, install a TDI Emissions Modification - Proof of Completion Label and install a Supplemental Vehicle Emissions Control Information Label.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

Recall #: 24CV | SNOW FLAP AND OXYGEN SENSOR Recall Date: 2017 Aug 11

Recall Description

The snow flap in the inlet air box housing may remain partially to fully open. Should this occur, excess warm air could enter the air intake though the snow flap inlet.

Remedy

Install an improved inlet air box housing snow flap and, if measured degradation tolerances are met, replace the oxygen sensor.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

**Stolen Vehicle Check**

This vehicle is not actively declared stolen.

**Detailed History**

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|-----------|---|------------------|--|
| 2010 Oct 8 | | Motor Vehicle Dept. Québec, Canada | Canadian Renewal | Registration Issued or Renewed First Owner Reported |
| 2012 May 7 | 42,054 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2012 Aug 28 | 55,028 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2013 Feb 6 | 66,791 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2013 Mar 28 | 68,254 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2013 May 21 | 74,039 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2013 Jun 17 | 77,689 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2013 Sep 20 | 90,400 KM | Independent Source Rimouski, Québec, Canada | Odometer reading | |
| 2013 Sep 25 | | Motor Vehicle Dept. Québec, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported Previous Use: Commercial |
| 2014 Apr 2 | | Motor Vehicle Dept. Québec, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported Previous Use: Commercial |
| 2014 May 12 | | Motor Vehicle Dept. Québec, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported |
| 2014 Dec 10 | | Motor Vehicle Dept. Québec, Canada | Canadian Renewal | Registration Issued or Renewed |

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|------------|---|------------------|---|
| 2014 Dec 10 | 99,115 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2015 Feb 4 | 101,427 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2015 Jun 19 | 105,499 KM | Volkswagen Rimouski Rimouski, Québec, Canada | Service Record | Vehicle serviced |
| 2015 Nov 3 | | Motor Vehicle Dept. Québec, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported |
| 2016 Jan 21 | 109,776 KM | Independent Source Ottawa, Ontario, Canada | Odometer reading | |
| 2016 Feb 2 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2016 Mar 14 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported |
| 2016 Aug 22 | | Police Reported Accident Ontario, Canada | Police Report | Accident Reported: <ul style="list-style-type: none"> • moderate damage • with another motor vehicle • Damage to left side |
| 2017 Feb 23 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2017 Aug 11 | | VOLKSWAGEN | Recall | Manufacturer Recall Issued Recall # 23U3 |
| 2017 Aug 11 | | VOLKSWAGEN | Recall | Manufacturer Recall Issued Recall # 24CV |
| 2019 Aug 27 | | VOLKSWAGEN | Recall | Manufacturer Recall Issued Recall # 37M2 |
| 2019 Oct 30 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2020 Feb 28 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2021 May 3 | 153,660 KM | Kellco Car Care Ottawa, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 Jun 3 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2021 Jul 6 | 156,637 KM | Kellco Car Care Ottawa, Ontario, Canada | Service Record | Vehicle serviced |



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



[Faint, illegible text from the report body]

Vehicle History Report

Accident/Damage

REPORT DATE: 05/19/22
BY: CARFAX CANADA
© 2022 May 22
CARFAX CANADA

3WDL7AJ6BM005340