



**Vehicle History Report #:** 62695514  
**Report Date:** July 8, 2025 | 3:32 p.m. EDT  
**Report Status:** Complete

## 2016 VOLKSWAGEN BEETLE SE

Hatchback | 4 Cylinders | Gas  
3VWJ07ATXGM616136  
Country of Assembly: Mexico  
Last Reported Odometer: 130,910 KM

No Reported  
Accidents™ >



Glass Records Found



Last Registered In:  
**Ontario (Normal)**



**10 Service Records Found**



No U.S. History Found



**2 Open Recalls Found**



Not Actively Declared Stolen



No Import/Export Records  
Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

3VWJ07ATXGM616136



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 08, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend

**this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report



## Accident/Damage



There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

## Other Damage Records

RECORD DATE	DETAILS	AMOUNT
! 2019 Aug 14	Ontario, Canada	
	Glass Record	\$123.00
! 2022 Apr 19	Ontario, Canada	
	Glass Record	\$131.00



## Registration



This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

**We checked for:** *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Dec 10		Maple Volkswagen Maple, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li><li>Vehicle washed/detailed</li></ul>
2016 Apr 20		Volkswagen Of Windsor Windsor, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li><li>Vehicle washed/detailed</li></ul>
2017 Jan 14	10,314 KM	Volkswagen Villa Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Recommended maintenance performed</li></ul>

2017 Oct 14	24,378 KM	Volkswagen Of Windsor Windsor, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Airbag system checked</li> <li>Brakes checked</li> <li>Cabin air filter replaced/cleaned</li> <li>Exhaust system checked</li> <li>Fluids checked</li> <li>Oil and filter changed</li> <li>Tire condition and pressure checked</li> <li>Tires rotated</li> </ul>
2018 Sep 29	39,725 KM	Volkswagen Of Windsor Windsor, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Recommended maintenance performed</li> <li>Battery/charging system checked</li> <li>Brakes checked</li> <li>Oil and filter changed</li> <li>Tires rotated</li> </ul>
2019 Mar 8		Volkswagen Of Windsor Windsor, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Pre-delivery inspection completed</li> <li>Recommended maintenance performed</li> <li>Air filter replaced</li> <li>Brakes checked</li> <li>Brake calipers cleaned/serviced</li> <li>Brake fluid flushed/changed</li> <li>Cabin air filter replaced/cleaned</li> <li>Fluids checked</li> <li>Front brake pads replaced</li> <li>Front wiper blades/refills replaced</li> <li>Fuel filter replaced</li> <li>Oil and filter changed</li> <li>Safety inspection performed</li> <li>Spark plug(s) replaced</li> <li>Tires rotated</li> <li>Vehicle washed/detailed</li> </ul>
2019 May 31		Volkswagen Of Windsor Windsor, Ontario, Canada	<b>Vehicle serviced</b>
2019 Nov 29	63,999 KM	Valvoline Express Care Chatham, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>
2021 Oct 23	88,083 KM	Great Canadian Oil Change Leamington, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Antifreeze/coolant checked</li> <li>Fluids checked</li> <li>Oil and filter changed</li> </ul>
2025 Mar 2	130,910 KM	Valvoline Express Care Chatham, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>



Open Recalls

Recall #: 37M2 | MICRO SWITCH   Recall Date: 2019 Aug 27

#### Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

#### Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html).  
(<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)

Recall #: 69EM | DRIVER FRONTAL AIRBAG INFLATOR (TAKATA SDI-D)   Recall Date: 2023 Jan 05

#### Recall Description

The drivers side airbag inflator may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling. An inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.

#### Remedy

Replace drivers frontal airbag.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html).  
(<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)



## Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Dec 10		Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 20		Volkswagen Of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2017 Jan 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Jan 14	10,314 KM	Volkswagen Villa Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2017 Oct 14	24,378 KM	Volkswagen Of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 29	39,725 KM	Volkswagen Of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 8		Volkswagen Of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as black
2019 May 31		Volkswagen Of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 14		Insurance Records Ontario, Canada	Glass Record	\$123.00
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued

2019 Nov 29	63,999 KM	Valvoline Express Care Chatham, Ontario, Canada	Service Record	Vehicle serviced
2020 Mar 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Oct 23	88,083 KM	Great Canadian Oil Change Leamington, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 19		Insurance Records Ontario, Canada	Glass Record	\$131.00
2022 Aug 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Jan 5		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 69EM
2024 Mar 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2025 Mar 2	130,910 KM	Valvoline Express Care Chatham, Ontario, Canada	Service Record	Vehicle serviced
2025 Jun 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2025 Jun 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black



## Questions? We're here to help.

Visit us at **support.carfax.ca**

### **CARFAX Canada No Reported Accidents™ Badge**

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

