

Vehicle History Report #: 56641598 Report Date: October 3, 2024 | 2:35 p.m. EDT Report Status: Complete

2013 BMW 328 XI

Sedan | 4 Cylinders | Gas WBA3B3C55DF533882 Country of Assembly: Germany Last Reported Odometer: 217,999 KM





Last Registered In: Ontario (Normal)



21 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found


Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 03, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
① 2018 Sep 15	Claremont, Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	Vehicle involved in a rear-end collision	
	with another motor vehicle	
	Damage to rear	
	Estimate: Rear Center Estimate Date: 2018 Nov 22	\$1,508.72
	Claim: Unknown	\$1,509.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2018 Dec 18	Ontario, Canada	
	Glass Record	\$325.00



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2012 Sep 27		Service Facility	Vehicle serviced	
		Toronto, Ontario, Canada		
2014 Dec 8	49,331 KM	Active Green & Ross	Vehicle serviced	
		Pickering, Ontario, Canada	 Maintenance inspection completed 	
		5.	 Tire repaired 	
			 Tire(s) balanced 	
			 Tire condition and pressure checked 	
			 Four tires balanced 	
			Four tires mounted	
2015 Apr 17	63,221 KM	Active Green & Ross	Vehicle serviced	
		Pickering, Ontario, Canada	Maintenance inspection completed	

	ODOMETER	SOURCE	DETAILS
2015 Dec 11	82,255 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced • Maintenance inspection completed
2016 May 16	90,445 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced • Maintenance inspection completed
2016 Nov 30	102,982 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed
2017 May 10	110,770 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed
2017 Jul 6	114,891 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Brakes serviced • Rear brake pads replaced • Rear brake rotor(s) replaced • Brake pad sensor(s) replaced • Brakes checked
2017 Dec 1	123,916 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2018 Apr 16	129,670 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed
2018 Nov 12	145,879 KM	Active Green & Ross Pickering, Ontario, Canada	Vehicle serviced Maintenance inspection completed Tire repaired Tire(s) replaced Four wheel alignment performed Alignment checked
2019 May 23	155,318 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2019 Nov 27	165,597 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed
2020 Jun 11	171,691 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2020 Nov 23	176,899 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced Maintenance inspection completed Lights checked
2021 Apr 19	181,341 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced • Maintenance inspection completed
2021 Nov 10	186,610 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2022 Nov 30	196,258 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced • Maintenance inspection completed

	ODOMETER	SOURCE	DETAILS	
2023 May 24	204,717 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle servicedMaintenance inspection completedOil and filter changed	
2023 Dec 6	215,931 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed	
2024 Jun 13	217,999 KM	Pickering Auto Lab Pickering, Ontario, Canada	Vehicle serviced • No-start/hard start condition checked	



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact your local BMW Retailer.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Sep 27		Service Facility Toronto, Ontario, Canada	Service Record	Vehicle serviced
2012 Sep 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2012 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2013 Jun 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Aug 25	8,431 KM	Independent Source Thornhill, Ontario, Canada	Odometer reading	
2013 Nov 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2014 Dec 8	49,331 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced
2015 Apr 17	63,221 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced
2015 May 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

O I IVI		OAK AX Gallada Velliole Filstery Reports					
	ODOMETER	SOURCE	RECORD TYPE	DETAILS			
2015 Dec 11	82,255 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2016 May 16	90,445 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2016 Nov 30	102,982 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2017 May 10	110,770 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2017 Jul 6	114,891 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2017 Jul 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal			
2017 Dec 1	123,916 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2018 Apr 16	129,670 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2018 Sep 15		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage Vehicle involved in a rear-end collision with another motor vehicle Damage to rear			
2018 Sep 15		Ontario, Canada	Unknown				
2018 Nov 12	145,879 KM	Active Green & Ross Pickering, Ontario, Canada	Service Record	Vehicle serviced			
2018 Nov 22	146,334 KM	Insurance Records Claremont, Ontario, Canada	Estimate Repair	Incident Date: 2018-09-15 Rear Center			
2018 Dec 18		Insurance Records Ontario, Canada	Glass Record	\$325.00			
2019 May 23	155,318 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced			
2019 Jun 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray			
2019 Nov 27	165,597 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced			
2020 Jun 11	171,691 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced			
	176,899 KM	Active Green & Ross - Ajax	Service Record	Vehicle serviced			

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Apr 19	181,341 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 10	186,610 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2022 Nov 30	196,258 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced
2023 May 24	204,717 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 6	215,931 KM	Active Green & Ross - Ajax Ajax, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 13	217,999 KM	Pickering Auto Lab Pickering, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Jul 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Sconditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

