



Vehicle History Report #: 60390150
Report Date: April 1, 2025 | 4:06 p.m. EDT
Report Status: Complete

2014 VOLKSWAGEN JETTA SE

Sedan | 4 Cylinders | Gas
3VWDK7AJ1EM441326
Country of Assembly: Mexico
Last Reported Odometer: 124,837 KM

No Reported
Accidents™ >



No Accident/Damage Records
Found



Last Registered In:
Ontario (Normal)



13 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 01, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VWDK7AJ1EM441326

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Jun 26		Town and Country Volkswagen Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Wheel locks removed
2017 Dec 11	121,177 KM	King Automotive Repair Service Nobleton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire(s) changed
2018 Jan 4		King Automotive Repair Service Nobleton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2018 Apr 13	138,888 KM	King Automotive Repair Service Nobleton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2019 Jun 19	180,963 KM	Car-Tech Auto Services North York, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Air filter replaced Cabin air filter replaced/cleaned Oil and filter changed
2019 Sep 20		Car-Tech Auto Services North York, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Headlight bulb(s) replaced Ignition system checked Ignition coil(s) replaced Spark plug wires replaced Spark plug(s) replaced
2019 Nov 8	195,471 KM	Car-Tech Auto Services North York, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire(s) changed
2020 Jan 9	203,106 KM	Car-Tech Auto Services North York, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery/charging system checked Oil and filter changed
2020 May 29		Cosmocare Collision Ltd Nobleton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Safety inspection performed

3VWDK7AJ1EM441326

ODOMETER		SOURCE	DETAILS
2021 Jun 28		MIDTOWN AUTO REPAIR Arthur, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Spark plug wires replaced
2023 Jul 13	121,448 KM	Speedy Auto Service St. Thomas, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Cooling system checkedDrive belts checkedOil and filter changedTire condition and pressure checkedWipers/washers checked
2024 Aug 9	124,837 KM	Finch Chrysler London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completedBrake rotor(s) replacedBrakes servicedOil and filter changedRear brake caliper(s) replacedRear brake pads replacedRear brake rotor(s) replacedRear brakes serviced/adjustedWipers/washers checked
2024 Aug 14		Finch Chrysler London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

3WWDK7AJ1EM441326

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Jun 26		Town and Country Volkswagen Markham, Ontario, Canada	Service Record	Vehicle serviced
2014 Jul 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2015 Sep 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Sep 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Oct 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Dec 11	121,177 KM	King Automotive Repair Service Nobleton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 4		King Automotive Repair Service Nobleton, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 13	138,888 KM	King Automotive Repair Service Nobleton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 19	180,963 KM	Car-Tech Auto Services North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2019 Sep 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Sep 20		Car-Tech Auto Services North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 8	195,471 KM	Car-Tech Auto Services North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 9	203,106 KM	Car-Tech Auto Services North York, Ontario, Canada	Service Record	Vehicle serviced
2020 May 27	209,619 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2020 May 29		Cosmocare Collision Ltd Nobleton, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal

3WWDK7AJ1EM441326

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Dec 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2021 Mar 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Apr 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2021 Apr 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2021 Jun 28		MIDTOWN AUTO REPAIR Arthur, Ontario, Canada	Service Record	Vehicle serviced
2022 Feb 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2022 Sep 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2023 Jul 13	121,448 KM	Speedy Auto Service St. Thomas, Ontario, Canada	Service Record	Vehicle serviced
2024 Jul 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Jul 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2024 Aug 9	124,837 KM	Finch Chrysler London, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2024 Aug 14		Finch Chrysler London, Ontario, Canada	Service Record	Vehicle serviced
2025 Mar 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

