

Vehicle History Report #: 54958731 Report Date: July 20, 2024 | 1:24 p.m. EDT Report Status: Complete

Reference:

2015 NISSAN ROGUE S

Sport utility vehicle | 4 Cylinders | Gas 5N1AT2MT3FC762737

Country of Assembly: United States Last Reported Odometer: 126,990 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



1 Service Record Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 20, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration


- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
 - In the province of **Québec** with **Normal** branding.
 - In the province of **Ontario** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Mar 10	126,990 KM	Service Facility Québec, Québec, Canada	Vehicle serviced



Recall #: R1609 | MAX ALT RG MUR OCS NTB16-052 Recall Date: 2016 May 24

Recall Description

The Occupant Classification System (OCS) is designed to classify the size and weight of the front seat passenger and, under certain conditions, automatically turn OFF the passenger air bag. The OCS system is designed to only deploy the front passenger airbag when the front passenger seat is occupied by an adult. In the affected vehicles, the OCS software may incorrectly classify the passenger seat as empty when it is occupied by an adult. If the OCS does not detect an adult occupant in the passenger seat, the passenger airbag would be deactivated.

Remedy

The OCS software will be reprogrammed to reduce the potential for classifying the seat as empty. This reprogram will be offered at no charge to the customer and should take less than an hour to complete. Your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)

Recall #: PC459 | ROGUE LIFTGTE STAY NTB16-105 Recall Date: 2016 Nov 08

Recall Description

On certain Model Year 2014-2016 Rogue vehicles, the anti-corrosion treatment on the rear lift gate stays may be insufficient. The rear lift gate stays provide power assist to the rear lift gate and operate under high pressure gas. If the anti-corrosion coating is insufficient, in certain rare instances, the rear lift gate stay may corrode over time due to salt and water penetration; causing a sudden release of pressure.

Remedy

Nissan is currently awaiting parts to remedy the affected vehicles. Nissan will send you a second letter, when parts are available, asking you to bring your vehicle to a Nissan dealer for the remedy at that time. This repair is free of charge for parts and labor. In the meantime, if you believe there is an issue with the rear door stays your vehicle, you may bring your vehicle into the nearest Nissan dealer for inspection.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)

Recall #: PC490 | ALT RGE CVT P0776 NTB16-121 Recall Date: 2016 Dec 20

Recall Description

Under specific driving conditions, hydraulic pressure may decrease and result in belt slip within the CVT. This may result in MIL illumination. Continuing to drive the vehicle in this condition can lead to accelerated wear and damage to the CVT. Nissan is proactively reprogramming the Transmission Control Module (TCM) with updated CVT software to prevent decreased hydraulic pressure and belt slip from occurring. This is not a safety issue, and the vehicle still meets and/or exceeds all applicable safety standards.

Remedy

To assure your continued satisfaction and confidence in your vehicle, and prevent possible future damage to the CVT, your Nissan dealer will reprogram the Transmission Control Module (TCM) at no charge to you for parts or labor. The service should take less than one (1) hour to complete, but your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)

Recall #: R21B9 | ROUGE WIRE HARNESS NTB22-076 Recall Date: 2022 Jan 25

Recall Description

IN AFFECTED VEHICLES, IF WATER AND SALT COLLECT IN THE DRIVER S SIDE FOOT WELL, IT MAY WICK UP THE DASH SIDE HARNESS TAPE AND ENTER THE CONNECTOR. IF THIS OCCURS, THE DASH SIDE HARNESS CONNECTOR MAY CORRODE AND POSSIBLY CAUSE ISSUES SUCH AS DRIVER S POWER WINDOW OR POWER SEAT INOPERATIVE, ALL-WHEEL DRIVE (AWD) WARNING LIGHT ON, BATTERY DISCHARGE, AND/OR THERMAL DAMAGE TO THE CONNECTOR. IN RARE CASES, THE CORROSION COULD POTENTIALLY LEAD TO A FIRE, WHICH MAY INCREASE RISK OF INJURY.

Remedy

YOUR NISSAN DEALER WILL INSPECT YOUR VEHICLE AND PERFORM THE APPROPRIATE REPAIR 1) IF CORROSION IS PRESENT ON EITHER THE MAIN HARNESS OR THE BODY HARNESS CONNECTORS, THE DEALER WILL REMOVE THE HARNESS TAPE AND HARNESS COVERING, REPLACE BOTH CONNECTORS AND APPLY WHITE LITHIUM GREASE TO THE CONNECTORS 2) IF CORROSION IS NOT PRESENT ON EITHER OF THE CONNECTORS, THE DEALER WILL REMOVE THE HARNESS TAPE AND HARNESS COVERING AND APPLY WHITE LITHIUM GREASE TO THE CONNECTORS. THIS SERVICE WILL BE CONDUCTED AT NO CHARGE TO YOU FOR PARTS AND LABOR, AND MAY TAKE UP TO TWO (2) HOURS TO

COMPLETE IF YOUR HARNESS CONNECTORS REQUIRE REPLACEMENT. HOWEVER, YOUR NISSAN DEALER MAY REQUIRE YOUR VEHICLE FOR A LONGER PERIOD OF TIME BASED UPON THEIR WORK SCHEDULE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Sep 29		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial
2015 Apr 8		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 Mar 10	126,990 KM	Service Facility Québec, Québec, Canada	Service Record	Vehicle serviced
2016 Mar 30		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 May 24		NISSAN	Recall	Manufacturer Recall Issued Recall # R1609
2016 Nov 8		NISSAN	Recall	Manufacturer Recall Issued Recall # PC459
2016 Dec 20		NISSAN	Recall	Manufacturer Recall Issued Recall # PC490
2016 Dec 28		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2017 Jan 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as red
2017 Feb 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2018 Feb 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Feb 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Jan 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial
2022 Jan 25		NISSAN	Recall	Manufacturer Recall Issued Recall # R21B9



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information from rediscrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Stonditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

