



Vehicle History Report #: 62409795

Report Date: June 24, 2025 | 4:47 p.m. EDT

Report Status: Complete

2019 NISSAN ROGUE SPORT S

Wagon | 4 Cylinders | Gas

JN1BJ1CP4KW213525

Country of Assembly: Japan

Last Reported Odometer: 126,699 KM

No Reported
Accidents

No Accident/Damage Records Found

Last Registered In:
Ontario (Normal)


9 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of June 24, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

- There are no accidents/damage reported on this vehicle.



Registration

- This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Jan 11		Midway Nissan Whitby, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Wheel locks installed
2019 Feb 7		Midway Nissan Whitby, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Computer reprogrammed Wheel locks installed
2019 Feb 28		Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Nitrogen fill tires
2019 Jun 20	11,129 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tires rotated
2019 Aug 27	25,366 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire repaired
2020 Jan 7	48,657 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Battery/charging system checked Brakes checked Lights checked Oil and filter changed Tire condition and pressure checked Tires rotated
2020 Jun 15	72,501 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2024 Jan 4	119,363 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Oil and filter changed Tires rotated
2024 Jul 30	126,699 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed

JN1BJ1CP4KW213525



Open Recalls

Recall #: R22C9 | ROGUE MCH KEY SPCR NTB23-068 Recall Date: 2023 Aug 24

Recall Description

CERTAIN 2014-2020 ROGUE AND 2017-2022 ROGUE SPORT VEHICLES ARE EQUIPPED WITH A JACKKNIFE KEY THAT MAY NOT HOLD THE KEY BLADE IN THE EXTENDED OPEN POSITION. OVER TIME THE INTERNAL PIVOT OF THE JACKKNIFE KEY MAY WEAKEN AND THE KEY COULD UNLOCK AND ROTATE DOWNWARDS.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (<https://www.nissanusa.com/recalls-vin.html>)



Stolen Vehicle Check

☒ This vehicle is not actively declared stolen.


Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jan 11		Midway Nissan Whitby, Ontario, Canada	Service Record	Vehicle serviced
2019 Feb 7		Midway Nissan Whitby, Ontario, Canada	Service Record	Vehicle serviced
2019 Feb 28		Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as silver
2019 Jun 20	11,129 KM	Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27	25,366 KM	Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 7	48,657 KM	Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Jun 15	72,501 KM	Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2023 May 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as silver
2023 May 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as silver

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Aug 24		NISSAN	Recall	Manufacturer Recall Issued Recall # R22C9
2024 Jan 4	119,363 KM	Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2024 Jul 30	126,699 KM	Willowdale Nissan Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

