


Vehicle History Report #: 56555040 Report Date: September 30, 2024 | 1:20 p.m. EDT Report Status: Complete Reference:

## 2016 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas 5N1AR2MM0GC649501 Country of Assembly: United States Last Reported Odometer: 108,137 KM









16 Service Records Found



No U.S. History Found





Not Actively Declared Stolen



No Import Record Found

(i)

Questions? We're here to help.

Visit us at **support.carfax.ca** 

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 30, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle

inspection and test drive, to make an informed decision.

# **Vehicle History Report**



## 🎍 Accident/Damage

INCIDENT DATE	DETAILS		AMOUNT	
2023 Nov 3	North York, Ontario, Canada			
	Police Reported	Accident reported: minor damage		
	Accident:	Vehicle involved in a sideswipe		
		collision		
		with another motor vehicle		
		Damage to right front		
		Damage to front		
	Estimate: Not Availab	ole   Estimate Date: 2023 Nov 6	\$4,699.06	
🕽 2024 May 30	North York, Ontario,	Canada		
	Police Reported Accid	dent: Accident reported: minor damage		
		with another motor vehicle		
		Damage to left front		
	<b>Estimate:</b> Total Loss	Damage to left front	\$11,080.38	
	<b>Estimate:</b> Total Loss   <b>Claim:</b> Collision	Damage to left front Damage to front	\$11,080.38 \$0.00	

### Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

🦲 Servi	ice Records			IGC649501
DATE	ODOMETER	SOURCE	DETAILS	ZMMC
2016 May 4		Avenue Nissan North York, Ontario, Canada	Vehicle serviced	5 N 1 AR

	ODOMETER	SOURCE	DETAILS
2018 Feb 13	1,110 KM	Avenue Nissan	Vehicle serviced
		North York, Ontario, Canada	Pre-delivery inspection completed
2018 Jul 27		Avenue Nissan	Vehicle serviced
		North York, Ontario, Canada	Roof molding replaced
		North Tork, Ontano, Canada	Antenna installed
2018 Sep 11	2,927 KM	Avenue Nissan	Vehicle serviced
	,	North York, Ontario, Canada	Maintenance inspection completed
			· · ·
2019 Feb 15	8,151 KM	Avenue Nissan	Vehicle serviced
		North York, Ontario, Canada	<ul> <li>Maintenance inspection completed</li> </ul>
			Fluids checked
			Oil and filter changed
			Tire condition and pressure checked
			<ul> <li>Wipers/washers checked</li> </ul>
			Vehicle washed/detailed
			Lights checked
2019 Sep 4	15,812 KM	Avenue Nissan	Vehicle serviced
	,	North York, Ontario, Canada	Maintenance inspection completed
		North Tork, Offano, Canada	Air filter replaced
			Drive belts checked
			Exhaust system checked
			Brakes checked
			Oil and filter changed
			Tires rotated
			Steering/suspension checked
			Vehicle washed/detailed
2020 Jun 12	23,435 KM	Avenue Nissan	Vehicle serviced
	,	North York, Ontario, Canada	Maintenance inspection completed
		North fork, Ontario, Canada	Brake fluid flushed/changed
			<ul> <li>Tire(s) mounted</li> </ul>
			Battery/charging system checked
			Oil and filter changed
			Tire condition and pressure checked
			Steering/suspension checked
			Four wheel alignment performed
			Alignment performed
2020 5 6 7 17		Ctrong Automotive Circeture Time	Vahiela comvised
2020 Sep 17	27,335 KM	Strong Automotive Signature Tire	Vehicle serviced
		North York, Ontario, Canada	
2020 Dec 8	29,947 KM	Avenue Nissan	Vehicle serviced
		North York, Ontario, Canada	Maintenance inspection completed
		NOLUT TOTA, OLICATIO, CALIAUA	<ul> <li>Fluids checked</li> </ul>
			Oil and filter changed
			Tire condition and pressure checked
			Wipers/washers checked
			Lights checked
			Lights checked

	ODOMETER	SOURCE	DETAILS
2020 Dec 21	30,219 KM	Avenue Nissan North York, Ontario, Canada	<ul> <li>Vehicle serviced</li> <li>Maintenance inspection completed</li> <li>Front brakes serviced</li> <li>Rear brake pads replaced</li> <li>Brake rotor(s) resurfaced</li> </ul>
2021 Jul 15	34,266 KM	Avenue Nissan North York, Ontario, Canada	<ul> <li>Vehicle serviced</li> <li>Maintenance inspection completed</li> <li>Fluids checked</li> <li>Oil and filter changed</li> <li>Tire condition and pressure checked</li> </ul>
2022 Jul 6	59,953 KM	Bathurst Car Care North York, Ontario, Canada	<ul> <li>Vehicle serviced</li> <li>Tire condition and pressure checked</li> <li>Tire(s) replaced</li> <li>Tire(s) balanced</li> <li>Tire repaired</li> <li>Brakes checked</li> </ul>
2022 Aug 16	60,548 KM	Bathurst Car Care North York, Ontario, Canada	<ul> <li>Vehicle serviced</li> <li>Tire pressure monitoring system reset</li> <li>Tire condition and pressure checked</li> <li>Spare tire installed</li> </ul>
2022 Sep 27	67,023 KM	Willowdale Nissan Thornhill, Ontario, Canada	Vehicle serviced
2024 Feb 5		Evolution Racing North York, Ontario, Canada	Vehicle serviced
2024 Feb 17	108,137 KM	Bathurst Car Care North York, Ontario, Canada	Vehicle serviced

#### **Open Recalls**

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)



This vehicle is not actively declared stolen.



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 May 4		Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Feb 13	1,110 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as white
2018 Jul 27		Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 11	2,927 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Feb 15	8,151 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Sep 4	15,812 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 12	23,435 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 17	27,335 KM	Strong Automotive Signature Tire North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 8	29,947 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 21	30,219 KM	Avenue Nissan North York, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
				Previous Use
				Personal
				Vehicle colou
				noted as whi
2021 Jul 15	34,266 KM	Avenue Nissan	Service Record	Vehicle
		North York, Ontario, Canada		serviced
2021 Sep 1		Motor Vehicle Dept.	Canadian Renewal	Registration
		Ontario, Canada		Issued or
				Renewed
				New Owner
				reported
				Previous Use
				Personal
				Vehicle colou
				noted as whi
2022 Jul 1		Motor Vehicle Dept.	Canadian Renewal	Registration
2022 Jul 1		Ontario, Canada	cultural in Kenewal	Issued or
		ontano, canada		Renewed
				Previous Use
				Personal
				Vehicle color
				noted as whi
2022 Jul 6	59,953 KM	Bathurst Car Care	Service Record	Vehicle
,	,	North York, Ontario, Canada		serviced
2022 Aug 16	60,548 KM	Bathurst Car Care	Service Record	Vehicle
-		North York, Ontario, Canada		serviced
2022 Sep 27	67,023 KM	Willowdale Nissan	Service Record	Vehicle
		Thornhill, Ontario, Canada		serviced
2023 Nov 3		Police Reported Accident	Police Report	Accident
		Ontario, Canada		Reported:
				• minor
				damag
				Vehicle     involve
				in a
				sideswi
				collisio
				• with
				anothe
				motor vehicle
				• Damag
				to right
				front
				<ul> <li>Damage to front</li> </ul>

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Nov 6	102,530 KM	Insurance Records North York, Ontario, Canada	Estimate Repair	Incident Date 2023-11-03 Not Available
2024 Feb 5		Evolution Racing North York, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 17	108,137 KM	Bathurst Car Care North York, Ontario, Canada	Service Record	Vehicle serviced
2024 May 30		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage with another motor vehicle Damage to left front Damage to front
2024 May 30		Insurance Records Ontario, Canada		
2024 May 30		Insurance Records Ontario, Canada		
2024 May 30		Insurance Records North York, Ontario, Canada	Estimate Repair	Estimate Dat 2024-06-20 Total Loss
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use Personal
2024 Jul 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colou noted as whi
2024 Aug 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colou noted as whi



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Conada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada's Line history report.

© 2024 CARFAX Canada ULC. All rights reserved.

